**EXHIBIT F-1**

**DEP AGREEMENT NO. 22PLN75**

# VILLAGE OF TEQUESTA VULNERABILITY ASSESSMENT AND ADAPTATION PLAN

**Village of Tequesta**

## Task 8: Final Vulnerability Assessment Report

**October 2024**

**This report is funded in part through a grant agreement from the Florida Department of Environmental Protection. The views, statements, findings, conclusions, and recommendations expressed herein are those of the author(s) and do not necessarily reflect the views of the State of Florida or any of its subagencies.**

# VILLAGE OF TEQUESTA
# VULNERABILITY ASSESSMENT AND ADAPTATION PLAN

**Prepared for:**

Village of Tequesta

345 Tequesta Drive

Tequesta, Florida 33469

**Prepared by:**

Jones Edmunds & Associates, Inc.

13545 Progress Boulevard, Suite 100

Alachua, Florida 32615

**Funded by:**

Florida Department of Environmental Protection

2600 Blair Stone Road MS 235

Tallahassee, Florida 32399-2400

Jones Edmunds Project No.: 20850-002-01

October 2024

_____

Karen Liang, PE, CFM
Florida PE No.: 77471

# TABLE OF CONTENTS

**PART I. EXECUTIVE SUMMARY ..... I-1**
**PART II. METHODOLOGY ..... II-1**
**1 Kickoff Meeting ..... II-1**
**2 Public Outreach Meetings ..... II-1**
**3 Background Data ..... II-1**
3.1 Critical and Regionally Significant Assets Inventory ..... II-1
3.2 Topographic Data ..... II-5
3.3 Field Survey Data ..... II-5
3.4 Flood Scenario-Related Data ..... II-5
3.4.1 Rainfall-Induced Flooding ..... II-5
3.4.2 Coastal Flooding ..... II-6
**PART III. OUTCOME ..... III-1**
**4 Exposure Analysis ..... III-1**
4.1 Rainfall-Induced Flooding ..... III-1
4.1.1 Computational Mesh ..... III-1
4.1.2 Green-Ampt Soil Parameters ..... III-1
4.1.3 Landcover and Impervious Mapping ..... III-2
4.1.4 1-D Hydraulic Features ..... III-3
4.1.5 Design-Storm Rainfall ..... III-4
4.1.6 Results Generation ..... III-4
4.2 Coastal Flooding ..... III-4
4.2.1 High Tide Flooding ..... III-4
4.2.2 Storm Surge Flooding ..... III-28
**5 Sensitivity Analysis ..... III-34**
**6 Focus Areas ..... III-68**
**PART IV. PRELIMINARY ADAPTATION PLAN ..... IV-1**
**7 Initial Adaptation Plan ..... IV-1**
7.1 Prioritization of Adaptation Needs ..... IV-1
7.2 Elevate the Village Hall, Public Safety Building, and Rec Center Generators ..... IV-1
7.3 Restore and Improve Dover Ditch (Dover Ditch Living Shoreline Project) ..... IV-2
7.4 Village Roads Subject to Existing and Future Flooding with Feasible Solutions ..... IV-4
7.5 More Resilient WTP ..... IV-5
7.6 More Resilient Wastewater Lift Stations ..... IV-5

# LIST OF TABLES


Table 1 Critical and Regionally Significant Assets ..... II-2
Table 2 Data Gaps and Gap Filling Summary ..... II-4
Table 3 Rainfall Depths and Change Factors ..... II-6
Table 4 1-Percent Annual Chance Stillwater Elevations ..... II-7
Table 5 NOAA 2017 Projected SLR Values at the Vaca Key Station ..... II-7
Table 6 Extreme High Tide Elevations (MHHW + 2 ft) at the Vaca Key Station Estimated Using NOAA 2017 SLR Projections ..... II-7
Table 7 Modeled Landcover Parameters ..... III-2
Table 8 Existing and Proposed SLR Scenario Rainfall Values ..... III-4
Table 9 Storm Surge Flooding Results ..... III-28
Table 10 Exposure Level for Critical Assets ..... III-35
Table 11 Village-Wide Summary of Exposure Level Results for Critical Assets ..... III-36
Table 12 Exposure Weighting Factor ..... III-65
Table 13 Asset Priorities and Regional Significance ..... III-65


# LIST OF FIGURES


Figure 1 Critical Assets ..... II-3
Figure 2 Rainfall-Induced Flooding for the 100-Year Storm Event Under Existing Conditions ..... III-5
Figure 3 Rainfall-Induced Flooding for the 100-Year Storm Event Under Intermediate – High 2040 Conditions ..... III-6
Figure 4 Rainfall-Induced Flooding for the 100-Year Storm Event Under Intermediate – High 2070 Conditions ..... III-7
Figure 5 Rainfall-Induced Flooding for the 500-Year Storm Event Under Existing Conditions ..... III-8
Figure 6 Rainfall-Induced Flooding for the 500-Year Storm Event Under Intermediate – High 2040 Conditions ..... III-9
Figure 7 Rainfall-Induced Flooding for the 500-Year Storm Event Under Intermediate – High 2070 Conditions ..... III-10
Figure 8 Rainfall-Induced Flooding for the 100-Year Storm Event Under Intermediate – Low 2040 Conditions ..... III-11
Figure 9 Rainfall-Induced Flooding for the 100-Year Storm Event Under Intermediate – Low 2070 Conditions ..... III-12
Figure 10 Rainfall-Induced Flooding for the 500-Year Storm Event Under Intermediate – Low 2040 Conditions ..... III-13
Figure 11 Rainfall-Induced Flooding for the 500-Year Storm Event Under Intermediate – Low 2070 Conditions ..... III-14
Figure 12 High Tide Flooding Days Under Existing Conditions ..... III-15
Figure 13 High Tide Flooding Days Under Intermediate – High 2040 Conditions ..... III-16
Figure 14 High Tide Flooding Days Under Intermediate – High 2070 Conditions ..... III-17
Figure 15 High Tide Flooding Days Under Intermediate – Low 2040 Conditions ..... III-18
Figure 16 High Tide Flooding Days Under Intermediate – Low 2070 Conditions ..... III-19
Figure 17 High Tide Flooding Depth Under Existing Conditions ..... III-20
Figure 18 High Tide Flooding Depth Under Intermediate – High 2040 Conditions ..... III-21
Figure 19 High Tide Flooding Depth Under Intermediate – High 2070 Conditions ..... III-22

Figure 20 Extreme High Tide (2 Feet Above MHHW) Flooding Depth Under Existing Conditions ..... III-23
Figure 21 Extreme High Tide (2 Feet Above MHHW) Flooding Depth Under Intermediate – High 2040 Conditions ..... III-24
Figure 22 Extreme High Tide (2 Feet Above MHHW) Flooding Depth Under Intermediate – High 2070 Conditions ..... III-25
Figure 23 Extreme High Tide (2 Feet Above NHHW) Flooding Depth Under Intermediate – Low 2040 Conditions ..... III-26
Figure 24 Extreme High Tide (2 Feet Above NHHW) Flooding Depth Under Intermediate – Low 2070 Conditions ..... III-27
Figure 25 100-Year Storm Surge Flooding Under Existing Conditions ..... III-29
Figure 26 100-Year Storm Surge Flooding Under Intermediate – Low SLR Projections for 2040 Conditions ..... III-30
Figure 27 100-Year Storm Surge Flooding Under Intermediate – Low SLR Projections for 2070 Conditions ..... III-31
Figure 28 100-Year Storm Surge Flooding Under Intermediate – High SLR Projections for 2040 Conditions ..... III-32
Figure 29 100-Year Storm Surge Flooding Under Intermediate – High SLR Projections for 2070 Conditions ..... III-33
Figure 30 Critical Assets with Rainfall Flooding Depth for the 100-Year Storm Event Under Existing Conditions ..... III-37
Figure 31 Critical Assets with Rainfall Flooding Depth for the 100-Year Storm Event Under Intermediate – High 2040 Conditions ..... III-38
Figure 32 Critical Assets with Rainfall Flooding Depth for the 100-Year Storm Event Under Intermediate – High 2070 Conditions ..... III-39
Figure 33 Critical Assets with Rainfall Flooding Depth for the 500-Year Storm Event Under Existing Conditions ..... III-40
Figure 34 Critical Assets with Rainfall Flooding Depth for the 500-Year Storm Event Under Intermediate – High 2040 Conditions ..... III-41
Figure 35 Critical Assets with Rainfall Flooding Depth for the 500-Year Storm Event Under Intermediate – High 2070 Conditions ..... III-42
Figure 36 Critical Assets with Rainfall Flooding Depth for the 100-Year Storm Event Under Intermediate – Low 2040 Conditions ..... III-43
Figure 37 Critical Assets with Rainfall Flooding Depth for the 100-Year Storm Event Under Intermediate – Low 2070 Conditions ..... III-44
Figure 38 Critical Assets with Rainfall Flooding Depth for the 500-Year Storm Event Under Intermediate – Low 2040 Conditions ..... III-45
Figure 39 Critical Assets with Rainfall Flooding Depth for the 500-Year Storm Event Under Intermediate – Low 2070 Conditions ..... III-46
Figure 40 Critical Assets with High-Tide Flooding Days Under Existing Conditions .. III-47
Figure 41 Critical Assets with High-Tide Flooding Days Under Intermediate – High 2040 Conditions ..... III-48
Figure 42 Critical Assets with High-Tide Flooding Days Under Intermediate – High 2070 Conditions ..... III-49
Figure 43 Critical Assets with High-Tide Flooding Days Under Intermediate – Low 2040 Conditions ..... III-50
Figure 44 Critical Assets with High-Tide Flooding Days Under Intermediate – Low 2070 Conditions ..... III-51
Figure 45 Critical Assets with High-Tide Flooding Depth Under Existing Conditions . III-52
Figure 46 Critical Assets with High-Tide Flooding Depth Under Intermediate – High 2040 Conditions ..... III-53

Figure 47 Critical Assets with High-Tide Flooding Depth Under Intermediate – High 2070 Conditions ..... III-54
Figure 48 Critical Assets with Extreme High-Tide (2 Feet Above MHHW) Flooding Depth Under Existing Conditions ..... III-55
Figure 49 Critical Assets with Extreme High-Tide (2 Feet Above MHHW) Flooding Depth Under Intermediate – High 2040 Conditions ..... III-56
Figure 50 Critical Assets with Extreme High-Tide (2 Feet Above MHHW) Flooding Depth Under Intermediate – High 2070 Conditions ..... III-57
Figure 51 Critical Assets with Extreme High-Tide (2 Feet Above NHHW) Flooding Depth Under Intermediate – Low 2040 Conditions ..... III-58
Figure 52 Critical Assets with Extreme High-Tide (2 Feet Above NHHW) Flooding Depth Under Intermediate – Low 2070 Conditions ..... III-59
Figure 53 Critical Assets with 100-Year Storm-Surge Flooding Under Existing Conditions ..... III-60
Figure 54 Critical Assets with 100-Year Storm-Surge Flooding Under Intermediate – Low SLR Projections for 2040 Conditions ..... III-61
Figure 55 Critical Assets with 100-Year Storm-Surge Flooding Under Intermediate – Low SLR Projections for 2070 Conditions ..... III-62
Figure 56 Critical Assets with 100-Year Storm-Surge Flooding Under Intermediate – High SLR Projections for 2040 Conditions ..... III-63
Figure 57 Critical Assets with 100-Year Storm-Surge Flooding Under Intermediate – High SLR Projections for 2070 Conditions ..... III-64
Figure 58 Exposure-Level Ranking of Critical Assets ..... III-67
Figure 59 Focus Area Boundaries ..... III-69
Figure 60 Dover Ditch Living Shoreline Project Plan View ..... IV-3

# APPENDICES

Appendix A Kickoff Meeting Minutes and Sign-In Sheet

Appendix B Public Outreach #1 Meeting Minutes and Sign-In Sheet

Appendix C Public Outreach Meeting #2 Meeting Minutes and Sign-In Sheet

Appendix D FDEP Approval To Use Vaca Key Tide Gauge Data

# ATTACHMENTS

Attachment 1 Exposure Level Results for Tidal Flooding

Attachment 2 Exposure Level Results for Rainfall-Induced Flooding

Attachment 3 Exposure Level Results for Coastal Flooding

# PART I. EXECUTIVE SUMMARY

As part of its continuing efforts to become a more resilient community, the Village of Tequesta applied for and received a Planning Grant from the Florida Department of Environmental Protection (FDEP) under their Resilient Florida Grant Program. The grant covers the following Tasks:

- Task 1 – Kickoff Meeting
- Task 2 – Public Outreach Meetings (up to two)
- Task 3 – Acquire Background Data
- Task 4 – Exposure Analysis
- Task 5 – Sensitivity Analysis
- Task 6 – Identify Focus Areas
- Task 7 – Develop Initial Adaptation Plan (up to five conceptual alternatives)
- Task 8 – Final Vulnerability Assessment Report, Maps, and Tables

This report documents each task pursuant to the requirements in Section 380.093, Florida Statutes (FS) and based on public outreach efforts.

The Kickoff Meeting was used to confirm project goals, establish lines of communication, review the scope of services, and discuss data collection and analyses. Jones Edmunds acquired publicly available critical asset data from local, regional, state, and federal sources and combined it with data acquired directly from the Village, resulting in approximately 393 critical and regionally significant assets. After evaluating the data, we provided a gap analysis with a plan for gap-filling. After approval of the plan, we filled the data gaps and made the data available to the Village on a limited-access webpage because some of the data were restricted. Additional data gap fulfillment was later completed using desktop research and field survey methods with FDEP's approved additional funding.

We performed an Exposure Analysis on the following 27 scenarios:

1. Tidal Mean Higher High Water (MHHW) Intermediate (Int)-High Existing Conditions.
2. Tidal MHHW Int-Low 2040.
3. Tidal MHHW Int-Low 2070.
4. Tidal MHHW Int-High 2040.
5. Tidal MHHW Int-High 2070.
6. Tidal MHHW Plus 2ft Int-High Existing Conditions.
7. Tidal MHHW Plus 2ft Int-Low 2040.
8. Tidal MHHW Plus 2ft Int-Low 2070.
9. Tidal MHHW Plus 2ft Int-High 2040.
10. Tidal MHHW Plus 2ft Int-High 2070.
11. Rainfall-Induced 100-Year (YR)/24-Hour (HR) Existing Conditions.
12. Rainfall-Induced 100-YR/3-Day (D) Existing Conditions.
13. Rainfall-Induced 100-YR/24-HR Int-High 2040.
14. Rainfall-Induced 100-YR/3-D Int-High 2040.
15. Rainfall-Induced 100-YR/24-HR Int-High 2070.
16. Rainfall-Induced 100-YR/3-D Int-High 2070.
17. Rainfall-Induced 500-YR/24-HR Existing Conditions.

18. Rainfall-Induced 500-YR/3-D Existing Conditions.
19. Rainfall-Induced 500-YR/24-HR Int-High 2040.
20. Rainfall-Induced 500-YR/3-D Int-High 2040.
21. Rainfall-Induced 500-YR/24-HR Int-High 2070.
22. Rainfall-Induced 500-YR/3-D Int-High 2070.
23. Storm Surge 100-YR Existing Conditions.
24. Storm Surge 100-YR Int-Low 2040.
25. Storm Surge 100-YR Int-Low 2070.
26. Storm Surge 100-YR Int-High 2040.
27. Storm Surge 100-YR Int-High 2070.

Jones Edmunds also performed rainfall-induced Int-Low analyses; however, the results were excluded since they were nearly identical to Int-High for the inland portions of the watershed. Throughout the Village, the predicted storm-surge flooding is more severe than the predicted rainfall-induced flooding.

For the Sensitivity Analysis, Jones Edmunds compared the flood elevations from the 27 scenarios to known or estimated critical asset elevations. We created a high/medium/low (H/M/L) ranking for the severity of flooding of each asset type and converted the results into H/M/L. Similarly, we developed a prioritization methodology that combined the severity of flooding with the criticality of each asset type to rank each predicted flooding problem into an H/M/L category. We created Focus Areas based on the concentration of critical assets and urbanization and then prioritized the predicted flooding within each Focus Area.

Based on a review of the results with the Village, we developed an Initial Adaptation Plan that includes the following conceptual alternatives for the prioritized problem areas:

1. Elevate the Town Hall, Public Safety Building, and Rec Center generators.
2. Restore and improve Dover Ditch (Dover Ditch Living Shoreline Project).
3. Improve Village roads subject to existing and future flooding with feasible solutions.
4. Increase resiliency at the water treatment plant (WTP).
5. Increase resiliency at the wastewater lift stations.

# PART II. METHODOLOGY

This section describes the methodology used for the Vulnerability Assessment.

## 1 KICKOFF MEETING

The Kickoff Meeting was held on November 22, 2022, at the Village Hall. The meeting included reviewing the project goals, scope, schedule, milestones/deliverables, and communication/points of contact. Appendix A includes the meeting minutes and the sign-in sheet.

## 2 PUBLIC OUTREACH MEETINGS

The first Public Outreach Meeting was held on August 16, 2023, at the Village Hall Council Chambers. This meeting informed the public on the methodologies being used for creating and the findings from the Vulnerability Assessment and solicited input on priorities. Appendix B includes the meeting minutes and the sign-in sheet. No public comments were made requesting changes in the methodologies or priorities. The comments related to additional clarification on parts of the study, which were provided in the responses and recorded in the meeting minutes.

The second Public Outreach Meeting was held on June 26, 2024, also at the Village Hall Council Chambers. This meeting was held to inform the public on updates to the Vulnerability Assessment since the first Public Outreach meeting. Appendix C includes the meeting minutes and the sign-in sheet. No public comments were made requesting changes in methodologies or priorities. The comments related to additional clarification on parts of the study, historical flooding issues, and planned projects.

## 3 BACKGROUND DATA

Jones Edmunds researched and compiled the spatial data required to perform the Vulnerability Assessment as defined in Section 380.093, Florida Statutes (FS). The following subsections describe the data.

### 3.1 CRITICAL AND REGIONALLY SIGNIFICANT ASSETS INVENTORY

Jones Edmunds assembled many of the critical and regionally significant assets from existing data sources. Table 1 summarizes the asset class, asset type, dataset type, source, and data type for each asset. Figure 1 shows the locations of the critical assets. Point, line, and polygon geographic information system (GIS) feature classes are used due to the nature of the critical assets. These representations are important for the Sensitivity Analysis.

Jones Edmunds and the Village reviewed each dataset for completeness and accuracy as part of the gap analysis. Table 2 summarizes the gap analysis and how the gaps were filled.

**Table 1 Critical and Regionally Significant Assets**

| Asset Class | Asset Type | Dataset | Source | Data Type | Data Gaps |
|---|---|---|---|---|---|
| Transportation and Evacuation Routes | Airports | NA | | | VOT confirmed |
| | Bridges | Bridges | FDEM/VOT | Point | Not preferred data type - ideally polygon layer |
| | | | | | Missing data - need sizes |
| | Bus Terminals | NA | | | VOT confirmed |
| | Ports | NA | | | VOT confirmed |
| | Major Roadways | Major Roads | VOT | Line | Missing data - need to define major roadways; scale issue |
| | | | | | Not preferred data type - ideally polygon layer |
| | Marinas | NA | | | VOT confirmed |
| | Rail Facilities | NA | | | Missing data - use alternative source |
| | Railroad Bridges | NA | | | VOT confirmed |
| Critical Infrastructure | Wastewater Treatment Facilities and Lift Stations | Wastewater Treatment Fac | Loxahatchee River District | Point | |
| | | Wastewater Lift Stations | Loxahatchee River District | Point | |
| | Stormwater Treatment Facilities and Lift Stations | NA | | | VOT confirmed |
| | Drinking Water Facilities | Water Treament Plants | FDEM / VOT | Point | |
| | | Water Supply Wells | VOT | Point | |
| | | Elevated/Ground Storage Tanks | JE Review | Point | Missing data - VOT/FTE confirm |
| | | Water Distribution Pumps | VOT | Point | Missing data - VOT/FTE confirm |
| | Electric Production and Supply | Electric Facilities | VOT | Point | |
| | | Electric Substations | NA | | VOT confirmed |
| | Solid and Hazardous Waste Facilities | NA | | | Missing data - VOT/FTE confirm |
| | Military Installations | NA | | | VOT confirmed |
| | Communications Facilities | NA | | | VOT confirmed |
| | Disaster Debris Management Sites | NA | | | Missing data - VOT/FTE confrim |
| Critical Community and Emergency Facilities | Schools | Schools | FEMA | Point | Low quality data - locations may not be accurate |
| | | Day Cares | FDEM | Point | Low quality data - locations may not be accurate |
| | Colleges and Universities | NA | | | VOT confirmed |
| | Community Centers | NA | | | Missing data - VOT/FTE confirm |
| | Correctional Facilities | NA | | | VOT confirmed |
| | Disaster Recovery Centers | NA | | | Missing data - VOT/FTE confirm |
| | Emergency Medical Service Facilities | Emergency Medical Services | FDEM | Point | |
| | Emergency Operation Centers | Emergency Operations Center | VOT | Point | Missing data - VOT/FTE confirm |
| | Fire Stations | Fire Stations | VOT | Point | |
| | Health Care Facilities | Health Care Facilites | FDEM / FEMA | Point | Missing data - JE / VOT review |
| | Hospitals | NA | | | VOT confirmed |
| | Law Enforcement Facilities | Law Enforcement Facilities | VOT | Point | |
| | Local Government Facilities | Local Government Facilities | VOT/JE Review | Point | |
| | Affordable Public Housing | NA | | | Missing data - VOT/FTE confirm |
| | Risk Shelter Inventory | NA | | | Missing data - VOT/FTE confirm |
| | State Government Facilities | NA | | | Missing data - VOT/FTE confirm |
| Natural, Cultural, and Historical Resource | Conservation Lands | Conservation Lands | FNAI | Polygon | |
| | Parks | Parks | OSM/FNAI/VOT | Polygon | |
| | Shorelines | Shorelines | FL FWC | Line | Low quality data - locations may not be accurate |
| | Surface Waters | Surface Waters | FDEP | Polygon | |
| | Wetlands | Wetlands | SFWMD | Polygon | Low quality data - locations may not be accurate |
| | Historical and Cultural Assets | Historical Cultural Assets | NA | | VOT confirmed |
| | | Historical Cultural Assets - Sites | SHPO | Polygon | |

## Figure 1 Critical Assets



## Table 2 Data Gaps and Gap Filling Summary

| Asset Class | Asset Type | Dataset | Data Gaps | Gap Fill | Elevation Notes |
|---|---|---|---|---|---|
| Transportation and Evacuation Routes | Airports | NA | VOT confirmed | None within VOT. | |
| | Bridges | Bridges | Not preferred data type - ideally polygon layer | Buffered bridge points | Used polygon features and took max elevation from the edges, as bridges not captured in DEM |
| | Bus Terminals | NA | VOT confirmed | None within VOT. | |
| | Ports | NA | VOT confirmed | None within VOT. | |
| | Major Roadways | Major Roads | Missing roadway classification | FDOT and FEMA Hazus provided layer with roadway classification | Used polygon features and took min surface elevation |
| | | | Not preferred data type - ideally polygon layer | Buffered roadway lines | |
| | Marinas | NA | VOT confirmed | None within VOT. | |
| | Rail Facilities | NA | Missing data - use alternative source | USGS provided layer with railway lines | |
| | Railroad Bridges | NA | VOT confirmed | None within VOT. | |
| Critical Infrastructure | Wastewater Treatment Facilities and Lift Stations | Wastewater Treatment Fac | | Confirmed with VOT | |
| | | Wastewater Lift Stations | | Loxahatchee River District provided data | Surface elevation; Surface elevation + 4ft |
| | Stormwater Treatment Facilities and Lift Stations | NA | VOT confirmed | None within VOT | |
| | Drinking Water Facilities | Water Treament Plants | | VOT provided data | 90th percentile + 1.5ft of 5ft buffer; used main building |
| | | Water Supply Wells | | FDEP provided layer with PWS data | Surface elevation |
| | | Elevated/Ground Storage Tanks | Missing data - VOT/FTE confirm | VOT provided data | 90th percentile of surface elevation |
| | | Water Distribution Pumps | Missing data - VOT/FTE confirm | VOT provided data | Surface elevation |
| | Electric Production and Supply | Electric Facilities | | | 90th percentile + 1.5ft of 5ft buffer |
| | | Electric Substations | VOT confirmed | None within VOT. | |
| | Solid and Hazardous Waste Facilities | NA | Missing data - VOT/FTE confirm | Confirmed with VOT | |
| | Military Installations | NA | VOT confirmed | None within VOT. | |
| | Communications Facilities | NA | VOT confirmed | None within VOT. | |
| | Disaster Debris Management Sites | NA | Missing data - VOT/FTE confrim | Data collection by FTC | |
| Critical Community and Emergency Facilities | Schools | Schools | Low quality data - locations may not be accurate | Data collection by FTC | 90th percentile + 1.5ft of 5ft buffer |
| | | Day Cares | Low quality data - locations may not be accurate | Data collection by FTC | 90th percentile + 1.5ft of 5ft buffer |
| | Colleges and Universities | NA | VOT confirmed | None within VOT. | |
| | Community Centers | NA | Missing data - VOT/FTE confirm | Confirmed with VOT | |
| | Correctional Facilities | NA | VOT confirmed | None within VOT. | |
| | Disaster Recovery Centers | NA | Missing data - VOT/FTE confirm | Confirmed with VOT | |
| | Emergency Medical Service Facilities | Emergency Medical Services | | | 90th percentile + 1.5ft of 5ft buffer |
| | Emergency Operation Centers | Emergency Operations Center | Missing data - VOT/FTE confirm | Confirmed with VOT | 90th percentile + 1.5ft of 5ft buffer |
| | Fire Stations | Fire Stations | | | 90th percentile + 1.5ft of 5ft buffer |
| | Health Care Facilities | Health Care Facilites | Missing data - JE / VOT review | Used business directory | 90th percentile + 1.5ft of 5ft buffer |
| | Hospitals | NA | VOT confirmed | None within VOT. | |
| | Law Enforcement Facilities | Law Enforcement Facilities | | | 90th percentile + 1.5ft of 5ft buffer |
| | Local Government Facilities | Local Government Facilities | | | 90th percentile + 1.5ft of 5ft buffer; 90th percentile of surface elevation for tanks |
| | Affordable Public Housing | NA | Missing data - VOT/FTE confirm | Data collection by FTC | |
| | Risk Shelter Inventory | NA | Missing data - VOT/FTE confirm | Data collection by FTC | |
| | State Government Facilities | NA | Missing data - VOT/FTE confirm | Data collection by FTC | |
| Natural, Cultural, and Historical Resource | Conservation Lands | Conservation Lands | | | Min of surface elevation |
| | Parks | Parks | | | Min of surface elevation |
| | Shorelines | Shorelines | Low quality data - locations may not be accurate | VOT provided data, compared with PBC DEM | Min of surface elevation |
| | Surface Waters | Surface Waters | | | Min of surface elevation |
| | Wetlands | Wetlands | Low quality data - locations may not be accurate | NWI, FL FWC, VOT provided data | Min of surface elevation |
| | Historical and Cultural Assets | Historical Cultural Assets | VOT confirmed | | 90th percentile + 1.5ft of 5ft buffer |
| | | Historical Cultural Assets - Sites | | | Min of surface elevation |

## 3.2 TOPOGRAPHIC DATA

Jones Edmunds obtained a copy of the 2019 light detection and ranging (LiDAR) data for Palm Beach County from the Palm Beach County GIS Department and the 2018 LiDAR data for Martin County from the US Geological Survey (USGS). The 2019 Palm Beach County LiDAR data were collected between December 28, 2016, and March 10, 2017, and the 2018 Martin County LiDAR data were collected between December 24, 2018, and April 25, 2019. The data coordinate reference systems for the LiDAR datasets are as follows:

- The horizontal datum is the North American Datum of 1983 with the 2011 Adjustment (NAD83 [2011]).
- The vertical datum is the North American Vertical Datum of 1988 (NAVD88).
- The coordinate system is NAD83 (2011) State Plane Florida East (US Survey Feet).
- The geoid model is Geoid12B.

The vertical accuracy of the LiDAR datasets was reported as having a root-mean-square-error (RMSE) relative to non-vegetated checkpoints of 0.64 foot at the 95-percent confidence interval. The LiDAR data were provided as a 2.5-foot-by-2.5-foot digital elevation model (DEM).

## 3.3 FIELD SURVEY DATA

During the data assessment, Jones Edmunds discovered that certain crucial data were missing from the Village's stormwater infrastructure database, posing a significant gap in the system's information. To address this issue, Jones Edmunds performed field surveying to rectify the data deficiency at major stormwater structures. Through meticulous on-site investigations and data collection efforts, Jones Edmunds successfully filled the missing information gaps in the Village's stormwater infrastructure database at 268 locations. The vertical accuracy of the collected elevation data was determined to be 0.197 foot or better at a 95-percent confidence level, which was derived using RMSE(z) X 1.9600 as defined by the National Standards for Spatial Data Accuracy (NSSDA). This proactive approach enhances the accuracy and reliability of the database and also ensures better planning and management of the Village's stormwater systems for improved resilience and efficiency.

## 3.4 FLOOD SCENARIO-RELATED DATA

### 3.4.1 RAINFALL-INDUCED FLOODING

Jones Edmunds developed a rapid two-dimensional (2D) inundation model for the Village within TUFLOW HPC (Release 2020-10-AF) that covers all of the Village and portions of the adjacent areas that drain into the Village. The model uses a rapid-flood modeling approach to predict inundation areas for user-supplied design storms. The following datasets were collected for generating model parameters:

- Stormwater drainage structures database from the Village.
- Road lines from the Village and Palm Beach County.
- Waterbodies shapefile from USGS.
- 2018 USGS National Hydrography Dataset (NHD).

- 2022 statewide building footprints from Microsoft Bing.
- 2019 land use mapping from Palm Beach County.
- As-built and design plans from the Village.
- As-built and design plans from Environmental Resource Permits (ERPs) from the South Florida Water Management District (SFWMD).
- Soils data from the US Department of Agriculture-Natural Resources Conservation Service (USDA-NRCS) Soil Survey Geographic (SSURGO) Database.
- National Oceanic and Atmospheric Administration (NOAA) Atlas 14, Volume 9, Version 2 rainfall data.
- Palm Beach County aerial imagery (2019).

The model was based on the 2019 Palm Beach County LiDAR and the 2018 Martin County LiDAR. Section 380.093, FS, requires that the flood projections performed under this project were based on the most recent LiDAR dataset described in Section 3.2. The two LiDAR datasets used are the most recent available data.

Rainfall totals from NOAA Atlas 14, Volume 9, Version 2 were used to simulate the existing conditions flood risk in the Village. Jones Edmunds evaluated the 24-hour and 3-day storm event durations for the 100- and 500-year return periods. The rainfall distribution pattern that was applied was the Florida Type II Modified Rainfall Distribution for the 24-hour event and the Florida Department of Transportation (FDOT) Intensity-Duration-Frequency (IDF) Curve for the 3-day event. For 2040 and 2070 conditions, we used the rainfall change factors from the Florida International University's (FIU) Sea-Level Solutions Center (Updating the Statewide Extreme Rainfall Projections | Tableau Public) based on the 50$^{th}$ percentile. Table 3 shows the rainfall depths and change factors taken from the FIU website.

**Table 3 Rainfall Depths and Change Factors**

| | Existing (inches) | Change Factor | 2040 (inches) | Change Factor | 2070 (inches) |
|---|---|---|---|---|---|
| 100-Year/24-Hour | 16.1 | 1.15 | 18.5 | 1.2 | 19.3 |
| 500-Year/24-Hour | 21.9 | 1.16 | 25.4 | 1.23 | 26.9 |
| 100-Year/3-Day | 18.3 | 1.14 | 20.9 | 1.17 | 21.4 |
| 500-Year/3-Day | 25.1 | 1.14 | 28.6 | 1.2 | 30.1 |

### 3.4.2 Coastal Flooding

The coastal storm surge flooding analysis was based on the Federal Emergency Management Agency (FEMA) 1-percent annual chance (i.e., 100-year) still-water elevation level (SWEL) raster, FEMA's floodplain and base flood elevation (BFE) polygon, and NOAA's sea-level rise (SLR) projection curves. We downloaded FEMA's SWEL raster from the FEMA library (Study ID 15-04-4157S, preliminary issue January 3, 2023) and the floodplain polygons with BFE values to assist with the coastal storm surge flooding analysis. Table 4 summarizes the SWEL values within the Village.

**Table 4 1-Percent Annual Chance Stillwater Elevations**

| | Stillwater Elevations (in feet NAVD88) | |
|---|---|---|
| | Int-Low | Int-High |
| Existing Conditions | 4.5 to 5.9 | |
| 2040 | 5.7 to 7.1 | 6.2 to 7.6 |
| 2070 | 6.3 to 7.7 | 8.1 to 9.5 |

For tidal flooding, the data that Jones Edmunds used to calculate the MHHW elevation for existing conditions (0.056 foot-NAVD88 for 2023) were taken from NOAA's website for the Vaca Key gauge (station 8723970). We used the Vaca Key gauge due to its proximity to the Village and its active and compliant status. Other tide gauges along the east coast of Florida were also considered; those gauges are Virginia Key (Station 8723214), Daytona Beach Shores (Station 8721120), and Trident Pier (Station 721604). Although those gauges are also in the same region, their statuses are either non-compliant or inactive/removed. Consequently, only data from the Vaca Key gauge were used in this study. Appendix D includes the approval documentation from FDEP to use the Vaca Key gauge for this study.

Projections for intermediate-low and intermediate-high SLR for 2040 and 2070 were also taken from NOAA's website for the SLRs projected by NOAA in 2017. Table 5 presents these values.

**Table 5 NOAA 2017 Projected SLR Values at the Vaca Key Station**

| | Int-Low (feet) | Int-High (feet) |
|---|---|---|
| 2040 | 0.41 | 0.88 |
| 2070 | 1.00 | 2.81 |

Using the MHHW elevation at the Vaca Key gauge and the SLR projections presented in Table 4, we estimated the extreme high-tide elevations under existing, 2040, and 2070 conditions. Table 6 presents the estimated elevations.

**Table 6 Extreme High Tide Elevations (MHHW + 2 ft) at the Vaca Key Station Estimated Using NOAA 2017 SLR Projections**

| | Existing Conditions | 2040 | | 2070 | |
|---|---|---|---|---|---|
| | | Int-Low (feet) | Int-High (feet) | Int-Low (feet) | Int-High (feet) |
| Extreme High Tide Elevation (in feet NAVD88) | 2.056 | 2.386 | 2.852 | 2.976 | 4.782 |

# PART III. OUTCOME

# 4 EXPOSURE ANALYSIS

The Village is concerned about the impact of climate change on its critical infrastructure and natural resources and the well-being of its citizens and their property. To help evaluate these impacts, the Village is completing a critical infrastructure and land use climate Vulnerability Analysis. One of the primary climate impacts in the Village will most likely be altered flooding conditions due to changing rainfall volume, frequency, and intensity.

Rainfall-driven flooding occurs throughout the Village, but not all flooded areas are presented in flood risk maps or represented in existing flood models. FEMA mapping studies typically focus on riverine or lake flooding with occurrence intervals of 100 or 500 years and generally with a drainage area of at least 100 acres. These studies also focus on current rainfall conditions and do not consider the future probability of extreme rainfall events.

Jones Edmunds developed a 2D inundation model that covers all of the Village and portions of the adjacent area that drain into the Village.

## 4.1 RAINFALL-INDUCED FLOODING

Jones Edmunds developed the 2D inundation model for the Village within TUFLOW HPC (Release 2020-10-AF) using the rainfall volumes reported in Part III, Section 3.4.1. The model covers approximately 2.3 square miles. We also adjusted the boundary condition and initial conditions for the projected increases in SLR using the Intermediate-High scenario. We tested the Intermediate-Low scenario as well and determined that the results were nearly identical to the Intermediate-High scenario for most of the watershed; therefore, we only used the slightly more conservative scenario. The model is referred herein as the *TUFLOW* model and uses a rapid-flood modeling approach to predict inundation areas for rainfall events.

### 4.1.1 COMPUTATIONAL MESH

The TUFLOW model employs hydraulic and hydrologic methods that are grid based with a uniform grid resolution of 20 feet. The surface hydraulics are defined based on surface roughness and the 2.5-foot LiDAR DEMs. The TUFLOW model uses sub-grid sampling that allows each cell in the model to account for the 2.5-foot-resolution DEM when determining conveyance between cells and storage within cells.

### 4.1.2 GREEN-AMPT SOIL PARAMETERS

The modeled hydrologic response uses a rain-on-grid approach instead of the lumped-basin approach used in traditional flood studies. The TUFLOW model uses the Green-Ampt infiltration method and accounts for a varying water table. This physically based infiltration model predicts runoff response regardless of rainfall depth or duration. The grid-based Green-Ampt approach provides flexibility for the model to generate a hydrologic response from a variety of rainfall events without compromising prediction accuracy.

The Green-Ampt model input was developed based on the SSURGO Database for classifying soils within each planning region. NRCS last updated the SSURGO data that we downloaded in September 2019. Jones Edmunds used the SSURGO soil characteristic data combined with the *Characterization of Florida Soil* (University of Florida/Institute of Food and Agricultural Sciences [UF/IFAS], 2006) and other standard soil characterization references to develop the Green-Ampt infiltration parameters for the model.

### 4.1.3 Landcover and Impervious Mapping

Jones Edmunds used the following sources to generate a landcover map over the model domain:

- 2019 Palm Beach County existing land use mapping.
- 2018 USGS NHD.
- 2022 Microsoft statewide building footprints.
- Roadway map from the Village and Palm Beach County

The USGS NHDPlus dataset uses the 10-meter Three-Dimensional Elevation Program Digital Elevation Model (3DEP DEM) and the National Watershed Boundary Dataset (WBD) to map stream networks and waterbodies across the County. We supplemented our land cover dataset with the 2022 Microsoft building footprints feature class.

The study-wide landcover classification generated by Jones Edmunds consists of approximately 8,000 unique polygons. Jones Edmunds aggregated the previous sources to create a 5-foot countywide landcover raster categorized into eight classes. Table 7 lists the eight classes. Each class was then assigned a constant or depth-varying Manning's *n* value. Classes were also classified as being impervious or pervious. Impervious landcover classes do not allow infiltration to take place. In a traditional lumped-parameter model, impervious areas are generally classified as being made of directly connected or unconnected areas. However, the connectedness of the impervious areas is not defined in a high-resolution distributed model such as TUFLOW because the model simulates the infiltration downstream of the mapped impervious areas.

**Table 7 Modeled Landcover Parameters**

| Landcover | Roughness | | | | Pervious/ Impervious |
|---|---|---|---|---|---|
| | Depth 1 | | Depth 2 | | |
| | Depth (inch) | Manning's *n* | Depth (inch) | Manning's *n* | |
| Building | 0.1 | 0.02 | 0.3 | 3 | Impervious |
| Compacted Dirt | 0.1 | 0.022 | 0.3 | 0.022 | Impervious |
| Forest | 0.1 | 0.192 | 0.3 | 0.192 | Pervious |
| Grassed | 0.1 | 0.1 | 0.3 | 0.04 | Pervious |
| Paved | 0.1 | 0.011 | 0.3 | 0.011 | Impervious |
| Water | 0.1 | 0.03 | 0.3 | 0.03 | Impervious |
| Wetland | 0.1 | 0.1 | 0.3 | 0.1 | Impervious |
| Open Space | 0.1 | 0.06 | 0.3 | 0.06 | Pervious |

We based buildings on the 2022 Microsoft building footprints, which are represented explicitly in the landcover mapping. We defined buildings as having a low roughness at low-flow depths (0.1 inch) and a very high roughness at higher depths (0.3 inch). This representation allows the model to represent rainfall-induced runoff from building roofs with minimal attenuation while reducing overland flow velocity over areas defined as buildings within the landcover. Alternatives for modeling buildings included blocking buildings out of the 2D domain, which would prevent runoff from being generated from roofs, or raising the DEM elevations over buildings, thereby creating discontinuities in the DEM surface that can result in model instabilities.

### 4.1.4 1-D Hydraulic Features

The TUFLOW model employs a hydraulic method that is primarily grid-based surface routing of overland flow but is supplemented by one-dimensional (1D) modeling of hydraulic features such as significant culverts and stormwater inlets. The hydraulic feature modeling is more like a traditional 1D stormwater model.

Jones Edmunds obtained the asset database from the Village. Jones Edmunds reviewed the databases for completeness of pipe sizes and updated invert elevations where these elevations were missing or appeared unreasonable. We assigned these new elevations based on surrounding structure inverts or by setting a fixed cover relative to the LiDAR DEM.

Jones Edmunds then used the Village data and a desktop review to identify stormwater culverts, pipes, and weirs to include in the TUFLOW model. We selected structures based on our estimate of the structure's impact on the inundation mapping, especially for the simulated extreme rainfall events. We considered the intended planning-level accuracy of the final mapping when selecting these features. Most subsurface stormwater systems within the Village are designed for more frequently occurring storms and do not significantly impact inundation during extreme, infrequent storms. The same considerations were used to identify missing stormwater features in the Village data. Missing features were identified based on the LiDAR DEMs and preliminary model results and were added based on aerial imagery, street view, plan sets from ERPs, and the LiDAR DEMs. The model included 1,408 pipes, culverts, or weirs. In some cases, we made assumptions for the invert elevations or pipe dimensions based on the LiDAR DEMs, assumed pipe cover, and drainage area upstream of the structure.

For this planning-level inundation modeling, only primary hydraulic conveyance features were included in the model; however, a more detailed network of stormwater pipes and weirs could be added to the model in the future. All overland hydraulic routing is handled by the surface grid. Considered together, the countywide model's hydrologic and hydraulic approach allows the rapid generation of approximate inundation areas from a variety of rainfall events.

### 4.1.5 Design-Storm Rainfall

Jones Edmunds used the NOAA Atlas 14 rainfall totals to simulate flood risk in the Village for the following storms:

- 100-year/24-hour.
- 500-year/24-hour.
- 100-year/3-day.
- 500-year/3-day.

We assigned rainfall using the NOAA Atlas 14 rainfall depths based on the centroid of the watershed. Table 8 shows the rainfall values (in inches) for each storm event for each scenario.

**Table 8 Existing and Proposed SLR Scenario Rainfall Values**

| Storm Event | Existing Conditions (inches) | 2040 SLR (inches) | 2070 SLR (inches) |
|---|---|---|---|
| 100-Year/24-Hour | 16.1 | 18.5 | 19.3 |
| 500-Year/24-Hour | 21.9 | 25.4 | 26.9 |
| 100-Year/3-Day | 18.3 | 20.9 | 21.4 |
| 500-Year/3-Day | 25.1 | 28.6 | 30.1 |

### 4.1.6 Results Generation

For each scenario, Jones Edmunds tested the 24-hour and 3-day design events and generated flood elevation result rasters. We then compared the rasters at grid level and created a new raster to represent the scenario using the higher of the two at each grid. Figure 2 through Figure 11 show the flood depths for the 100- and 500-year return periods for the existing, 2040, and 2070 conditions, respectively.

## 4.2 Coastal Flooding

### 4.2.1 High Tide Flooding

To calculate the number of days that high tides would inundate each part of the Village, Jones Edmunds downloaded the most recent 2 years of hourly tide gauge data from Vaca Key. We created a lookup table for the existing conditions of the number of days that each elevation was exceeded by the highest tide elevation of each day. We then mapped the lookup table to the existing terrain data and checked where elevations may need to be breached for flooding to occur. We then updated the lookup tables using the SLR projections discussed in Part II, Section 3.4.2. Figure 12 through Figure 16 show the number of days of projected flooding due to high tides for the existing, 2040, and 2070 conditions, respectively. Figure 17 through Figure 19 show the corresponding depths of flooding for each condition, respectively.

To evaluate the potential extreme conditions, we also analyzed the high-tide scenario of 2 feet above mean higher-high water (MHHW). Figure 20 through Figure 24 show the inundation extent and flood depth for the existing, 2040, and 2070 conditions, respectively.

## Figure 2 Rainfall-Induced Flooding for the 100-Year Storm Event Under Existing Conditions



**Figure 3 Rainfall-Induced Flooding for the 100-Year Storm Event Under Intermediate – High 2040 Conditions**



**Figure 4 Rainfall-Induced Flooding for the 100-Year Storm Event Under Intermediate – High 2070 Conditions**



## Figure 5 Rainfall-Induced Flooding for the 500-Year Storm Event Under Existing Conditions



**Figure 6 Rainfall-Induced Flooding for the 500-Year Storm Event Under Intermediate – High 2040 Conditions**



**Figure 7 Rainfall-Induced Flooding for the 500-Year Storm Event Under Intermediate – High 2070 Conditions**



**Figure 8 Rainfall-Induced Flooding for the 100-Year Storm Event Under Intermediate – Low 2040 Conditions**



**Figure 9 Rainfall-Induced Flooding for the 100-Year Storm Event Under Intermediate – Low 2070 Conditions**



**Figure 10 Rainfall-Induced Flooding for the 500-Year Storm Event Under Intermediate – Low 2040 Conditions**



**Figure 11 Rainfall-Induced Flooding for the 500-Year Storm Event Under Intermediate – Low 2070 Conditions**



## Figure 12 High Tide Flooding Days Under Existing Conditions



## Figure 13 High Tide Flooding Days Under Intermediate – High 2040 Conditions



## Figure 14 High Tide Flooding Days Under Intermediate – High 2070 Conditions



## Figure 15 High Tide Flooding Days Under Intermediate – Low 2040 Conditions



## Figure 16 High Tide Flooding Days Under Intermediate – Low 2070 Conditions



## Figure 17 High Tide Flooding Depth Under Existing Conditions



## Figure 18 High Tide Flooding Depth Under Intermediate – High 2040 Conditions



## Figure 19 High Tide Flooding Depth Under Intermediate – High 2070 Conditions



## Figure 20 Extreme High Tide (2 Feet Above MHHW) Flooding Depth Under Existing Conditions



## Figure 21 Extreme High Tide (2 Feet Above MHHW) Flooding Depth Under Intermediate – High 2040 Conditions



## Figure 22 Extreme High Tide (2 Feet Above MHHW) Flooding Depth Under Intermediate – High 2070 Conditions



## Figure 23 Extreme High Tide (2 Feet Above NHHW) Flooding Depth Under Intermediate – Low 2040 Conditions



## Figure 24 Extreme High Tide (2 Feet Above NHHW) Flooding Depth Under Intermediate – Low 2070 Conditions



### 4.2.2 Storm Surge Flooding

Jones Edmunds calculated the storm surge for the 100-year storm for 2040 and 2070 conditions using the Intermediate-Low and Intermediate-High SLR projections. We started with the existing conditions SWEL raster from FEMA and created new SWEL rasters by adding the SLR projections to them. We then created an existing conditions BFE raster using coastal floodplains and BFE values from FEMA's DFIRM database. SWEL represents the elevated water level during a storm event, and BFE is the sum of SWEL and the additional height of waves that ride on top of the water surface. Using the BFE and SWEL rasters, we could approximate the wave height and wave type. We estimated wave heights under existing conditions for full and breaking waves using the following approximations:

- Full wave: (BFE raster – SWEL raster [no SLR])/0.7.
- Breaking wave: (SWEL raster [no SLR] – DEM)*0.78.

The full-wave equation is based on FEMA's assumption that 70-percent of the controlling wave height rides on top of the SWEL; the breaking-wave equation is based on the wave-height-to-water-depth ratio theoretical limit – 0.78 – derived from the solitary wave theory.

The full-wave estimates represent the full-wave height if the wave was not breaking; the breaking-wave estimates represent the maximum wave height that could occur at a given water depth before depth-induced breaking occurs. By comparing the two wave-height estimates, we then created a wave-type raster by characterizing the wave type that the local water depth could support. Where the full wave height is less than the breaking wave height, we set the value to the full-wave type. Where DEM > SWEL, we set the raster to no wave and buffered the raster to accommodate greater flood depths/areas. We then applied the same wave-height formulas previously detailed to the 2040 and 2070 SWEL rasters.

Figure 25 through Figure 27 show the depths of 100-year storm-surge flooding calculated under existing conditions and the Intermediate-Low SLR estimates for 2040 and 2070 conditions, respectively. Figure 28 and Figure 29 show the 100-year storm-surge flooding calculated under the Intermediate-High SLR estimates for 2040 and 2070 conditions, respectively. These figures show that nearly all of the Village west of Highway A1A is subject to 100- and 500-year coastal surge flood risk under 2040 and 2070 conditions. Table 9 summarizes the estimated maximum flood depths under each scenario.

**Table 9 Storm Surge Flooding Results**

| | Maximum Storm Surge Flood Depth (feet) | |
|---|---|---|
| | Int-Low | Int-High |
| Existing Conditions | 12.0 | |
| 2040 | 15.1 | 15.6 |
| 2070 | 15.7 | 17.5 |

## Figure 25 100-Year Storm Surge Flooding Under Existing Conditions



## Figure 26 100-Year Storm Surge Flooding Under Intermediate – Low SLR Projections for 2040 Conditions



## Figure 27 100-Year Storm Surge Flooding Under Intermediate – Low SLR Projections for 2070 Conditions



## Figure 28 100-Year Storm Surge Flooding Under Intermediate – High SLR Projections for 2040 Conditions



## Figure 29 100-Year Storm Surge Flooding Under Intermediate – High SLR Projections for 2070 Conditions



# 5 SENSITIVITY ANALYSIS

For the Sensitivity Analysis, Jones Edmunds began by comparing the results from the Exposure Analysis presented in Part III, Section 4 to the elevations of the critical and regionally significant assets presented in Part II, Section 3.1.

Table 10 shows the exposure level or severity we assigned to the flooding by critical asset.

Attachment 1 shows the results of the Sensitivity Analysis by asset for tidal flooding, Attachment 2 for rainfall-induced flooding, and Attachment 3 for coastal flooding. Table 11 provides a Village-wide summary by major asset type. All road segments within the Village were included for completeness and accordingly are labeled as Major Roadways in Attachments 1, 2, and 3. However, a finer definition of roadway type is given under Exposure Level Type. Unique IDs are also presented in the table to relate back to the GIS road layer. Figure 30 through Figure 57 show the critical asset locations and scenario specific risk ranking relative to the inundation results for each flood scenario from the exposure analysis.

We developed a risk-based methodology to rank the problem areas. With the severity of flooding assigned for each event as described above, we developed a weighting for the 16 scenarios analyzed. Flooding that would occur sooner and more frequently was assigned a higher weighting factor.

Table 12 shows the exposure weighting factor for the 16 scenarios. The high/medium/low (H/M/L) severities were assigned point values of 5/3/1, respectively. Each severity was multiplied by its respective weighting factor and totaled. The total was then normalized by dividing by 70 to generally put scores in the 0 to 10 range.

Each asset type was given an H/M/L rank corresponding to the same 5/3/1 scoring described above. Assets were also given a regionally significant score of 2/0 based on a H/L assignment.

Table 13 shows the priority and regional significance score assigned to each asset type. The normalized flooding score was then multiplied by the sum of the asset rank and regional significance scores. The total was then normalized again by dividing by 7 to generally put scores in the 0 to 10 range. Based on a distribution of the results, those numeric values were assigned an H/M/L value by using breakpoints in the total score of 4.5 and 3.0 by evaluating the distribution of total scores. Figure 58 shows the location and final composite ranking assignment of the critical assets.

The results in Attachments 1 to 3 are sorted by the final H/M/L assignments within the Focus Area. Part III, Section 6 describes the Focus Areas.

## Table 10 Exposure Level for Critical Assets

| Dataset | High | Medium | Low | High | Medium | Low |
|---|---|---|---|---|---|---|
| Airports | Exceeds critical elevation | Within 6 inches of critical elevation | Within 6-12 inches of critical elevation | 0 | -6 | -12 |
| Bridges | Dependent on road type. Local LOS criteria prevail. Greater than 12 inches above critical elevation (assumes 6 inch difference between edge and centerline) as a guideline. | Dependent on road type. Local LOS criteria prevail. Between 6-12 inches above critical elevation as a guideline. | Greater than critical elevation but less than 6 inches. Local LOS criteria prevail. | 12 | 6 | 0 |
| Bus Terminals | Building flooding or greater than 12 inches of flooding on paved surface | No building flooding and 6-12 inches on paved surface | Between 0-6 inches on paved surface | 12 | 6 | 0 |
| Ports | Building flooding or greater than 12 inches of flooding on paved surface | No building flooding and 6-12 inches on paved surface | Between 0-6 inches on paved surface | 12 | 6 | 0 |
| Evacuation Route | Greater than 0 inches of flooding | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Arterial | Greater than 6 inches of flooding | Greater than 3 inches of flooding | Within 0 inches of flooding | 6 | 3 | 0 |
| Collector | Greater than 9 inches of flooding | Greater than 6 inches of flooding | Within 0 inches of flooding | 9 | 6 | 0 |
| Local | Greater than 12 inches of flooding | Greater than 9 inches of flooding | Within 0 inches of flooding | 12 | 9 | 0 |
| Marinas | Building flooding | Within 6 inches of building flooding | Within 12 inches of building flooding | 0 | -6 | -12 |
| Rail Facilities | Building flooding or greater than 12 inches of flooding on paved surface | No building flooding and 6-12 inches on paved surface | Between 0-6 inches on paved surface | 12 | 6 | 0 |
| Railroad Bridges | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Waste Water Facilities | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Lift Stations | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Stormwater Facility | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Water Treatment Plants | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Water Supply Wells | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Ground Storage Tanks | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Water Distribution Pumps | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Electric Facilities | Within 24 inches of flooding | Within 30 inches of flooding | Within 36 inches of flooding | -24 | -30 | -36 |
| Electric Substations | Greater than 6 inches | Between 3-6 inches | Between 0-3 inches | 6 | 3 | 0 |
| Solid and Hazardous Waste Facilities | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Military Installations | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Radio Communications Towers | Greater than 6 inches | Between 3-6 inches | Between 0-3 inches | 6 | 3 | 0 |
| Disaster Debris Management Sites | Greater than 6 inches | Between 3-6 inches | Between 0-3 inches | 6 | 3 | 0 |
| Schools | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Day Cares | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Colleges and Universities | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Community Centers | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Correctional Facilities | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Disaster Recovery Centers | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Emergency Medical Service Facilities | Greater than 6 inches | Between 3-6 inches | Between 0-3 inches | 6 | 3 | 0 |
| Emergency Operation Centers | Greater than 6 inches | Between 3-6 inches | Between 0-3 inches | 6 | 3 | 0 |
| Fire Stations | Greater than 6 inches | Between 3-6 inches | Between 0-3 inches | 6 | 3 | 0 |
| Health Care Facilities | Greater than 6 inches | Between 3-6 inches | Between 0-3 inches | 6 | 3 | 0 |
| Hospitals | Greater than 6 inches | Between 3-6 inches | Between 0-3 inches | 6 | 3 | 0 |
| Law Enforcement Facilities | Greater than 6 inches | Between 3-6 inches | Between 0-3 inches | 6 | 3 | 0 |
| Local Government Facilities | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Affordable Public Housing | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Risk Shelter Inventory | Greater than 6 inches | Between 3-6 inches | Between 0-3 inches | 6 | 3 | 0 |
| State Government Facilities | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Conservation Lands | Greater than 24 inches | Between 18-24 inches | Between 12-18 inches | 24 | 18 | 12 |
| Parks | Greater than 24 inches | Between 18-24 inches | Between 12-18 inches | 24 | 18 | 12 |
| Shorelines | Greater than 24 inches | Between 18-24 inches | Between 12-18 inches | 24 | 18 | 12 |
| Surface Waters | NA | NA | NA | | | |
| Wetlands | NA | NA | NA | | | |
| Historical and Cultural Assets | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |
| Historical Cultural Assets - Sites | Greater than 0 | Within 3 inches of flooding | Within 6 inches of flooding | 0 | -3 | -6 |

## Table 11 Village-Wide Summary of Exposure Level Results for Critical Assets

| Asset Class | Total Number of Critical Assets | Exposure Level | Number of critical assets by exposure level | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | 100-YR Rainfall-Induced Flooding | | | 500-YR Rainfall-Induced Flooding | | | Tidal Flooding | | | | | 100-YR Storm Surge Flooding | | | | | |
| | | | Existing Conditions | Intermediate-High | | Existing Conditions | Intermediate-High | | Existing Conditions | Intermediate-Low | | Intermediate-High | | Existing Conditions | Intermediate-Low | | Intermediate-High | |
| | | | | 2040 | 2070 | | 2040 | 2070 | | 2040 | 2070 | 2040 | 2070 | | 2040 | 2070 | 2040 | 2070 |
| Transportation and Evacuation Routes | 267 | High | 163 | 186 | 206 | 213 | 230 | 236 | 1 | 1 | 1 | 1 | 24 | 25 | 101 | 121 | 119 | 151 |
| | | Medium | 32 | 31 | 18 | 15 | 6 | 6 | 0 | 0 | 0 | 0 | 8 | 3 | 8 | 5 | 3 | 6 |
| | | Low | 30 | 19 | 14 | 13 | 10 | 8 | 0 | 0 | 2 | 1 | 35 | 1 | 19 | 11 | 15 | 9 |
| Critical Infrastructure | 70 | High | 7 | 11 | 16 | 16 | 21 | 25 | 0 | 0 | 0 | 0 | 4 | 3 | 5 | 8 | 8 | 15 |
| | | Medium | 1 | 1 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| | | Low | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 1 | 0 |
| Critical Community and Emergency Facilities | 25 | High | 0 | 0 | 0 | 1 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 |
| | | Medium | 0 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| | | Low | 0 | 0 | 0 | 1 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 |
| Natural, Cultural, and Historical Resources | 31 | High | 18 | 18 | 18 | 18 | 18 | 18 | 11 | 11 | 12 | 12 | 12 | 11 | 13 | 13 | 13 | 13 |
| | | Medium | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| | | Low | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

## Figure 30 Critical Assets with Rainfall Flooding Depth for the 100-Year Storm Event Under Existing Conditions



**Figure 31 Critical Assets with Rainfall Flooding Depth for the 100-Year Storm Event Under Intermediate – High 2040 Conditions**



**Figure 32 Critical Assets with Rainfall Flooding Depth for the 100-Year Storm Event Under Intermediate – High 2070 Conditions**



## Figure 33 Critical Assets with Rainfall Flooding Depth for the 500-Year Storm Event Under Existing Conditions



**Figure 34 Critical Assets with Rainfall Flooding Depth for the 500-Year Storm Event Under Intermediate – High 2040 Conditions**



**Figure 35 Critical Assets with Rainfall Flooding Depth for the 500-Year Storm Event Under Intermediate – High 2070 Conditions**



## Figure 36 Critical Assets with Rainfall Flooding Depth for the 100-Year Storm Event Under Intermediate – Low 2040 Conditions



## Figure 37 Critical Assets with Rainfall Flooding Depth for the 100-Year Storm Event Under Intermediate – Low 2070 Conditions



## Figure 38 Critical Assets with Rainfall Flooding Depth for the 500-Year Storm Event Under Intermediate – Low 2040 Conditions



## Figure 39 Critical Assets with Rainfall Flooding Depth for the 500-Year Storm Event Under Intermediate – Low 2070 Conditions



## Figure 40 Critical Assets with High-Tide Flooding Days Under Existing Conditions



## Figure 41 Critical Assets with High-Tide Flooding Days Under Intermediate – High 2040 Conditions



## Figure 42 Critical Assets with High-Tide Flooding Days Under Intermediate – High 2070 Conditions



## Figure 43 Critical Assets with High-Tide Flooding Days Under Intermediate – Low 2040 Conditions



## Figure 44 Critical Assets with High-Tide Flooding Days Under Intermediate – Low 2070 Conditions



## Figure 45 Critical Assets with High-Tide Flooding Depth Under Existing Conditions



## Figure 46 Critical Assets with High-Tide Flooding Depth Under Intermediate – High 2040 Conditions



## Figure 47 Critical Assets with High-Tide Flooding Depth Under Intermediate – High 2070 Conditions



## Figure 48 Critical Assets with Extreme High-Tide (2 Feet Above MHHW) Flooding Depth Under Existing Conditions



## Figure 49 Critical Assets with Extreme High-Tide (2 Feet Above MHHW) Flooding Depth Under Intermediate – High 2040 Conditions



## Figure 50 Critical Assets with Extreme High-Tide (2 Feet Above MHHW) Flooding Depth Under Intermediate – High 2070 Conditions



## Figure 51 Critical Assets with Extreme High-Tide (2 Feet Above NHHW) Flooding Depth Under Intermediate – Low 2040 Conditions



## Figure 52 Critical Assets with Extreme High-Tide (2 Feet Above NHHW) Flooding Depth Under Intermediate – Low 2070 Conditions



## Figure 53 Critical Assets with 100-Year Storm-Surge Flooding Under Existing Conditions



## Figure 54 Critical Assets with 100-Year Storm-Surge Flooding Under Intermediate – Low SLR Projections for 2040 Conditions



## Figure 55 Critical Assets with 100-Year Storm-Surge Flooding Under Intermediate – Low SLR Projections for 2070 Conditions



## Figure 56 Critical Assets with 100-Year Storm-Surge Flooding Under Intermediate – High SLR Projections for 2040 Conditions



## Figure 57 Critical Assets with 100-Year Storm-Surge Flooding Under Intermediate – High SLR Projections for 2070 Conditions



**Table 12 Exposure Weighting Factor**

| Flood Scenario | Exposure Weighting Factor |
|---|---|
| Tidal MHHW+2ft Existing Conditions | 50 |
| Tidal MHHW+2ft Int-Low 2040 | 40 |
| Tidal MHHW+2ft Int-Low 2070 | 20 |
| Tidal MHHW+2ft Int-High 2040 | 30 |
| Tidal MHHW+2ft Int-High 2070 | 10 |
| Rainfall 100-YR/24-HR Existing Conditions | 24 |
| Rainfall 100-YR/24-HR Int-High 2040 | 9 |
| Rainfall 100-YR/24-HR Int-High 2070 | 3 |
| Rainfall 500-YR/24-HR Existing Conditions | 18 |
| Rainfall 500-YR/24-HR Int-High 2040 | 3 |
| Rainfall 500-YR/24-HR Int-High 2070 | 1 |
| Storm Surge 100-YR Existing Conditions | 24 |
| Storm Surge 100-YR Int-Low 2040 | 12 |
| Storm Surge 100-YR Int-Low 2070 | 6 |
| Storm Surge 100-YR Int-High 2040 | 9 |
| Storm Surge 100-YR Int-High 2070 | 3 |

**Table 13 Asset Priorities and Regional Significance**

| Dataset | Priority | Regionally Significant |
|---|---|---|
| Airports | High | Yes |
| Affordable Public Housing | High | No |
| Bridges | High | No |
| College | Low | No |
| Community Center | Low | No |
| Correctional Facility | Medium | No |
| Conservation Lands | High | Yes |
| Dam | High | No |
| Day Care | Low | No |
| Discharge Structure | High | Yes |
| Disaster Recovery Centers | High | No |
| Ground Storage Tanks | High | Yes |
| Water Distribution Pumps | High | Yes |
| Drinking Water Well | High | Yes |
| Electric Facilities | High | Yes |
| Elevated Storage Tank | High | Yes |
| Emergency Operation Centers | High | Yes |
| Fire Stations | High | Yes |
| Gas Pump | Low | No |
| Gas Station Facility | Low | No |

| Dataset | Priority | Regionally Significant |
|---|---|---|
| Generator | High | Yes |
| Health Care Facilities | High | No |
| Hospitals | High | Yes |
| Historical and Cultural Asset | Medium | No |
| Historical Cultural Assets - Sites | Medium | No |
| Law Enforcement Facilities | High | Yes |
| Lift Stations | High | Yes |
| Local Government Facilities | High | No |
| Major Roadway | High | No |
| Arterial | High | No |
| Collector | High | No |
| Minor Arterial | High | No |
| Minor Collector | High | No |
| Local | High | No |
| Marina | Low | No |
| Military Installation | High | No |
| Parks | Low | No |
| Port | Medium | No |
| Water Supply Wells | High | Yes |
| Railroad | High | No |
| Railroad Bridge | High | No |
| Radio Communication Towers | Medium | Yes |
| Risk Shelter | High | No |
| Schools | Low | No |
| Shorelines | Low | No |
| Solid Waste Facility | Medium | No |
| State Government Facility | High | No |
| SNAP-Authorized Retailer | Medium | No |
| Stormwater Facility | Low | No |
| Surface Waters | Low | No |
| Surface Waters | Low | No |
| Vacuum Station | High | Yes |
| Wastewater Lift Station | High | Yes |
| Wastewater Treatment Facility | High | Yes |
| Water Treatment Plants | High | No |
| Water Treatment Facility | High | No |
| Wetlands | Low | No |
| Emergency Medical Service Facilities | High | Yes |

## Figure 58 Exposure-Level Ranking of Critical Assets



# 6 FOCUS AREAS

The Village was subdivided into three Focus Areas based on characteristics of urbanization and clustering of critical assets. Figure 59 shows the boundaries of the three Focus Areas and that the downtown/central portion of the Village (Focus Area 2) has the largest concentration of critical and regionally significant assets. Focus Area 2 is the most urbanized area and contains the largest concentration of critical and regionally significant assets that are projected to be adversely impacted by flooding in the future. Accordingly, this area will be the primary Focus Area for adaptation planning. However, adaptation planning will cover the entire City. Focus Areas 1 and 3 are less urbanized and contain a lower density of critical assets. The coastal and intracoastal regions make up Focus Area 1, and Focus Area 3 encompasses the west peninsula of Tequesta, largely occupied by the Tequesta Country Club and adjacent residential communities.

Part II, Section 4 shows that future flooding during extreme events is widespread throughout the Village – particularly regarding rainfall and storm surge flooding. However, not all problem areas can be addressed in the short term due to budget limitations and the practicality of how many projects can be managed and implemented at one time. To that end, we reviewed priorities with the Village to determine the top problem areas to address as part of an Initial Adaptation Plan. The top five priorities identified are the following:

1. Elevate the Village Hall, Public Safety Building, and Rec Center generators.
2. Restore and improve Dover Ditch (Dover Ditch Living Shoreline Project).
3. Improve Village roads subject to existing and future flooding with feasible solutions.
4. Increase resiliency at the water treatment plant (WTP).
5. Increase resiliency at the wastewater lift stations by working with Loxahatchee River District.

## Figure 59 Focus Area Boundaries



# PART IV. PRELIMINARY ADAPTATION PLAN

# 7 INITIAL ADAPTATION PLAN

The Village's Adaption Plan will generally follow the guidance in FDEP's *Florida Adaptation Planning Guidebook*. In that document, Adaptation Strategies are broken into the following items:

- Assess Adaptive Capacities
- Prioritize Adaptation Needs
- Identify Adaptation Strategies
- Integrate into Existing Plan

This Initial Adaptation Plan is an early-out prioritization of needs and adaptation strategies and focuses on solutions to the Village's highest priorities identified in Part III, Section 6.

## 7.1 PRIORITIZATION OF ADAPTATION NEEDS

To identify adaptation needs for the Initial Adaptation Plan, Jones Edmunds:

- Reviewed previous grant submissions, the Village's 20-year Capital Improvement Plan (CIP), the Village's Comprehensive Plan, the Village's FY 2023-2024 budget, and the County's Local Mitigation Strategy (LMS) and Prioritized Project List for existing needs that had already been identified.
- Received feedback from Village staff on their highest priority areas of concern.
- Reviewed the highest-ranked critical assets from the sensitivity analysis and identified areas of potential adaptation need.

Based on this review, potential adaptation needs were identified. Jones Edmunds reviewed the areas that were identified with Village staff to determine the relative priority of the adaptation needs. The following sections summarize the high-priority adaptation projects/ strategies that were identified.

## 7.2 ELEVATE THE VILLAGE HALL, PUBLIC SAFETY BUILDING, AND REC CENTER GENERATORS

The grade surrounding the generator at the Rec Center is projected to be within 1.1 feet of submersion from a 100-year rainfall event under existing conditions and 2.4 feet under water from a 100-year coastal surge event by 2070 under Intermediate-High conditions. At the Village Hall, the grade surrounding the generator is expected to be within 1.4 feet of submersion from a 100-year rainfall event under existing conditions and 1.1 feet from a 500-year rainfall event by 2040 under Intermediate-High conditions. Similarly, the grade surrounding the generator at the Public Safety Building is projected to be within 2.2 feet of submersion from a 100-year rainfall event under existing conditions and 1.9 feet from a 500-year rainfall event by 2040 under Intermediate-High conditions.

When a generator is flooded, several critical issues can arise. A generator cannot supply power when flooded, and the flood water can cause significant damage to the internal

components, rendering the generator inoperable. This failure can lead to significant disruptions, especially for essential services and critical infrastructure. For instance, if the generators at the Village Hall, Public Safety Building, and Rec Center were to be flooded, emergency response operations would be severely disrupted, public safety compromised, and essential government services hindered. These buildings house regionally critical infrastructure, and their operational integrity is vital during and after a disaster. Elevating these generators should be a priority to ensure continuous power supply, minimize recovery time, and maintain the resilience of the Village's emergency management and governmental functions.

The current grades of the generators at the Rec Center, Village Hall, and Public Safety buildings are approximately 8.3, 12.9, and 14.3 feet NAVD88, respectively. The plan is to install new generators at the existing locations at an elevation that would place the top of slab above the rainfall and coastal surge event, which would place it above the existing grade.

Generators for the Village Hall and Public Safety Building have been identified by Palm Beach County as important community long-term mitigation projects and are included in the Prioritized Project List for fall 2023 and spring 2024. The estimated cost for a new generator at the Public Safety Building is $535,000 and $450,000 at the Village Hall. The Village solicited proposals for the design and installation of the generator at Village Hall, with a deadline of August 14, 2024. Hazard Mitigation Grant Program (HMGP) funding has been approved for these two projects. HMGP is a grant with a 75-percent federal and 25-percent state/local match, which can be covered by cash or in-kind sources.

## 7.3 Restore and Improve Dover Ditch (Dover Ditch Living Shoreline Project)

Dover Ditch, a major drainage canal stretching a half mile along the border of the Village of Tequesta and the Town of Jupiter, flows westward into the North Fork Loxahatchee River. It serves as a crucial stormwater outlet and flood protection system for adjacent single-family neighborhoods. However, since the 1990s, the canal's embankment has suffered from long-term erosion, leading to sediment displacement into the Loxahatchee Estuary. This erosion has diminished the natural habitat, water conveyance capacity, and flood protection capabilities of both waterways.

The surrounding neighborhoods are currently at risk of significant flooding, with projections indicating up to 2.7 feet of inundation from a 100-year rainfall event and 2.3 feet from a 100-year coastal surge event under existing conditions. By 2070, under Intermediate-High sea level rise (SLR) scenarios, these areas could face up to 3.6 feet of flooding from a 100-year rainfall event and 5.8 feet of flooding from a 100-year coastal surge event.

As sea levels continue to rise, the canal’s flood protection capacity is expected to further deteriorate, with notable impacts expected by 2040 and 2070. This ongoing degradation poses an increasing threat to the area's flood resilience. Critical assets in this area include 26 local roads and one lift station, which are all vulnerable to flooding from rainfall and coastal surge 100-year and 500-year events.

Chen Moore & Associates has designed the Dover Ditch Living Shoreline Project to rehabilitate and enhance the westernmost 350 feet of Dover Ditch. Figure 60 shows the proposed plan view of the project. This initiative involves dredging, realigning, and stabilizing the canal section to establish a living shoreline and meandering channel. The project aims to boost aquatic habitat, enhance water quality, and improve flood protection and water conveyance. These goals are consistent with the Coastal Management Element goals and objectives described in the Village's Comprehensive Plan.

**Figure 60 Dover Ditch Living Shoreline Project Plan View**




The living shoreline will feature 1,100 square feet of engineered wetlands comprising four 10-foot-wide planting zones – two for Maritime Hammock vegetation that remains dry at high tide, and two for Intertidal Salt Marsh plants that submerge during high tide. This design is projected to reduce sediment deposition by up to 57 tons annually, mitigating future erosion and turbidity issues.

Chen Moore estimates that the project will decrease Total Nitrogen (TN) by 93 grams per square meter per year (g/m²-yr) and Total Phosphorus (TP) by 0.52 g/m²-yr. Furthermore, the enhanced habitat is expected to significantly increase local biodiversity, with fish abundance projected to rise by 220 percent and overall biodiversity by 130 percent.

The estimated construction cost for this project is $315,000. Progress has been made toward its implementation. The properties within the project area are owned by the project sponsors. The preliminary engineering design is completed, and the detailed engineering design and permits are currently in progress. The Town of Jupiter and the Village of Tequesta, who jointly share maintenance responsibilities for Dover Ditch, have applied for

and received a joint grant with a 50-percent local match from the Loxahatchee River Preservation Initiative Grant.

The project design also includes installing a concrete weir at the east boundary of the enhanced section of Dover Ditch where it interfaces with the rest of the canal. Although this weir can regulate flow from the unimproved to the improved section, it does not provide flood protection from SLR in the unimproved portion. An alternative approach would be to install a control structure, which would enable water-level management in the larger, unimproved section of the canal where adjacent neighborhoods discharge stormwater. This control structure would offer greater flexibility, allowing operators to lower water levels before storm events and raise gates to prevent inflow during high sea levels. Such a system could significantly enhance long-term resilience against rising sea levels, providing more comprehensive flood protection for the entire canal system and surrounding areas.

## 7.4 Village Roads Subject to Existing and Future Flooding with Feasible Solutions

Part III, Section 5 shows that numerous road segments in the Village experience flooding under existing conditions during 100-year events. Of the 240 Village-owned road segments, 209 (87 percent) are vulnerable to at least one type of flooding. Specifically, 29 segments (12 percent) are at risk from 100-year rainfall and coastal surge events under existing conditions, and 162 segments (68 percent) are projected to be vulnerable to both types of events by 2070. These flooding issues are expected to worsen with projected increases in rainfall and SLR. Although completely eliminating flooding from rare events may not be possible, feasible solutions can reduce the frequency of flooding in some areas.

The Village's stormwater system inventory consists of approximately 12.6 miles of buried culverts, 0.5 mile of Dover Ditch, four pollutant separators, and three water-level control structures. In recent years, the Village has planned and invested in the repair and rehabilitation of this stormwater system. The Village has projected the end of the useful life of these assets and adopted a 20-year Stormwater CIP to plan for their replacement and pipe lining. Of the 17 replacement projects in the CIP, the largest are the installation of 518 feet of pipe along Tequesta Drive/Point Drive and 1,065 feet along Dover Road/Dover Circle. These projects aim to restore and enhance the stormwater-conveyance and flood-protection capabilities of the existing system, with an estimated total cost of approximately $822,100.

Swale restoration is another feasible solution for stormwater improvement. Most Village roads originally had swales, but over time, they have significantly degraded or filled in and need restoration. Swales are natural systems that can store and slow down stormwater runoff by ponding water between their sloping sides. This ponding not only reduces road flooding but also allows pollutants to settle out of the water. Eventually, the remaining ponded water will either evaporate or infiltrate into the soil. Swale restoration is a nature-based solution that can mitigate flood risk and improve water quality, with an estimated cost of approximately $25,000 in the CIP.

Another stormwater improvement solution is to install tide check valves that close during storm events to temporarily sever the connection until the tide level recedes. Some installations may also require minor grading to prevent overland connections. The CIP

identified four outfalls that could benefit from check valve installation: Tequesta Bridge, River Drive, Pinehill Trail W, and Gulfstream Drive. The CIP estimated the total cost for these restorations to be approximately $223,000.

Implementing these protective measures could minimize the frequency and severity of flooding on Village roads, reducing associated disruptions and flood damage costs.

## 7.5 More Resilient WTP

The Village of Tequesta owns and maintains the WTP, which is a critical infrastructure for the community. To enhance the resilience of the WTP, the primary improvement needed is to elevate or floodproof the most critical components such as the generator, electrical building, and pumps. Projections indicate that the ground storage tanks may also experience inundation of up to 0.6 foot during a 100-year rainfall event by 2070, potentially increasing to 1.4 feet during a 500-year event. However, for tanks of this size and type, inundation at these depths is not expected to pose significant operational or structural issues.

A detailed assessment will be required to analyze each of the WTP's components relative to the projected flood elevations and determine the best strategy for modifying each component to handle the projected flooding conditions. The Village could expect the detailed evaluation to cost approximately $30,000.

## 7.6 More Resilient Wastewater Lift Stations

The Loxahatchee River District owns and maintains the wastewater infrastructure, which is critical for the Village. Seventeen of the wet wells within the Village are low-lying and vulnerable to tidal, rainfall, and coastal storm surge flooding. To enhance resilience, these lift stations may need to be elevated out of the floodplain or modified to operate under projected flooding conditions.

A detailed cost estimate for these improvements was not developed since the assets are not owned or maintained by the Village. Any upgrades to the wet wells would need to be initiated by the District. The Village should continue to coordinate with the District, sharing results from this study and providing support for potential improvements.

# Appendix A

# Kick-Off Meeting
# Minutes and Sign-In Sheet

# KICKOFF MEETING MINUTES

| | |
|---|---|
| **PROJECT:** | FDEP Vulnerability Assessment |
| **PROJECT NO.:** | 20850-002-01 |
| **MEETING DATE:** | November 22, 2022 |
| **SUBJECT:** | Kick-Off Meeting |
| **PARTICIPANTS:** | Village of Tequesta – Marjorie Craig, Doug Chambers, David Tinoco |
| | Jones Edmunds – Karen Liang, Brett Cunningham, Alex Buchans |

The following are minutes for the Village of Tequesta's FDEP Vulnerability Assessment Kickoff Meeting. The list of attendees is provided above, and a copy of the sign-in sheet is attached. Action items from the meeting are in bold font below.

- Reviewed the project goals as stated in the kickoff meeting agenda.
- Reviewed project scope and FDEP Work Plan. Specific items of discussion included:
    - Marjorie commented that DEP has funding, we can potentially explore expanding the scope if needed within this funding cycle.
    - Emails for the project should begin with "FDEP Vulnerability Assessment" in the Subject line.
    - We intend to touch base approximately once a month to review progress and discuss any issues that have come up. More immediate concerns will be communicated in a timelier manner with the Village.
    - No Steering Committee is included for this project (not needed).
    - Public Outreach meetings and timing were discussed. Up to two Public Outreach meetings are included in the scope. Jones Edmunds recommended holding one meeting towards the beginning of the project before the Exposure Analysis and one later in the project following completion of the Exposure and Sensitivity Analyses. **Marjorie will have internal discussion about when to host the 2 public outreach meetings.**
    - Acquisition and sources of background data were discussed, with an emphasis on critical asset data.
        - Jones Edmunds has compiled available local, state, and national datasets and made those available for review by the Village via a web map and a draft gap analysis summary spreadsheet. **Jones Edmunds will also provide the currently compiled critical assets to the Village in a second spreadsheet.**
        - **The Village will review the currently compiled critical assets as part of a gap analysis and complete the review by mid-January 2023.**
        - The City and Jones Edmunds will collectively prioritize what missing critical asset data will be collected with the remainder of the task budget after mid-January 2023.
        - There is a NASA site that is labeled as an Air Force site. It is for missile launching purpose.
        - The Emergency Operations Center is in the fire station. **Jones Edmunds will add a spatial point for it.**
    - Exposure analysis task was discussed.
        - Jones Edmunds reviewed the FDEP required scenarios and flood sources that will be included in the analysis.
        - Jones Edmunds will create a TUFLOW model of the Village and its contributing areas to simulate rainfall-induced flooding.

        - Future conditions storm surge exposure will be calculated using a process similar to FEMA's.
    - Sensitivity Analysis task was discussed.
        - Jones Edmunds will incorporate elevation data for critical assets provided by the Village and estimate other elevations based on previously used methods.
    - Identification of Focus Areas was discussed.
        - It is anticipated that flooding in the future scenarios will be extensive throughout the Village due to its elevations and proximity to the coast. The Village will assist Jones Edmunds in reviewing the sensitivity analysis results to determine focus areas in which adaptation projects will be developed.
    - Adaptation Planning was discussed.
        - Jones Edmunds reiterated that this is a preliminary adaptation planning effort, but enough projects (five) should be generated to cover several years' worth of construction grant applications. For some projects, a design phase may be needed in advance of the construction grant application.
        - Projects will be developed to maximize points based on FDEP's scoring criteria.
        - The initial Adaptation Plan may also include non-structural recommendations.
- The proposed schedule was reviewed briefly. The project should be completed well in advance of the grant deadline. Initial efforts will be focused on data collection.
- Marjorie Craig and Karen Liang will by the primary points of contact for the project, but all kickoff meeting participants should be copied on project correspondence.

# Village of Tequesta Vulnerability Assessment Kickoff Meeting

Tuesday, November 22, 2022
10AM – 11:30AM ET
345 Tequesta Drive, Tequesta, Florida 33469

## ATTENDEE SIGN-IN SHEET

**(PLEASE PRINT)**

| NAME | ENTITY/COMPANY | PHONE AND EMAIL |
|---|---|---|
| Brett Cunningham | Jones Edmunds | PHONE: 325.871.7048<br>EMAIL: bcunningham@jonesedmunds.com |
| Marjorie Craig | Village of Tequesta | PHONE: 561.768.0459<br>EMAIL: mcraig@tequesta.org |
| Doug Chambers | Village of Tequesta | PHONE: 561.945.1389<br>EMAIL: dchambers@tequesta.org |
| Karen Liang | Jones Edmunds | PHONE: 561.236.7943<br>EMAIL: KLiang@jonesedmunds.com |
| Alex Buchans | Jones Edmunds | PHONE: 352-377-5821 ext.1466<br>EMAIL: ABuchans@jonesedmunds.com |
| David Tinonco | Village of Tequesta | PHONE: 561.768.0484<br>EMAIL: dtinoco@tequesta.org |
| | | PHONE:<br>EMAIL: |
| | | PHONE:<br>EMAIL: |
| | | Phone:<br>EMAIL: |
| | | Phone:<br>EMAIL: |

# Appendix B

# Public Outreach Meeting #1
# Minutes and Sign-In Sheet

# KICKOFF MEETING MINUTES

| | |
|---|---|
| **PROJECT:** | FDEP Vulnerability Assessment |
| **PROJECT NO.:** | 20850-002-01 |
| **MEETING DATE:** | August 16, 2023 |
| **SUBJECT:** | Public Outreach Meeting #1 |
| **PARTICIPANTS:** | Village of Tequesta – Marjorie Craig, Rick Sartory, Tom Bradford, Jeremy Allen<br>Jones Edmunds – Karen Liang, Brett Cunningham, Alex Buchans |

The following are minutes for the Village of Tequesta's FDEP Vulnerability Assessment Public Outreach Meeting #1. The list of attendees is provided above, and a copy of the sign-in sheet is attached. A copy of the presentation is attached as well. Action items from the meeting are in bold font below.

- Karen presented a Powerpoint presentation to go over the project's background, goals, scope, data collection, data gaps, and engineering models.
- During introduction, Tom explained that he was part of the Town of Palm Beach's vulnerability assessment (town funded) effort in 2019 and he wants to ensure that all assets are considered, including sewer lift stations.
- After the presentation, the following was discussed:
    - Tom noted Tequesta Park could be added as disaster debris management site. Not currently designated as such, but most likely candidate if Village needed one – lots of open space.
        - Marjorie commented that the Village is tied to the County, so the debris can be sent to SWA. To use Tequesta Park, it has to be designated prior to a disaster event.
    - Rick commented that, in one of the 2040 inundation examples, it appears many areas will become inundated, including residential areas.
        - Marjorie remarked that it's the 100yr (or 1% chance) event, not necessary mean they will be underwater by 2040.
    - Tom asked if stormwater network assets included in the critical assets database? Catch basins, etc could be considered for flood control.
        - Karen noted we have major stormwater assets from data provided by the Village. JE added additional ones during the modeling effort from ERPs and estimation, those could be added to the database.
        - Marjorie is interested in capturing these estimated assets using additional grant funding that the Village may apply for.
    - Marjorie noted other data gaps JE identified, as possibilities to be address with the additional grant funding
        - Shoreline and wetlands, delineation candidates
        - Water distribution pumps are all at the WTP
            - Tom Bradford added that there is a pump in the water well at every well location. **JE will confirm that they are included in the database.**
        - **JE will provide Marjorie with the last list of data gaps and a GIS shapefiles of the stormwater assets that JE manually added during modeling.**
    - Tom asked about the rainfall change factor. Given the recent drought experienced locally and in other states, can we reliably assume that rainfall amount will increase in the future?
        - Karen responded that the change factor is a projection of the future based on best available data. We used the FIU values because they cover the required

2040 and 2070 planning horizons, and they are comparable to the values from another effort performed by USGS/SFWMD/FIU.

- Tom expressed concern that as public views final report and maps, they will ask how the Village and/or State will help them (private properties) with flood risk and damage. So how is private property being considered in this vulnerability assessment? Are there other funding sources?
  - Karen noted FEMA has a Residential Buyout Program that targets repetitive loss properties.
  - Brett noted that this grant program is very specific for publicly owned critical assets. He mentioned there are other programs from the State that address flooding and sea level rise risk to private property. Private properties could also benefit from adaptation actions that target critical assets.
- During the presentation, feedback was requested for locations of flood prone areas. **Marjorie and JE will work together to develop a list.** One of the areas is near the intersection of Tequesta Drive and Cypress Drive.

Village of Tequesta – Utilities Department
345 Tequesta Dr, Tequesta, FL 33469

# SIGN-IN SHEET

**August 16, 2023**
**VILLAGE OF TEQUESTA PUBLIC MEETING**
**On the Vulnerability Assessment – Grant Funded by the Florida Department of Environmental Protection**

| NAME | ADDRESS | E-MAIL ADDRESS/ PHONE |
|---|---|---|
| RICK SARTORY | 515 N. DOVER RD, TEQ | RSARTORY@TEQUESTA.ORG |
| Tom BRADFORD | 44 CHESTNUT TR, TEQ, FL | tgbradford3@gmail.com |
| Karen Liang | 237 Atwell Drive, WPB, FL | kliang@jonesedmunds.com/561-236-7943 |
| MARJORIE CRAIG | UTILITIES DIRECTOR 345 TEQUESTA | mcraig@tequesta.org |
| Jeremy Allen | 345 Tequesta Drive | jallen@tequesta.org |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

# Appendix C

# Public Outreach Meeting #2
# Minutes and Sign-In Sheet

# KICKOFF MEETING MINUTES

| | |
|---|---|
| **PROJECT:** | FDEP Vulnerability Assessment |
| **PROJECT NO.:** | 20850-002-01 |
| **MEETING DATE:** | June 26, 2024 |
| **SUBJECT:** | Public Outreach Meeting #2 |
| **PARTICIPANTS:** | Village of Tequesta – Marjorie Craig, Jeremy Allen |
| | Public - Tom Bradford, Jenn Todd, Nick |
| | Jones Edmunds – Karen Liang, Brett Cunningham, Alex Buchans |

The following are minutes for the Village of Tequesta's FDEP Vulnerability Assessment Public Outreach Meeting #2. The list of attendees is provided above, and a copy of the sign-in sheet is attached. A copy of the presentation is attached as well. Action items from the meeting are in bold font below.

- Karen presented a Powerpoint presentation to go over the project's background, goals, sensitivity analysis, and preliminary focus areas.
- During the presentation, the following was discussed:
    - The sensitivity analysis results suggest that half of the lift stations are at risk of being flooded. Marjorie noted that Loxahatchee owns the lift stations so it is not Tequesta's responsibility, but we can notify Loxahatchee.
    - Other than the intersection of Tequesta Drive and Cypress Drive, Tom noted frequent flooding is also experienced at near the intersection of Willow Road and Tequesta Drive.
    - Dover has no known complaints of recent floodings.
        - Tom commented that there used to be frequent floodings prior to the improvements made in the 1990s, the improvements resolved the issue.
        - Jenn commented, as a resident on Dover, she's only witnessed minor flooding on the driveway.
        - Marjorie pointed out that the extreme events that this study analyzes are more severe than the usual events that are typically observed.
    - Dover Outfall drains stormwater from Dover and discharges into Dover Ditch. The condition and the elevations of the outfall were discussed, low topography appears to be the main issue. Marjorie mentioned that there is a newly proposed living shoreline project for Dover Ditch, Tequesta will provide Jones Edmunds with the information.
    - Marjorie commented that there is a 10yr plan for stormwater pipelining that needs funding.
    - Swales have deteriorated over the years. Restoration and/or addition of swales along the roads could mitigate road flood risk.
    - **Tequesta and JE will work together to finalize the focus areas list and develop an adaptation plan**.

# Village of Tequesta Vulnerability Assessment Public Outreach Meeting #2

Wednesday, June 26, 2024
5:30PM – 6:30PM ET
345 Tequesta Drive, Tequesta, Florida 33469

## ATTENDEE SIGN-IN SHEET

**(PLEASE PRINT)**

| NAME | ENTITY/COMPANY | PHONE AND EMAIL |
|---|---|---|
| Brett Cunningham, PE, ENV SP | Jones Edmunds | PHONE: 305.871.7049<br>EMAIL: bcunningham@jonesedmunds.com |
| Karen Liang, PE, CFM | Jones Edmunds | PHONE: 561.236.7949<br>EMAIL: KLiang@jonesedmunds.com |
| Alex Buchans | Jones Edmunds | PHONE: 352-377-5821 ext.1488<br>EMAIL: ABuchans@jonesedmunds.com |
| Marjorie Craig, PE | Village of Tequesta | PHONE: 561.768.0459<br>EMAIL: mcraig@tequesta.org |
| Thomas G. Bradford | citizen | PHONE: 561-346-6061<br>EMAIL: tgbradford3@gmail.com |
| Jenn Todd | VOT / Citizen | PHONE:<br>EMAIL: |
| | | PHONE:<br>EMAIL: |
| | | PHONE:<br>EMAIL: |
| | | Phone:<br>EMAIL: |
| | | Phone:<br>EMAIL: |

# Appendix D

# FDEP Approval To Use Vaca Key Tide Gauge Data

## Karen Liang, PE, CFM

**From:** Slyter, Krista <Krista.Slyter@FloridaDEP.gov>
**Sent:** Thursday, August 8, 2024 12:26 PM
**To:** Karen Liang, PE, CFM
**Cc:** Munoz, Terence; mcraig@tequesta.org; Brett A. Cunningham, PE, ENV SP; Field, Claire; Link, Stephanie
**Subject:** RE: Grant 22PLN75 - Approval Request for Single Tide Gauge

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Good afternoon –

Based on the below request, use of a single tide gauge is approved for 22PLN75, Village of Tequesta Vulnerability Assessment and Adaptation Plan. Please include this approval when submitting deliverables for which it is relevant, including the final vulnerability assessment.

Thank you,

*Krista*

---

**From:** Karen Liang, PE, CFM <Kliang@jonesedmunds.com>
**Sent:** Tuesday, August 6, 2024 4:17 PM
**To:** Dunbar, Tyler <Tyler.Dunbar@FloridaDEP.gov>
**Cc:** Field, Claire <Claire.Field@FloridaDEP.gov>; Munoz, Terence <Terence.Munoz@FloridaDEP.gov>; Marjorie Craig <mcraig@tequesta.org>; Brett Cunningham <bcunningham@jonesedmunds.com>
**Subject:** Grant 22PLN75 - Approval Request for Single Tide Gauge

**EXTERNAL MESSAGE**
This email originated outside of DEP. Please use caution when opening attachments, clicking links, or responding to this email.

Good afternoon Tyler,

We used the Vaca Key tide gauge for the Village of Tequesta Vulnerability Assessment (VA) study. We understand that approval from the DEP is required when only a single tide gauge is utilized. This email is to formally request DEP's approval.

The Vaca Key tide gauge (station 8723970) was selected for the study due to its proximity to the Village and its active and compliant status. During our analysis, we also considered the gauges at Virginia Key (station 8723214), Daytona Beach Shores (station 8721120), and Trident Pier (station 8721604). Although these gauges are also located along the east coast of Florida, they are either non-compliant or inactive/removed. Consequently, only data from the Vaca Key gauge was used in this study.

We appreciate your consideration and look forward to your approval.

Have a good day,

**Karen Liang, PE, CFM**
Project Engineer

# Attachment 1

# Exposure Level Results for Tidal Flooding

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Tidal Flooding | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Tidal MHHW Existing Conditions | Tidal MHHW Int-Low 2040 | Tidal MHHW Int-Low 2070 | Tidal MHHW Int-High 2040 | Tidal MHHW Int-High 2070 |
| Transportation and Evacuation Routes | Bridge | Bridges | Tequesta Bridge | Village of Tequesta | | BRD_001 | 17.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Bridge | Bridges | Beach Rd Bridge | Palm Beach County | | BRD_002 | 17.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_001 | 18.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_002 | 17.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_003 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_004 | 16.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_005 | 24.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_006 | 21.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_007 | 18.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_008 | 21.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_009 | 18.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_010 | 22.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_011 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_012 | 13.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_013 | 16.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_014 | 18.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_015 | 18.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_016 | 7.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_017 | 17.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_018 | 17.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_019 | 18.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_020 | 17.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_021 | 18.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_022 | 17.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_023 | 17.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_024 | 12.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_025 | 13.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chestnut Trl | Village of Tequesta | Local | MJRD_026 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cedar Hill Ln | Village of Tequesta | Local | MJRD_027 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_028 | 10.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Ln | Village of Tequesta | Local | MJRD_029 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Cir | Village of Tequesta | Local | MJRD_030 | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Ct | Village of Tequesta | Local | MJRD_031 | 10.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Ct | Village of Tequesta | Local | MJRD_032 | 8.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Ln | Village of Tequesta | Local | MJRD_033 | 8.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Magnolia Way | Village of Tequesta | Local | MJRD_034 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 5.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Magnolia Way | Village of Tequesta | Local | MJRD_035 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beechwood Trl | Village of Tequesta | Local | MJRD_036 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_037 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 4.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_038 | 3.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 13.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_039 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_040 | 7.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hemlock Ln | Village of Tequesta | Local | MJRD_041 | 7.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_042 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_043 | 7.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dogwood Rdg | Village of Tequesta | Local | MJRD_044 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_045 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_046 | 7.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_047 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_048 | 7.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Buttonwood Cir | Village of Tequesta | Local | MJRD_049 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 4.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_050 | 7.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_051 | 7.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_052 | 3.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 10.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_053 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Birch Pl | Village of Tequesta | Local | MJRD_054 | 9.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beechwood Trl | Village of Tequesta | Local | MJRD_055 | 6.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chestnut Trl | Village of Tequesta | Local | MJRD_056 | 7.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_057 | 8.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_058 | 6.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Tidal Flooding | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Tidal MHHW Existing Conditions | Tidal MHHW Int-Low 2040 | Tidal MHHW Int-Low 2070 | Tidal MHHW Int-High 2040 | Tidal MHHW Int-High 2070 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pinetree Cir | Village of Tequesta | Local | MJRD_059 | 6.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_060 | 7.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oak Ridge Ln | Village of Tequesta | Local | MJRD_061 | 7.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bay Tree Ln | Village of Tequesta | Local | MJRD_062 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oak Ridge Ln | Village of Tequesta | Local | MJRD_063 | 8.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Cypress Dr | Village of Tequesta | Local | MJRD_064 | 10.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_065 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_066 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Cypress Dr | Village of Tequesta | Local | MJRD_067 | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Poplar Rd | Village of Tequesta | Local | MJRD_068 | 8.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_069 | 9.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Woodland Dr | Village of Tequesta | Local | MJRD_070 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_071 | 9.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_072 | 9.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Acorn Cir | Village of Tequesta | Local | MJRD_073 | 11.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Teakwood Cir | Village of Tequesta | Local | MJRD_074 | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_075 | 9.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_076 | 16.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oakleaf Ct | Village of Tequesta | Local | MJRD_077 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Laurel Oaks Cir | Village of Tequesta | Local | MJRD_078 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_079 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oakland Ct | Village of Tequesta | Local | MJRD_080 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_081 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Live Oak Cir | Village of Tequesta | Local | MJRD_082 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_083 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tall Oaks Cir | Village of Tequesta | Local | MJRD_084 | 18.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Live Oak Cir | Village of Tequesta | Local | MJRD_085 | 19.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Live Oak Cir | Village of Tequesta | Local | MJRD_086 | 18.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Village Blvd | Village of Tequesta | Local | MJRD_087 | 13.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Intracoastal Cir | Village of Tequesta | Local | MJRD_088 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Coconut Ln | Village of Tequesta | Local | MJRD_089 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Intracoastal Cir | Village of Tequesta | Local | MJRD_090 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Intracoastal Cir | Village of Tequesta | Local | MJRD_091 | 11.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Intracoastal Cir | Village of Tequesta | Local | MJRD_092 | 6.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Point Dr | Village of Tequesta | Local | MJRD_093 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Tree Dr | Village of Tequesta | Local | MJRD_094 | 6.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Tree Dr | Village of Tequesta | Local | MJRD_095 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_096 | -0.5 | 30.7 | 34.7 | 41.8 | 40.2 | 63.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_097 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 4.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_098 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 5.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_099 | 4.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 3.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_100 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 7.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_101 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -0.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Evergreen Ave | Village of Tequesta | Local | MJRD_102 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 5.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Evergreen Ave | Village of Tequesta | Local | MJRD_103 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 5.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_104 | 4.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 3.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_105 | 3.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 15.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Evergreen Ave | Village of Tequesta | Local | MJRD_106 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 7.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Norfolk Ave | Village of Tequesta | Local | MJRD_107 | 4.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 8.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_108 | 4.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 2.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_109 | 4.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 3.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_110 | 3.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 15.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_111 | 4.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 9.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_112 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Venus Ave | Village of Tequesta | Local | MJRD_113 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_114 | 6.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Mars Ave | Village of Tequesta | Local | MJRD_115 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Saturn Ave | Village of Tequesta | Local | MJRD_116 | 6.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Venus Ave | Village of Tequesta | Local | MJRD_117 | 6.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Franklin Rd | Village of Tequesta | Local | MJRD_118 | 3.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 17.8 |

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Tidal Flooding | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Tidal MHHW Existing Conditions | Tidal MHHW Int-Low 2040 | Tidal MHHW Int-Low 2070 | Tidal MHHW Int-High 2040 | Tidal MHHW Int-High 2070 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_119 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 7.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_120 | 4.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 9.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Saturn Ave | Village of Tequesta | Local | MJRD_121 | 8.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Church Rd | Village of Tequesta | Local | MJRD_122 | 3.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 14.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Venus Ave | Village of Tequesta | Local | MJRD_123 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Saturn Ave | Village of Tequesta | Local | MJRD_124 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_125 | 3.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 13.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Venus Ave | Village of Tequesta | Local | MJRD_126 | 8.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_127 | 8.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_128 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_129 | 9.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_130 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_131 | 7.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_132 | 4.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Holly Cir | Village of Tequesta | Local | MJRD_133 | 10.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_134 | 10.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Cypress Dr | Village of Tequesta | Local | MJRD_135 | 10.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Camelia Cir | Village of Tequesta | Local | MJRD_136 | 10.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_137 | 10.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Ridgewood Cir | Village of Tequesta | Local | MJRD_138 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Azalea Cir | Village of Tequesta | Local | MJRD_139 | 9.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_140 | 8.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Short Ave | Village of Tequesta | Local | MJRD_141 | 4.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 9.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_142 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 4.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_143 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 5.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Maple Ave | Village of Tequesta | Local | MJRD_144 | 3.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 17.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_145 | 3.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 17.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_146 | 3.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 20.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Garden St | Village of Tequesta | Local | MJRD_147 | 5.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Westwood Ave | Village of Tequesta | Local | MJRD_148 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Garden St | Village of Tequesta | Local | MJRD_149 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 4.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_150 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 5.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Elm Ave | Village of Tequesta | Local | MJRD_151 | 3.0 | Not Flooded | Not Flooded | -0.2 | Not Flooded | 21.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_152 | 3.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 16.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_153 | 2.9 | Not Flooded | Not Flooded | 1.0 | Not Flooded | 22.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oak Ave | Village of Tequesta | Local | MJRD_154 | 3.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 20.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_155 | 3.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 20.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_156 | 3.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 10.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Cir | Village of Tequesta | Local | MJRD_157 | 3.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 21.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_158 | 3.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 15.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cedar Ave | Village of Tequesta | Local | MJRD_159 | 3.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 15.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_160 | 3.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 10.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_161 | 3.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 13.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_162 | 7.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_163 | 6.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_164 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_165 | 6.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_166 | 5.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_167 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_168 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 5.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_169 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 5.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_170 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 7.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_171 | 6.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fiesta Ave | Village of Tequesta | Local | MJRD_172 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_173 | 9.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_174 | 9.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_175 | 10.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cypress Dr | Village of Tequesta | Local | MJRD_176 | 10.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cove Rd | Village of Tequesta | Local | MJRD_177 | 20.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Leigh Rd | Village of Tequesta | Local | MJRD_178 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Tidal Flooding | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Tidal MHHW Existing Conditions | Tidal MHHW Int-Low 2040 | Tidal MHHW Int-Low 2070 | Tidal MHHW Int-High 2040 | Tidal MHHW Int-High 2070 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fiesta Ave | Village of Tequesta | Local | MJRD_179 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Daly Rd | Village of Tequesta | Local | MJRD_180 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fiesta Ave | Village of Tequesta | Local | MJRD_181 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_182 | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_183 | 11.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cypress Dr | Village of Tequesta | Local | MJRD_184 | 10.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_185 | 14.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_186 | 16.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_187 | 17.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bay Harbor Rd | Village of Tequesta | Local | MJRD_188 | 2.6 | Not Flooded | Not Flooded | 4.6 | 3.0 | 26.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Point Dr | Village of Tequesta | Local | MJRD_189 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Point Dr | Village of Tequesta | Local | MJRD_190 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_191 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_192 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview W | Village of Tequesta | Local | MJRD_193 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fair Pl | Village of Tequesta | Local | MJRD_194 | 4.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview E | Village of Tequesta | Local | MJRD_195 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview E | Village of Tequesta | Local | MJRD_196 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -0.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_197 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_198 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golf Pl | Village of Tequesta | Local | MJRD_199 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_200 | 4.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 2.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bunker Pl | Village of Tequesta | Local | MJRD_201 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 4.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_202 | 4.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 2.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | R View Pl | Village of Tequesta | Local | MJRD_203 | 5.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_204 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway W | Village of Tequesta | Local | MJRD_205 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway E | Village of Tequesta | Local | MJRD_206 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_207 | 6.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_208 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway N | Village of Tequesta | Local | MJRD_209 | 6.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | North Pl | Village of Tequesta | Local | MJRD_210 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway N | Village of Tequesta | Local | MJRD_211 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway N | Village of Tequesta | Local | MJRD_212 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway N | Village of Tequesta | Local | MJRD_213 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_214 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Cir | Village of Tequesta | Local | MJRD_215 | 5.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_216 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_217 | 7.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_218 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_219 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Palmetto Way | Village of Tequesta | Local | MJRD_220 | 4.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_221 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_222 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Starboard Way | Village of Tequesta | Local | MJRD_223 | 3.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 14.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_224 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Gulfstream Dr | Village of Tequesta | Local | MJRD_225 | 3.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 13.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Leeward Cir | Village of Tequesta | Local | MJRD_226 | 3.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 14.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_227 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tradewinds Cir | Village of Tequesta | Local | MJRD_228 | 3.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 16.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_229 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Cir | Village of Tequesta | Local | MJRD_230 | 3.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 10.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_231 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_232 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golf Club Cir | Village of Tequesta | Local | MJRD_233 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_234 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Yacht Club Pl | Village of Tequesta | | MJRD_235 | 4.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 9.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_236 | 5.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | El Portal Dr | Village of Tequesta | Local | MJRD_237 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview E | Village of Tequesta | Local | MJRD_238 | 4.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 3.4 |

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Tidal Flooding | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Tidal MHHW Existing Conditions | Tidal MHHW Int-Low 2040 | Tidal MHHW Int-Low 2070 | Tidal MHHW Int-High 2040 | Tidal MHHW Int-High 2070 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Tree Pl | Village of Tequesta | Local | MJRD_239 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | El Portal Dr | Village of Tequesta | Local | MJRD_240 | 5.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_241 | 5.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | El Portal Dr | Village of Tequesta | Local | MJRD_242 | 5.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Yacht Club Pl | Village of Tequesta | Local | MJRD_243 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Yacht Club Pl | Village of Tequesta | Local | MJRD_244 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_245 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_246 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Ct | Village of Tequesta | Local | MJRD_247 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Ter | Village of Tequesta | Local | MJRD_248 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 7.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Rd | Village of Tequesta | Local | MJRD_249 | 4.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 2.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Rd | Village of Tequesta | Local | MJRD_250 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 5.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Shady Ln | Village of Tequesta | Local | MJRD_251 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 7.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Rd | Village of Tequesta | Local | MJRD_252 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 5.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Point Dr | Village of Tequesta | Local | MJRD_253 | 6.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_254 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_255 | 5.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_256 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -0.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_257 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview W | Village of Tequesta | Local | MJRD_258 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -0.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_259 | 5.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Club Pl | Village of Tequesta | Local | MJRD_260 | 5.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Magnolia Way | Village of Tequesta | Local | MJRD_261 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Coconut Ln | Village of Tequesta | Local | MJRD_262 | 20.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Shady Ln | Village of Tequesta | Local | MJRD_263 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 5.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_264 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Alley | Village of Tequesta | Local | MJRD_265 | 10.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Water Treatment Facility | Water Treatment Plants | Water Treatment Facility | Village of Tequesta | | DWF_001 | 18.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Water Ground Storage Tank | Ground Storage Tanks | Ground Storage Tank | Village of Tequesta | | DWF_008 | 15.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Water Ground Storage Tank | Ground Storage Tanks | Ground Storage Tank | Village of Tequesta | | DWF_009 | 15.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well R4 | Village of Tequesta | | DWF_002 | 19.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well R3 | Village of Tequesta | | DWF_003 | 14.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 7 | Village of Tequesta | | DWF_004 | 11.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 20 | Village of Tequesta | | DWF_005 | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 19 | Village of Tequesta | | DWF_006 | 12.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 18 | Village of Tequesta | | DWF_007 | 13.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well R4 Pump | Village of Tequesta | | DWF_010 | 19.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well R3 Pump | Village of Tequesta | | DWF_011 | 14.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 7 Pump | Village of Tequesta | | DWF_012 | 11.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 20 Pump | Village of Tequesta | | DWF_013 | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 19 Pump | Village of Tequesta | | DWF_014 | 12.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 18 Pump | Village of Tequesta | | DWF_015 | 13.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Generator | Electric Facilities | Village Hall IT Standby Generator | Village of Tequesta | | ELC_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Generator | Electric Facilities | Public Safety 300kw Standby Generator | Village of Tequesta | | ELC_002 | 12.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Generator | Electric Facilities | Rec Center 100kw LP Standby Generator | Village of Tequesta | | ELC_003 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS053 - Wetwell | Loxahatchee River District | | WWF_001 | 16.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS066 - Wetwell | Loxahatchee River District | | WWF_002 | 4.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 3.0 |
| Critical Infrastructure | Lift Station | Lift Stations | LS050 - Wetwell | Loxahatchee River District | | WWF_003 | 10.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS055 - Wetwell | Loxahatchee River District | | WWF_004 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS057 - Wetwell | Loxahatchee River District | | WWF_005 | 10.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS058 - Wetwell | Loxahatchee River District | | WWF_006 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS061 - Wetwell | Loxahatchee River District | | WWF_007 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS064 - Wetwell | Loxahatchee River District | | WWF_008 | 13.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS065 - Wetwell | Loxahatchee River District | | WWF_009 | 5.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS067 - Wetwell | Loxahatchee River District | | WWF_010 | 3.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 20.2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS069 - Wetwell | Loxahatchee River District | | WWF_011 | 11.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS070 - Wetwell | Loxahatchee River District | | WWF_012 | 6.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS071 - Wetwell | Loxahatchee River District | | WWF_013 | 7.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS072 - Wetwell | Loxahatchee River District | | WWF_014 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS075 - Wetwell | Loxahatchee River District | | WWF_015 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Tidal Flooding | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Tidal MHHW Existing Conditions | Tidal MHHW Int-Low 2040 | Tidal MHHW Int-Low 2070 | Tidal MHHW Int-High 2040 | Tidal MHHW Int-High 2070 |
| Critical Infrastructure | Lift Station | Lift Stations | LS076 - Wetwell | Loxahatchee River District | | WWF_016 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS077 - Wetwell | Loxahatchee River District | | WWF_017 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS078 - Wetwell | Loxahatchee River District | | WWF_018 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS141 - Wetwell | Loxahatchee River District | | WWF_019 | 6.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS144 - Wetwell | Loxahatchee River District | | WWF_020 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS079 - Wetwell | Loxahatchee River District | | WWF_021 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS054 - Wetwell | Loxahatchee River District | | WWF_022 | 9.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS143 - Wetwell | Loxahatchee River District | | WWF_023 | 3.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 16.7 |
| Critical Infrastructure | Lift Station | Lift Stations | LS062 - Wetwell | Loxahatchee River District | | WWF_024 | 15.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS060 - Wetwell | Loxahatchee River District | | WWF_025 | 9.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS107 - Wetwell | Loxahatchee River District | | WWF_026 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 4.3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS053 - Electrical Panel | Loxahatchee River District | | WWF_001a | 20.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS066 - Electrical Panel | Loxahatchee River District | | WWF_002a | 8.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -45.0 |
| Critical Infrastructure | Lift Station | Lift Stations | LS050 - Electrical Panel | Loxahatchee River District | | WWF_003a | 14.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS055 - Electrical Panel | Loxahatchee River District | | WWF_004a | 10.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS057 - Electrical Panel | Loxahatchee River District | | WWF_005a | 14.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS058 - Electrical Panel | Loxahatchee River District | | WWF_006a | 12.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS061 - Electrical Panel | Loxahatchee River District | | WWF_007a | 11.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS064 - Electrical Panel | Loxahatchee River District | | WWF_008a | 17.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS065 - Electrical Panel | Loxahatchee River District | | WWF_009a | 9.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS067 - Electrical Panel | Loxahatchee River District | | WWF_010a | 7.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -27.8 |
| Critical Infrastructure | Lift Station | Lift Stations | LS069 - Electrical Panel | Loxahatchee River District | | WWF_011a | 15.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS070 - Electrical Panel | Loxahatchee River District | | WWF_012a | 10.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS071 - Electrical Panel | Loxahatchee River District | | WWF_013a | 11.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS072 - Electrical Panel | Loxahatchee River District | | WWF_014a | 12.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS075 - Electrical Panel | Loxahatchee River District | | WWF_015a | 10.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS076 - Electrical Panel | Loxahatchee River District | | WWF_016a | 10.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS077 - Electrical Panel | Loxahatchee River District | | WWF_017a | 11.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS078 - Electrical Panel | Loxahatchee River District | | WWF_018a | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS141 - Electrical Panel | Loxahatchee River District | | WWF_019a | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS144 - Electrical Panel | Loxahatchee River District | | WWF_020a | 11.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS079 - Electrical Panel | Loxahatchee River District | | WWF_021a | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS054 - Electrical Panel | Loxahatchee River District | | WWF_022a | 13.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS143 - Electrical Panel | Loxahatchee River District | | WWF_023a | 7.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -31.3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS062 - Electrical Panel | Loxahatchee River District | | WWF_024a | 19.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS060 - Electrical Panel | Loxahatchee River District | | WWF_025a | 13.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS107 - Electrical Panel | Loxahatchee River District | | WWF_026a | 8.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -43.7 |
| Critical Community and Emergency Facilities | EMS | Emergency Medical Service Facilities | Tequesta EMS | Village of Tequesta | | EMF_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | EOC | Emergency Operations Centers | Emergency Operations Center | Village of Tequesta | | EOC_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Fire Station | Fire Stations | Tequesta Fire Department | Village of Tequesta | | FS_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Brookdale Tequesta | Private | | HCF_001 | 17.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Clarebridge Cottage Tequesta | Private | | HCF_002 | 18.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Terrace | Private | | HCF_003 | 23.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Urgent Care | Private | | HCF_004 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Publix Pharmacy | Private | | HCF_005 | 25.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Drugs | Private | | HCF_006 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | CVS Pharmacy | Private | | HCF_007 | 24.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Law Enforcement Facility | Law Enforcement Facilities | Tequesta Police Department | Village of Tequesta | | LEF_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Tequesta Village Hall | Village of Tequesta | | LGF_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - Warehouse and Offices | Village of Tequesta | | LGF_002 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - Clerk's Office Records | Village of Tequesta | | LGF_003 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - PD Evidence Bay | Village of Tequesta | | LGF_004 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Services Bulk Storage Fuel Tank | Village of Tequesta | | LGF_005 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Services 4000 Gallon Split Tank | Village of Tequesta | | LGF_006 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Village Hall IT Server Room | Village of Tequesta | | LGF_007 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Safety 4000g Bulk Storage Tank | Village of Tequesta | | LGF_008 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Tequesta Recreational Center | Village of Tequesta | | LGF_009 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Rec Center IT Server Room | Village of Tequesta | | LGF_010 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | School | Schools | Good Shepherd Episcopal School | Private | | SCL_001 | 9.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | School | Schools | Providence Education Group | Private | | SCL_002 | 8.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Tidal Flooding | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Tidal MHHW Existing Conditions | Tidal MHHW Int-Low 2040 | Tidal MHHW Int-Low 2070 | Tidal MHHW Int-High 2040 | Tidal MHHW Int-High 2070 |
| Critical Community and Emergency Facilities | School | Schools | Mary, Mother of the Light Academy | Private | | SCL_003 | 12.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | School | Schools | First Presbyterian Church Preschool of Tequesta | Private | | SCL_004 | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Conservation Lands | Conservation Lands | Jupiter Inlet Lighthouse Outstanding Natural Area | US DOI, BLM | | CL_001 | -1.7 | 45.1 | 49.1 | 56.2 | 54.6 | 77.8 |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical and Cultural Assets - Sites | Florida East Coast Railway | Private | | HCAS_001 | 7.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical and Cultural Assets - Sites | Old Dixie Highway | FDOT | | HCAS_002 | 11.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical and Cultural Assets - Sites | Broadway (US 1) | FDOT | | HCAS_003 | 12.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Parks | Parks | Constitution Park | Village of Tequesta | | PRK_001 | 3.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 11.8 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Paradise Park | Village of Tequesta | | PRK_002 | 16.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Parks | Parks | Coral Cove Park | Palm Beach County | | PRK_003 | -1.7 | 45.1 | 49.1 | 56.2 | 54.6 | 77.8 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Tequesta Park | FDEP | | PRK_004 | 9.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Palm Beach County | | SHL_001 | 0.6 | 17.5 | 21.5 | 28.6 | 27.0 | 50.2 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Palm Beach County | | SHL_002 | -1.0 | 36.7 | 40.7 | 47.8 | 46.2 | 69.4 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_003 | -3.0 | 60.7 | 64.7 | 71.8 | 70.2 | 93.4 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_004 | -1.7 | 45.1 | 49.1 | 56.2 | 54.6 | 77.8 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | US DOI, BLM | | SHL_005 | -1.7 | 45.1 | 49.1 | 56.2 | 54.6 | 77.8 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_006 | -1.7 | 45.1 | 49.1 | 56.2 | 54.6 | 77.8 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_007 | -0.5 | 30.7 | 34.7 | 41.8 | 40.2 | 63.4 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_008 | -0.5 | 30.7 | 34.7 | 41.8 | 40.2 | 63.4 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_009 | -1.5 | 42.7 | 46.7 | 53.8 | 52.2 | 75.4 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_010 | -2.7 | 57.1 | 61.1 | 68.2 | 66.6 | 89.8 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_001 | 0.4 | 19.9 | 23.9 | 31.0 | 29.4 | 52.6 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_002 | 0.8 | 15.1 | 19.1 | 26.2 | 24.6 | 47.8 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_003 | 3.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 17.8 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_004 | -1.7 | 45.1 | 49.1 | 56.2 | 54.6 | 77.8 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_005 | 0.5 | 18.7 | 22.7 | 29.8 | 28.2 | 51.4 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_006 | 0.6 | 17.5 | 21.5 | 28.6 | 27.0 | 50.2 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_007 | 0.3 | 21.1 | 25.1 | 32.2 | 30.6 | 53.8 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_008 | 0.5 | 18.7 | 22.7 | 29.8 | 28.2 | 51.4 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_009 | 0.5 | 18.7 | 22.7 | 29.8 | 28.2 | 51.4 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Village of Tequesta | | SFW_010 | 11.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_011 | 1.0 | 12.7 | 16.7 | 23.8 | 22.2 | 45.4 |
| Natural, Cultural, and Historical Resources | Wetland | Wetlands | Wetland | Palm Beach County | | WLD_001 | -1.7 | 45.1 | 49.1 | 56.2 | 54.6 | 77.8 |
| Natural, Cultural, and Historical Resources | Wetland | Wetlands | Wetland | Private | | WLD_002 | -1.7 | 45.1 | 49.1 | 56.2 | 54.6 | 77.8 |

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - FLOOD RISK LEVEL

| Tequesta Critical Assets | | | | | | | | Flood Risk Level | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | Tidal Flooding | | | | | | |
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Tidal MHHW Existing Conditions | Tidal MHHW Int-Low 2040 | Tidal MHHW Int-Low 2070 | Tidal MHHW Int-High 2040 | Tidal MHHW Int-High 2070 | Final Priority Ranking | Focus Area |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 20 | Village of Tequesta | | DWF_005 | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 1 |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 19 | Village of Tequesta | | DWF_006 | 12.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 1 |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 18 | Village of Tequesta | | DWF_007 | 13.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 1 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 19 Pump | Village of Tequesta | | DWF_014 | 12.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 1 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 18 Pump | Village of Tequesta | | DWF_015 | 13.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 1 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 20 Pump | Village of Tequesta | | DWF_013 | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS107 - Wetwell | Loxahatchee River District | | WWF_026 | 4.4 | High | High | High | High | High | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS141 - Wetwell | Loxahatchee River District | | WWF_019 | 6.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS066 - Electrical Panel | Loxahatchee River District | | WWF_002a | 8.5 | High | High | High | High | High | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS067 - Electrical Panel | Loxahatchee River District | | WWF_010a | 7.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS141 - Electrical Panel | Loxahatchee River District | | WWF_019a | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS060 - Wetwell | Loxahatchee River District | | WWF_025 | 9.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS069 - Electrical Panel | Loxahatchee River District | | WWF_011a | 15.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS060 - Electrical Panel | Loxahatchee River District | | WWF_025a | 13.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS067 - Wetwell | Loxahatchee River District | | WWF_010 | 3.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS066 - Wetwell | Loxahatchee River District | | WWF_002 | 4.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS061 - Wetwell | Loxahatchee River District | | WWF_007 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS069 - Wetwell | Loxahatchee River District | | WWF_011 | 11.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS107 - Electrical Panel | Loxahatchee River District | | WWF_026a | 8.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | 1 |
| Natural, Cultural, and Historical Resources | Conservation Lands | Conservation Lands | Jupiter Inlet Lighthouse Outstanding Natural Area | US DOI, BLM | | CL_001 | -1.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Coral Cove Park | Palm Beach County | | PRK_003 | -1.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 1 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Tequesta Park | FDEP | | PRK_004 | 9.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 1 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Palm Beach County | | SHL_001 | 0.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 1 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Palm Beach County | | SHL_002 | -1.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 1 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_003 | -3.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_004 | -1.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | US DOI, BLM | | SHL_005 | -1.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_006 | -1.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_004 | -1.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Natural, Cultural, and Historical Resources | Wetland | Wetlands | Wetland | Palm Beach County | | WLD_001 | -1.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Natural, Cultural, and Historical Resources | Wetland | Wetlands | Wetland | Private | | WLD_002 | -1.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Transportation and Evacuation Routes | Bridge | Bridges | Beach Rd Bridge | Palm Beach County | | BRD_002 | 17.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_011 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 1 |
| Transportation and Evacuation Routes | Major Roadway | Local | Coconut Ln | Village of Tequesta | Local | MJRD_089 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Transportation and Evacuation Routes | Major Roadway | Local | Coconut Ln | Village of Tequesta | Local | MJRD_262 | 20.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Transportation and Evacuation Routes | Major Roadway | Local | Intracoastal Cir | Village of Tequesta | Local | MJRD_090 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Transportation and Evacuation Routes | Major Roadway | Local | Intracoastal Cir | Village of Tequesta | Local | MJRD_091 | 11.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 1 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_016 | 7.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 1 |
| Transportation and Evacuation Routes | Major Roadway | Local | Intracoastal Cir | Village of Tequesta | Local | MJRD_092 | 6.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 1 |
| Critical Community and Emergency Facilities | EMS | Emergency Medical Service Facilities | Tequesta EMS | Village of Tequesta | | EMF_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Community and Emergency Facilities | EOC | Emergency Operation Centers | Emergency Operations Center | Village of Tequesta | | EOC_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Community and Emergency Facilities | Fire Station | Fire Stations | Tequesta Fire Department | Village of Tequesta | | FS_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Brookdale Tequesta | Private | | HCF_001 | 17.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Clarebridge Cottage Tequesta | Private | | HCF_002 | 18.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Terrace | Private | | HCF_003 | 23.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Publix Pharmacy | Private | | HCF_005 | 25.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Urgent Care | Private | | HCF_004 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Drugs | Private | | HCF_006 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | CVS Pharmacy | Private | | HCF_007 | 24.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Community and Emergency Facilities | Law Enforcement Facility | Law Enforcement Facilities | Tequesta Police Department | Village of Tequesta | | LEF_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Tequesta Village Hall | Village of Tequesta | | LGF_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Village Hall IT Server Room | Village of Tequesta | | LGF_007 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Safety 4000g Bulk Storage Tank | Village of Tequesta | | LGF_008 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Tequesta Recreational Center | Village of Tequesta | | LGF_009 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Rec Center IT Server Room | Village of Tequesta | | LGF_010 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - Warehouse and Offices | Village of Tequesta | | LGF_002 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - Clerk's Office Records | Village of Tequesta | | LGF_003 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - PD Evidence Bay | Village of Tequesta | | LGF_004 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Services Bulk Storage Fuel Tank | Village of Tequesta | | LGF_005 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Services 4000 Gallon Split Tank | Village of Tequesta | | LGF_006 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Community and Emergency Facilities | School | Schools | Good Shepherd Episcopal School | Private | | SCL_001 | 9.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Critical Community and Emergency Facilities | School | Schools | Providence Education Group | Private | | SCL_002 | 8.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Critical Community and Emergency Facilities | School | Schools | Mary, Mother of the Light Academy | Private | | SCL_003 | 12.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well R4 | Village of Tequesta | | DWF_002 | 19.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well R3 | Village of Tequesta | | DWF_003 | 14.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 7 | Village of Tequesta | | DWF_004 | 11.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 7 Pump | Village of Tequesta | | DWF_012 | 11.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - FLOOD RISK LEVEL

| Tequesta Critical Assets | | | | | | | | Flood Risk Level | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | Tidal Flooding | | | | | | |
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Tidal MHHW Existing Conditions | Tidal MHHW Int-Low 2040 | Tidal MHHW Int-Low 2070 | Tidal MHHW Int-High 2040 | Tidal MHHW Int-High 2070 | Final Priority Ranking | Focus Area |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well R4 Pump | Village of Tequesta | | DWF_010 | 19.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well R3 Pump | Village of Tequesta | | DWF_011 | 14.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Infrastructure | Generator | Electric Facilities | Rec Center 100kw LP Standby Generator | Village of Tequesta | | ELC_003 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | 2 |
| Critical Infrastructure | Generator | Electric Facilities | Public Safety 300kw Standby Generator | Village of Tequesta | | ELC_002 | 12.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | 2 |
| Critical Infrastructure | Generator | Electric Facilities | Village Hall IT Standby Generator | Village of Tequesta | | ELC_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS143 - Wetwell | Loxahatchee River District | | WWF_023 | 3.4 | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS054 - Wetwell | Loxahatchee River District | | WWF_022 | 9.6 | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS055 - Electrical Panel | Loxahatchee River District | | WWF_004a | 10.2 | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS058 - Electrical Panel | Loxahatchee River District | | WWF_006a | 12.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS061 - Electrical Panel | Loxahatchee River District | | WWF_007a | 11.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS064 - Electrical Panel | Loxahatchee River District | | WWF_008a | 17.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS065 - Electrical Panel | Loxahatchee River District | | WWF_009a | 9.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS079 - Electrical Panel | Loxahatchee River District | | WWF_021a | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS054 - Electrical Panel | Loxahatchee River District | | WWF_022a | 13.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS079 - Wetwell | Loxahatchee River District | | WWF_021 | 5.0 | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS144 - Wetwell | Loxahatchee River District | | WWF_020 | 7.3 | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS062 - Wetwell | Loxahatchee River District | | WWF_024 | 15.8 | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS053 - Electrical Panel | Loxahatchee River District | | WWF_001a | 20.1 | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS050 - Electrical Panel | Loxahatchee River District | | WWF_003a | 14.0 | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS057 - Electrical Panel | Loxahatchee River District | | WWF_005a | 14.5 | Not Flooded | Not Flooded | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS144 - Electrical Panel | Loxahatchee River District | | WWF_020a | 11.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS062 - Electrical Panel | Loxahatchee River District | | WWF_024a | 19.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS065 - Wetwell | Loxahatchee River District | | WWF_009 | 5.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS058 - Wetwell | Loxahatchee River District | | WWF_006 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS064 - Wetwell | Loxahatchee River District | | WWF_008 | 13.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS143 - Electrical Panel | Loxahatchee River District | | WWF_023a | 7.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS057 - Wetwell | Loxahatchee River District | | WWF_005 | 10.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS053 - Wetwell | Loxahatchee River District | | WWF_001 | 16.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS050 - Wetwell | Loxahatchee River District | | WWF_003 | 10.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS055 - Wetwell | Loxahatchee River District | | WWF_004 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Critical Infrastructure | Water Ground Storage Tank | Ground Storage Tanks | Ground Storage Tank | Village of Tequesta | | DWF_009 | 15.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Critical Infrastructure | Water Ground Storage Tank | Ground Storage Tanks | Ground Storage Tank | Village of Tequesta | | DWF_008 | 15.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Infrastructure | Water Treatment Facility | Water Treatment Plants | Water Treatment Facility | Village of Tequesta | | DWF_001 | 18.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical Cultural Assets - Sites | Florida East Coast Railway | Private | | HCAS_001 | 7.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical Cultural Assets - Sites | Old Dixie Highway | FDOT | | HCAS_002 | 11.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical Cultural Assets - Sites | Broadway (US 1) | FDOT | | HCAS_003 | 12.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Medium | 2 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Constitution Park | Village of Tequesta | | PRK_001 | 3.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 2 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Paradise Park | Village of Tequesta | | PRK_002 | 16.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 2 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_007 | -0.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_009 | 0.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Village of Tequesta | | SFW_010 | 11.2 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Bridge | Bridges | Tequesta Bridge | Village of Tequesta | | BRD_001 | 17.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_097 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Dover Rd | Village of Tequesta | Local | MJRD_098 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_099 | 4.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_100 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Evergreen Ave | Village of Tequesta | Local | MJRD_102 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Evergreen Ave | Village of Tequesta | Local | MJRD_103 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_104 | 4.5 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beacon St | Village of Tequesta | Local | MJRD_105 | 3.5 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Evergreen Ave | Village of Tequesta | Local | MJRD_106 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Norfolk Ave | Village of Tequesta | Local | MJRD_107 | 4.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Dover Rd | Village of Tequesta | Local | MJRD_108 | 4.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_109 | 4.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_110 | 3.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Seabrook Rd | Village of Tequesta | Local | MJRD_111 | 4.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Franklin Rd | Village of Tequesta | Local | MJRD_118 | 3.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Seabrook Rd | Village of Tequesta | Local | MJRD_119 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Seabrook Rd | Village of Tequesta | Local | MJRD_120 | 4.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Church Rd | Village of Tequesta | Local | MJRD_122 | 3.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beacon St | Village of Tequesta | Local | MJRD_125 | 3.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_132 | 4.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_007 | 18.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Cedar Hill Ln | Village of Tequesta | Local | MJRD_027 | 7.9 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chapel Ln | Village of Tequesta | Local | MJRD_029 | 8.8 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chapel Cir | Village of Tequesta | Local | MJRD_030 | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chapel Ct | Village of Tequesta | Local | MJRD_031 | 10.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - FLOOD RISK LEVEL

| Tequesta Critical Assets | | | | | | | | Flood Risk Level | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | Tidal Flooding | | | | | | |
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Tidal MHHW Existing Conditions | Tidal MHHW Int-Low 2040 | Tidal MHHW Int-Low 2070 | Tidal MHHW Int-High 2040 | Tidal MHHW Int-High 2070 | Final Priority Ranking | Focus Area |
| Transportation and Evacuation Routes | Major Roadway | Local | Chapel Ct | Village of Tequesta | Local | MJRD_032 | 8.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chapel Ln | Village of Tequesta | Local | MJRD_033 | 8.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Magnolia Way | Village of Tequesta | Local | MJRD_035 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beechwood Trl | Village of Tequesta | Local | MJRD_036 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_037 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Oak Ridge Ln | Village of Tequesta | Local | MJRD_063 | 8.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pineview Rd | Village of Tequesta | Local | MJRD_112 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pineview Rd | Village of Tequesta | Local | MJRD_114 | 6.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Venus Ave | Village of Tequesta | Local | MJRD_117 | 6.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Venus Ave | Village of Tequesta | Local | MJRD_126 | 8.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Willow Rd | Village of Tequesta | Local | MJRD_127 | 8.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_128 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_129 | 9.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_130 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_131 | 7.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Holly Cir | Village of Tequesta | Local | MJRD_133 | 10.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Willow Rd | Village of Tequesta | Local | MJRD_134 | 10.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Cypress Dr | Village of Tequesta | Local | MJRD_135 | 10.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Camelia Cir | Village of Tequesta | Local | MJRD_136 | 10.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Willow Rd | Village of Tequesta | Local | MJRD_137 | 10.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Magnolia Way | Village of Tequesta | Local | MJRD_034 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Dover Rd | Village of Tequesta | Local | MJRD_101 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Venus Ave | Village of Tequesta | Local | MJRD_113 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Mars Ave | Village of Tequesta | Local | MJRD_115 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Saturn Ave | Village of Tequesta | Local | MJRD_121 | 8.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Saturn Ave | Village of Tequesta | Local | MJRD_124 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Ridgewood Cir | Village of Tequesta | Local | MJRD_138 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Venus Ave | Village of Tequesta | Local | MJRD_123 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Short Ave | Village of Tequesta | Local | MJRD_141 | 4.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Dover Rd | Village of Tequesta | Local | MJRD_142 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_143 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Maple Ave | Village of Tequesta | Local | MJRD_144 | 3.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beacon St | Village of Tequesta | Local | MJRD_145 | 3.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_146 | 3.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Garden St | Village of Tequesta | Local | MJRD_149 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Dover Rd | Village of Tequesta | Local | MJRD_150 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Elm Ave | Village of Tequesta | Local | MJRD_151 | 3.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beacon St | Village of Tequesta | Local | MJRD_152 | 3.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_153 | 2.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Oak Ave | Village of Tequesta | Local | MJRD_154 | 3.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_155 | 3.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beacon St | Village of Tequesta | Local | MJRD_156 | 3.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Cir | Village of Tequesta | Local | MJRD_157 | 3.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_158 | 3.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Cedar Ave | Village of Tequesta | Local | MJRD_159 | 3.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beacon St | Village of Tequesta | Local | MJRD_160 | 3.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_161 | 3.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_168 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Seabrook Rd | Village of Tequesta | Local | MJRD_169 | 4.3 | Not Flooded | Not Flooded | Flooding Outside Cı | Not Flooded | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Seabrook Rd | Village of Tequesta | Local | MJRD_170 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_001 | 18.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_002 | 17.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_003 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_004 | 16.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_006 | 21.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_009 | 18.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_012 | 13.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_014 | 18.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_015 | 18.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_024 | 12.7 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_028 | 10.6 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_046 | 7.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_047 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_048 | 7.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Buttonwood Cir | Village of Tequesta | Local | MJRD_049 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_053 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Birch Pl | Village of Tequesta | Local | MJRD_054 | 9.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - FLOOD RISK LEVEL

| Tequesta Critical Assets | | | | | | | | Flood Risk Level | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | Tidal Flooding | | | | | | |
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Tidal MHHW Existing Conditions | Tidal MHHW Int-Low 2040 | Tidal MHHW Int-Low 2070 | Tidal MHHW Int-High 2040 | Tidal MHHW Int-High 2070 | Final Priority Ranking | Focus Area |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_058 | 6.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Cypress Dr | Village of Tequesta | Local | MJRD_064 | 10.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Cypress Dr | Village of Tequesta | Local | MJRD_067 | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Poplar Rd | Village of Tequesta | Local | MJRD_068 | 8.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl E | Village of Tequesta | Local | MJRD_069 | 9.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Woodland Dr | Village of Tequesta | Local | MJRD_070 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl E | Village of Tequesta | Local | MJRD_071 | 9.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl E | Village of Tequesta | Local | MJRD_072 | 9.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Teakwood Cir | Village of Tequesta | Local | MJRD_074 | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl E | Village of Tequesta | Local | MJRD_075 | 9.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_076 | 16.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Village Blvd | Village of Tequesta | Local | MJRD_087 | 13.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Intracoastal Cir | Village of Tequesta | Local | MJRD_088 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Azalea Cir | Village of Tequesta | Local | MJRD_139 | 9.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Willow Rd | Village of Tequesta | Local | MJRD_140 | 8.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_162 | 7.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_163 | 6.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_165 | 6.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pineview Rd | Village of Tequesta | Local | MJRD_171 | 6.8 | Not Flooded | Not Flooded | Low | Not Flooded | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fiesta Ave | Village of Tequesta | Local | MJRD_172 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pineview Rd | Village of Tequesta | Local | MJRD_173 | 9.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pineview Rd | Village of Tequesta | Local | MJRD_174 | 9.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Cypress Dr | Village of Tequesta | Local | MJRD_176 | 10.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fiesta Ave | Village of Tequesta | Local | MJRD_179 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fiesta Ave | Village of Tequesta | Local | MJRD_181 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Cypress Dr | Village of Tequesta | Local | MJRD_184 | 10.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_185 | 14.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_186 | 16.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_187 | 17.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Magnolia Way | Village of Tequesta | Local | MJRD_261 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Hickory Hill Rd | Village of Tequesta | Local | MJRD_045 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_050 | 7.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Hickory Hill Rd | Village of Tequesta | Local | MJRD_051 | 7.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_052 | 3.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pinetree Cir | Village of Tequesta | Local | MJRD_059 | 6.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Willow Rd | Village of Tequesta | Local | MJRD_060 | 7.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Oak Ridge Ln | Village of Tequesta | Local | MJRD_061 | 7.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bay Tree Ln | Village of Tequesta | Local | MJRD_062 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl E | Village of Tequesta | Local | MJRD_065 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl E | Village of Tequesta | Local | MJRD_066 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Garden St | Village of Tequesta | Local | MJRD_147 | 5.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Westwood Ave | Village of Tequesta | Local | MJRD_148 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_166 | 5.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Leigh Rd | Village of Tequesta | Local | MJRD_178 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_005 | 24.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_010 | 22.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_013 | 16.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_020 | 17.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_021 | 18.5 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_022 | 17.9 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Acorn Cir | Village of Tequesta | Local | MJRD_073 | 11.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pineview Rd | Village of Tequesta | Local | MJRD_175 | 10.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Cove Rd | Village of Tequesta | Local | MJRD_177 | 20.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_023 | 17.6 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_025 | 13.0 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_164 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_183 | 11.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Saturn Ave | Village of Tequesta | Local | MJRD_116 | 6.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_167 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Daly Rd | Village of Tequesta | Local | MJRD_180 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_182 | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_008 | 21.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_018 | 17.6 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_019 | 18.6 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chestnut Trl | Village of Tequesta | Local | MJRD_026 | 7.9 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_039 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Hemlock Ln | Village of Tequesta | Local | MJRD_041 | 7.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - FLOOD RISK LEVEL

| Tequesta Critical Assets | | | | | | | | Flood Risk Level | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | Tidal Flooding | | | | | | |
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Tidal MHHW Existing Conditions | Tidal MHHW Int-Low 2040 | Tidal MHHW Int-Low 2070 | Tidal MHHW Int-High 2040 | Tidal MHHW Int-High 2070 | Final Priority Ranking | Focus Area |
| Transportation and Evacuation Routes | Major Roadway | Local | Hickory Hill Rd | Village of Tequesta | Local | MJRD_043 | 7.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beechwood Trl | Village of Tequesta | Local | MJRD_055 | 6.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_057 | 8.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Oakleaf Ct | Village of Tequesta | Local | MJRD_077 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Laurel Oaks Cir | Village of Tequesta | Local | MJRD_078 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_079 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Oakland Ct | Village of Tequesta | Local | MJRD_080 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_081 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Live Oak Cir | Village of Tequesta | Local | MJRD_082 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_083 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tall Oaks Cir | Village of Tequesta | Local | MJRD_084 | 18.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Live Oak Cir | Village of Tequesta | Local | MJRD_085 | 19.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Live Oak Cir | Village of Tequesta | Local | MJRD_086 | 18.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_038 | 3.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_040 | 7.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Hickory Hill Rd | Village of Tequesta | Local | MJRD_042 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dogwood Rdg | Village of Tequesta | Local | MJRD_044 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chestnut Trl | Village of Tequesta | Local | MJRD_056 | 7.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Hickory Hill Rd | Village of Tequesta | Local | MJRD_264 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_017 | 17.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside C | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Alley | Village of Tequesta | Local | MJRD_265 | 10.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Critical Community and Emergency Facilities | School | Schools | First Presbyterian Church Preschool of Tequesta | Private | | SCL_004 | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS070 - Electrical Panel | Loxahatchee River District | | WWF_012a | 10.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS071 - Electrical Panel | Loxahatchee River District | | WWF_013a | 11.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS075 - Electrical Panel | Loxahatchee River District | | WWF_015a | 10.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS076 - Electrical Panel | Loxahatchee River District | | WWF_016a | 10.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS077 - Electrical Panel | Loxahatchee River District | | WWF_017a | 11.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS072 - Electrical Panel | Loxahatchee River District | | WWF_014a | 12.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS070 - Wetwell | Loxahatchee River District | | WWF_012 | 6.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS071 - Wetwell | Loxahatchee River District | | WWF_013 | 7.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS075 - Wetwell | Loxahatchee River District | | WWF_015 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS078 - Electrical Panel | Loxahatchee River District | | WWF_018a | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS072 - Wetwell | Loxahatchee River District | | WWF_014 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS076 - Wetwell | Loxahatchee River District | | WWF_016 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS077 - Wetwell | Loxahatchee River District | | WWF_017 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS078 - Wetwell | Loxahatchee River District | | WWF_018 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_008 | -0.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_009 | -1.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_010 | -2.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_001 | 0.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_002 | 0.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_003 | 3.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_005 | 0.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_006 | 0.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_007 | 0.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_008 | 0.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside C | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_011 | 1.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bay Harbor Rd | Village of Tequesta | Local | MJRD_188 | 2.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fair Pl | Village of Tequesta | Local | MJRD_194 | 4.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairview E | Village of Tequesta | Local | MJRD_196 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_200 | 4.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bunker Pl | Village of Tequesta | Local | MJRD_201 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_202 | 4.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Palmetto Way | Village of Tequesta | Local | MJRD_220 | 4.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Starboard Way | Village of Tequesta | Local | MJRD_223 | 3.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Gulfstream Dr | Village of Tequesta | Local | MJRD_225 | 3.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Leeward Cir | Village of Tequesta | Local | MJRD_226 | 3.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tradewinds Cir | Village of Tequesta | Local | MJRD_228 | 3.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Country Club Cir | Village of Tequesta | Local | MJRD_230 | 3.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Yacht Club Pl | Village of Tequesta | | MJRD_235 | 4.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairview W | Village of Tequesta | Local | MJRD_258 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Point Dr | Village of Tequesta | Local | MJRD_189 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Point Dr | Village of Tequesta | Local | MJRD_190 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golf Pl | Village of Tequesta | Local | MJRD_199 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairway N | Village of Tequesta | Local | MJRD_209 | 6.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | North Pl | Village of Tequesta | Local | MJRD_210 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tequesta Cir | Village of Tequesta | Local | MJRD_215 | 5.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - FLOOD RISK LEVEL

| Tequesta Critical Assets | | | | | | | | Flood Risk Level | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | Tidal Flooding | | | | | | |
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Tidal MHHW Existing Conditions | Tidal MHHW Int-Low 2040 | Tidal MHHW Int-Low 2070 | Tidal MHHW Int-High 2040 | Tidal MHHW Int-High 2070 | Final Priority Ranking | Focus Area |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_217 | 7.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_224 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_231 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_232 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Point Dr | Village of Tequesta | Local | MJRD_253 | 6.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Club Pl | Village of Tequesta | Local | MJRD_260 | 5.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_191 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_192 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairview W | Village of Tequesta | Local | MJRD_193 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairview E | Village of Tequesta | Local | MJRD_195 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_197 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_198 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | R View Pl | Village of Tequesta | Local | MJRD_203 | 5.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_204 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairway W | Village of Tequesta | Local | MJRD_205 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairway E | Village of Tequesta | Local | MJRD_206 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_207 | 6.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_208 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairway N | Village of Tequesta | Local | MJRD_211 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairway N | Village of Tequesta | Local | MJRD_212 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairway N | Village of Tequesta | Local | MJRD_213 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_214 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_216 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_218 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_219 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_221 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_222 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_227 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_229 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_254 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairview E | Village of Tequesta | Local | MJRD_238 | 4.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bayview Ter | Village of Tequesta | Local | MJRD_248 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bayview Rd | Village of Tequesta | Local | MJRD_250 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Shady Ln | Village of Tequesta | Local | MJRD_251 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bayview Rd | Village of Tequesta | Local | MJRD_252 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_256 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Shady Ln | Village of Tequesta | Local | MJRD_263 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | El Portal Dr | Village of Tequesta | Local | MJRD_242 | 5.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_255 | 5.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_259 | 5.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golf Club Cir | Village of Tequesta | Local | MJRD_233 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_234 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_236 | 5.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | El Portal Dr | Village of Tequesta | Local | MJRD_237 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Tree Pl | Village of Tequesta | Local | MJRD_239 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | El Portal Dr | Village of Tequesta | Local | MJRD_240 | 5.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_241 | 5.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Yacht Club Pl | Village of Tequesta | Local | MJRD_243 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Yacht Club Pl | Village of Tequesta | Local | MJRD_244 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_245 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_246 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bayview Ct | Village of Tequesta | Local | MJRD_247 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bayview Rd | Village of Tequesta | Local | MJRD_249 | 4.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_257 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_096 | -0.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Point Dr | Village of Tequesta | Local | MJRD_093 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Tree Dr | Village of Tequesta | Local | MJRD_094 | 6.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Tree Dr | Village of Tequesta | Local | MJRD_095 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - DAYS FLOODED ANNUALLY

| Tequesta Critical Assets | | | | | | | | Flood Frequency (Days Flooded Annually) | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | High Tide Flooding | | | | |
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | High Tide Existing Conditions | High Tide Int-Low 2040 | High Tide Int-Low 2070 | High Tide Int-High 2040 | High Tide Int-High 2070 |
| Transportation and Evacuation Routes | Bridge | Bridges | Tequesta Bridge | Village of Tequesta | | BRD_001 | 17.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Bridge | Bridges | Beach Rd Bridge | Palm Beach County | | BRD_002 | 17.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_001 | 18.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_002 | 17.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_003 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_004 | 16.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_005 | 24.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_006 | 21.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_007 | 18.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_008 | 21.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_009 | 18.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_010 | 22.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_011 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_012 | 13.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_013 | 16.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_014 | 18.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_015 | 18.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_016 | 7.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_017 | 17.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_018 | 17.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_019 | 18.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_020 | 17.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_021 | 18.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_022 | 17.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_023 | 17.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_024 | 12.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_025 | 13.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chestnut Trl | Village of Tequesta | Local | MJRD_026 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cedar Hill Ln | Village of Tequesta | Local | MJRD_027 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_028 | 10.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Ln | Village of Tequesta | Local | MJRD_029 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Cir | Village of Tequesta | Local | MJRD_030 | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Ct | Village of Tequesta | Local | MJRD_031 | 10.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Ct | Village of Tequesta | Local | MJRD_032 | 8.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Ln | Village of Tequesta | Local | MJRD_033 | 8.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Magnolia Way | Village of Tequesta | Local | MJRD_034 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Magnolia Way | Village of Tequesta | Local | MJRD_035 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beechwood Trl | Village of Tequesta | Local | MJRD_036 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_037 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_038 | 3.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 19 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_039 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_040 | 7.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hemlock Ln | Village of Tequesta | Local | MJRD_041 | 7.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_042 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_043 | 7.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dogwood Rdg | Village of Tequesta | Local | MJRD_044 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_045 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_046 | 7.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_047 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_048 | 7.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Buttonwood Cir | Village of Tequesta | Local | MJRD_049 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_050 | 7.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_051 | 7.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_052 | 3.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_053 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Birch Pl | Village of Tequesta | Local | MJRD_054 | 9.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beechwood Trl | Village of Tequesta | Local | MJRD_055 | 6.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chestnut Trl | Village of Tequesta | Local | MJRD_056 | 7.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_057 | 8.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_058 | 6.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pinetree Cir | Village of Tequesta | Local | MJRD_059 | 6.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - DAYS FLOODED ANNUALLY

| Tequesta Critical Assets | | | | | | | | Flood Frequency (Days Flooded Annually) | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | High Tide Flooding | | | | |
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | High Tide Existing Conditions | High Tide Int-Low 2040 | High Tide Int-Low 2070 | High Tide Int-High 2040 | High Tide Int-High 2070 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_060 | 7.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oak Ridge Ln | Village of Tequesta | Local | MJRD_061 | 7.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bay Tree Ln | Village of Tequesta | Local | MJRD_062 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oak Ridge Ln | Village of Tequesta | Local | MJRD_063 | 8.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Cypress Dr | Village of Tequesta | Local | MJRD_064 | 10.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_065 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_066 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Cypress Dr | Village of Tequesta | Local | MJRD_067 | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Poplar Rd | Village of Tequesta | Local | MJRD_068 | 8.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_069 | 9.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Woodland Dr | Village of Tequesta | Local | MJRD_070 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_071 | 9.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_072 | 9.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Acorn Cir | Village of Tequesta | Local | MJRD_073 | 11.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Teakwood Cir | Village of Tequesta | Local | MJRD_074 | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_075 | 9.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_076 | 16.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oakleaf Ct | Village of Tequesta | Local | MJRD_077 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Laurel Oaks Cir | Village of Tequesta | Local | MJRD_078 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_079 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oakland Ct | Village of Tequesta | Local | MJRD_080 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_081 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Live Oak Cir | Village of Tequesta | Local | MJRD_082 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_083 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tall Oaks Cir | Village of Tequesta | Local | MJRD_084 | 18.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Live Oak Cir | Village of Tequesta | Local | MJRD_085 | 19.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Live Oak Cir | Village of Tequesta | Local | MJRD_086 | 18.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Village Blvd | Village of Tequesta | Local | MJRD_087 | 13.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Intracoastal Cir | Village of Tequesta | Local | MJRD_088 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Coconut Ln | Village of Tequesta | Local | MJRD_089 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Intracoastal Cir | Village of Tequesta | Local | MJRD_090 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Intracoastal Cir | Village of Tequesta | Local | MJRD_091 | 11.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Intracoastal Cir | Village of Tequesta | Local | MJRD_092 | 6.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Point Dr | Village of Tequesta | Local | MJRD_093 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Tree Dr | Village of Tequesta | Local | MJRD_094 | 6.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Tree Dr | Village of Tequesta | Local | MJRD_095 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_096 | -0.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_097 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_098 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_099 | 4.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_100 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_101 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Evergreen Ave | Village of Tequesta | Local | MJRD_102 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Evergreen Ave | Village of Tequesta | Local | MJRD_103 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_104 | 4.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_105 | 3.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 54 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Evergreen Ave | Village of Tequesta | Local | MJRD_106 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Norfolk Ave | Village of Tequesta | Local | MJRD_107 | 4.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_108 | 4.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_109 | 4.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_110 | 3.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 54 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_111 | 4.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_112 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Venus Ave | Village of Tequesta | Local | MJRD_113 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_114 | 6.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Mars Ave | Village of Tequesta | Local | MJRD_115 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Saturn Ave | Village of Tequesta | Local | MJRD_116 | 6.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Venus Ave | Village of Tequesta | Local | MJRD_117 | 6.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Franklin Rd | Village of Tequesta | Local | MJRD_118 | 3.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 110 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_119 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_120 | 4.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 4 |

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - DAYS FLOODED ANNUALLY

| Tequesta Critical Assets | | | | | | | | Flood Frequency (Days Flooded Annually) | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | High Tide Flooding | | | | |
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | High Tide Existing Conditions | High Tide Int-Low 2040 | High Tide Int-Low 2070 | High Tide Int-High 2040 | High Tide Int-High 2070 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Saturn Ave | Village of Tequesta | Local | MJRD_121 | 8.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Church Rd | Village of Tequesta | Local | MJRD_122 | 3.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 30 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Venus Ave | Village of Tequesta | Local | MJRD_123 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Saturn Ave | Village of Tequesta | Local | MJRD_124 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_125 | 3.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 19 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Venus Ave | Village of Tequesta | Local | MJRD_126 | 8.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_127 | 8.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_128 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_129 | 9.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_130 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_131 | 7.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_132 | 4.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Holly Cir | Village of Tequesta | Local | MJRD_133 | 10.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_134 | 10.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Cypress Dr | Village of Tequesta | Local | MJRD_135 | 10.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Camelia Cir | Village of Tequesta | Local | MJRD_136 | 10.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_137 | 10.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Ridgewood Cir | Village of Tequesta | Local | MJRD_138 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Azalea Cir | Village of Tequesta | Local | MJRD_139 | 9.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_140 | 8.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Short Ave | Village of Tequesta | Local | MJRD_141 | 4.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_142 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_143 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Maple Ave | Village of Tequesta | Local | MJRD_144 | 3.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 110 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_145 | 3.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 110 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_146 | 3.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 163 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Garden St | Village of Tequesta | Local | MJRD_147 | 5.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Westwood Ave | Village of Tequesta | Local | MJRD_148 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Garden St | Village of Tequesta | Local | MJRD_149 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_150 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Elm Ave | Village of Tequesta | Local | MJRD_151 | 3.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 205 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_152 | 3.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 79 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_153 | 2.9 | Not Flooded | Not Flooded | Not Flooded | 1 | 241 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oak Ave | Village of Tequesta | Local | MJRD_154 | 3.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 138 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_155 | 3.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 163 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_156 | 3.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Cir | Village of Tequesta | Local | MJRD_157 | 3.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 205 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_158 | 3.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 54 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cedar Ave | Village of Tequesta | Local | MJRD_159 | 3.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 54 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_160 | 3.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_161 | 3.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 19 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_162 | 7.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_163 | 6.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_164 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_165 | 6.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_166 | 5.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_167 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_168 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_169 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_170 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_171 | 6.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fiesta Ave | Village of Tequesta | Local | MJRD_172 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_173 | 9.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_174 | 9.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_175 | 10.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cypress Dr | Village of Tequesta | Local | MJRD_176 | 10.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cove Rd | Village of Tequesta | Local | MJRD_177 | 20.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Leigh Rd | Village of Tequesta | Local | MJRD_178 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fiesta Ave | Village of Tequesta | Local | MJRD_179 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Daly Rd | Village of Tequesta | Local | MJRD_180 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fiesta Ave | Village of Tequesta | Local | MJRD_181 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - DAYS FLOODED ANNUALLY

| Tequesta Critical Assets | | | | | | | | Flood Frequency (Days Flooded Annually) | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | High Tide Flooding | | | | |
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | High Tide Existing Conditions | High Tide Int-Low 2040 | High Tide Int-Low 2070 | High Tide Int-High 2040 | High Tide Int-High 2070 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_182 | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_183 | 11.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cypress Dr | Village of Tequesta | Local | MJRD_184 | 10.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_185 | 14.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_186 | 16.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_187 | 17.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bay Harbor Rd | Village of Tequesta | Local | MJRD_188 | 2.6 | Not Flooded | Not Flooded | 1 | 1 | 342 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Point Dr | Village of Tequesta | Local | MJRD_189 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Point Dr | Village of Tequesta | Local | MJRD_190 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_191 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_192 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview W | Village of Tequesta | Local | MJRD_193 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fair Pl | Village of Tequesta | Local | MJRD_194 | 4.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview E | Village of Tequesta | Local | MJRD_195 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview E | Village of Tequesta | Local | MJRD_196 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_197 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_198 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golf Pl | Village of Tequesta | Local | MJRD_199 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_200 | 4.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bunker Pl | Village of Tequesta | Local | MJRD_201 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_202 | 4.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | R View Pl | Village of Tequesta | Local | MJRD_203 | 5.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_204 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway W | Village of Tequesta | Local | MJRD_205 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway E | Village of Tequesta | Local | MJRD_206 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_207 | 6.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_208 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway N | Village of Tequesta | Local | MJRD_209 | 6.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | North Pl | Village of Tequesta | Local | MJRD_210 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway N | Village of Tequesta | Local | MJRD_211 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway N | Village of Tequesta | Local | MJRD_212 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway N | Village of Tequesta | Local | MJRD_213 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_214 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Cir | Village of Tequesta | Local | MJRD_215 | 5.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_216 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_217 | 7.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_218 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_219 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Palmetto Way | Village of Tequesta | Local | MJRD_220 | 4.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_221 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_222 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Starboard Way | Village of Tequesta | Local | MJRD_223 | 3.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 30 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_224 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Gulfstream Dr | Village of Tequesta | Local | MJRD_225 | 3.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 19 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Leeward Cir | Village of Tequesta | Local | MJRD_226 | 3.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 30 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_227 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tradewinds Cir | Village of Tequesta | Local | MJRD_228 | 3.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 79 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_229 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Cir | Village of Tequesta | Local | MJRD_230 | 3.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_231 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_232 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golf Club Cir | Village of Tequesta | Local | MJRD_233 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_234 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Yacht Club Pl | Village of Tequesta | | MJRD_235 | 4.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_236 | 5.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | El Portal Dr | Village of Tequesta | Local | MJRD_237 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview E | Village of Tequesta | Local | MJRD_238 | 4.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Tree Pl | Village of Tequesta | Local | MJRD_239 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | El Portal Dr | Village of Tequesta | Local | MJRD_240 | 5.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_241 | 5.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | El Portal Dr | Village of Tequesta | Local | MJRD_242 | 5.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - DAYS FLOODED ANNUALLY

| Tequesta Critical Assets | | | | | | | | Flood Frequency (Days Flooded Annually) | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | High Tide Flooding | | | | |
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | High Tide Existing Conditions | High Tide Int-Low 2040 | High Tide Int-Low 2070 | High Tide Int-High 2040 | High Tide Int-High 2070 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Yacht Club Pl | Village of Tequesta | Local | MJRD_243 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Yacht Club Pl | Village of Tequesta | Local | MJRD_244 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_245 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_246 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Ct | Village of Tequesta | Local | MJRD_247 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Ter | Village of Tequesta | Local | MJRD_248 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Rd | Village of Tequesta | Local | MJRD_249 | 4.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Rd | Village of Tequesta | Local | MJRD_250 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Shady Ln | Village of Tequesta | Local | MJRD_251 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Rd | Village of Tequesta | Local | MJRD_252 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Point Dr | Village of Tequesta | Local | MJRD_253 | 6.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_254 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_255 | 5.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_256 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_257 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview W | Village of Tequesta | Local | MJRD_258 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_259 | 5.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Club Pl | Village of Tequesta | Local | MJRD_260 | 5.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Magnolia Way | Village of Tequesta | Local | MJRD_261 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Coconut Ln | Village of Tequesta | Local | MJRD_262 | 20.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Shady Ln | Village of Tequesta | Local | MJRD_263 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_264 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Alley | Village of Tequesta | Local | MJRD_265 | 10.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Water Treatment Facility | Water Treatment Plants | Water Treatment Facility | Village of Tequesta | | DWF_001 | 18.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Water Ground Storage Tank | Ground Storage Tanks | Ground Storage Tank | Village of Tequesta | | DWF_008 | 15.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Water Ground Storage Tank | Ground Storage Tanks | Ground Storage Tank | Village of Tequesta | | DWF_009 | 15.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well R4 | Village of Tequesta | | DWF_002 | 19.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well R3 | Village of Tequesta | | DWF_003 | 14.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 7 | Village of Tequesta | | DWF_004 | 11.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 20 | Village of Tequesta | | DWF_005 | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 19 | Village of Tequesta | | DWF_006 | 12.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 18 | Village of Tequesta | | DWF_007 | 13.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well R4 Pump | Village of Tequesta | | DWF_010 | 19.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well R3 Pump | Village of Tequesta | | DWF_011 | 14.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 7 Pump | Village of Tequesta | | DWF_012 | 11.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 20 Pump | Village of Tequesta | | DWF_013 | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 19 Pump | Village of Tequesta | | DWF_014 | 12.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 18 Pump | Village of Tequesta | | DWF_015 | 13.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Generator | Electric Facilities | Village Hall IT Standby Generator | Village of Tequesta | | ELC_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Generator | Electric Facilities | Public Safety 300kw Standby Generator | Village of Tequesta | | ELC_002 | 12.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Generator | Electric Facilities | Rec Center 100kw LP Standby Generator | Village of Tequesta | | ELC_003 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS053 - Wetwell | Loxahatchee River District | | WWF_001 | 16.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS066 - Wetwell | Loxahatchee River District | | WWF_002 | 4.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS050 - Wetwell | Loxahatchee River District | | WWF_003 | 10.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS055 - Wetwell | Loxahatchee River District | | WWF_004 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS057 - Wetwell | Loxahatchee River District | | WWF_005 | 10.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS058 - Wetwell | Loxahatchee River District | | WWF_006 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS061 - Wetwell | Loxahatchee River District | | WWF_007 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS064 - Wetwell | Loxahatchee River District | | WWF_008 | 13.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS065 - Wetwell | Loxahatchee River District | | WWF_009 | 5.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS067 - Wetwell | Loxahatchee River District | | WWF_010 | 3.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 163 |
| Critical Infrastructure | Lift Station | Lift Stations | LS069 - Wetwell | Loxahatchee River District | | WWF_011 | 11.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS070 - Wetwell | Loxahatchee River District | | WWF_012 | 6.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS071 - Wetwell | Loxahatchee River District | | WWF_013 | 7.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS072 - Wetwell | Loxahatchee River District | | WWF_014 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS075 - Wetwell | Loxahatchee River District | | WWF_015 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS076 - Wetwell | Loxahatchee River District | | WWF_016 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS077 - Wetwell | Loxahatchee River District | | WWF_017 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS078 - Wetwell | Loxahatchee River District | | WWF_018 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS141 - Wetwell | Loxahatchee River District | | WWF_019 | 6.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS144 - Wetwell | Loxahatchee River District | | WWF_020 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - DAYS FLOODED ANNUALLY

| Tequesta Critical Assets | | | | | | | | Flood Frequency (Days Flooded Annually) | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | High Tide Flooding | | | | |
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | High Tide Existing Conditions | High Tide Int-Low 2040 | High Tide Int-Low 2070 | High Tide Int-High 2040 | High Tide Int-High 2070 |
| Critical Infrastructure | Lift Station | Lift Stations | LS079 - Wetwell | Loxahatchee River District | | WWF_021 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS054 - Wetwell | Loxahatchee River District | | WWF_022 | 9.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS143 - Wetwell | Loxahatchee River District | | WWF_023 | 3.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 79 |
| Critical Infrastructure | Lift Station | Lift Stations | LS062 - Wetwell | Loxahatchee River District | | WWF_024 | 15.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS060 - Wetwell | Loxahatchee River District | | WWF_025 | 9.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS107 - Wetwell | Loxahatchee River District | | WWF_026 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS053 - Electrical Panel | Loxahatchee River District | | WWF_001a | 20.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS066 - Electrical Panel | Loxahatchee River District | | WWF_002a | 8.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS050 - Electrical Panel | Loxahatchee River District | | WWF_003a | 14.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS055 - Electrical Panel | Loxahatchee River District | | WWF_004a | 10.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS057 - Electrical Panel | Loxahatchee River District | | WWF_005a | 14.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS058 - Electrical Panel | Loxahatchee River District | | WWF_006a | 12.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS061 - Electrical Panel | Loxahatchee River District | | WWF_007a | 11.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS064 - Electrical Panel | Loxahatchee River District | | WWF_008a | 17.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS065 - Electrical Panel | Loxahatchee River District | | WWF_009a | 9.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS067 - Electrical Panel | Loxahatchee River District | | WWF_010a | 7.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 163 |
| Critical Infrastructure | Lift Station | Lift Stations | LS069 - Electrical Panel | Loxahatchee River District | | WWF_011a | 15.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS070 - Electrical Panel | Loxahatchee River District | | WWF_012a | 10.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS071 - Electrical Panel | Loxahatchee River District | | WWF_013a | 11.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS072 - Electrical Panel | Loxahatchee River District | | WWF_014a | 12.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS075 - Electrical Panel | Loxahatchee River District | | WWF_015a | 10.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS076 - Electrical Panel | Loxahatchee River District | | WWF_016a | 10.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS077 - Electrical Panel | Loxahatchee River District | | WWF_017a | 11.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS078 - Electrical Panel | Loxahatchee River District | | WWF_018a | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS141 - Electrical Panel | Loxahatchee River District | | WWF_019a | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS144 - Electrical Panel | Loxahatchee River District | | WWF_020a | 11.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS079 - Electrical Panel | Loxahatchee River District | | WWF_021a | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS054 - Electrical Panel | Loxahatchee River District | | WWF_022a | 13.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS143 - Electrical Panel | Loxahatchee River District | | WWF_023a | 7.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 79 |
| Critical Infrastructure | Lift Station | Lift Stations | LS062 - Electrical Panel | Loxahatchee River District | | WWF_024a | 19.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS060 - Electrical Panel | Loxahatchee River District | | WWF_025a | 13.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS107 - Electrical Panel | Loxahatchee River District | | WWF_026a | 8.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1 |
| Critical Community and Emergency Facilities | EMS | Emergency Medical Service Facilities | Tequesta EMS | Village of Tequesta | | EMF_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | EOC | Emergency Operations Centers | Emergency Operations Center | Village of Tequesta | | EOC_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Fire Station | Fire Stations | Tequesta Fire Department | Village of Tequesta | | FS_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Brookdale Tequesta | Private | | HCF_001 | 17.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Clarebridge Cottage Tequesta | Private | | HCF_002 | 18.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Terrace | Private | | HCF_003 | 23.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Urgent Care | Private | | HCF_004 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Publix Pharmacy | Private | | HCF_005 | 25.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Drugs | Private | | HCF_006 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | CVS Pharmacy | Private | | HCF_007 | 24.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Law Enforcement Facility | Law Enforcement Facilities | Tequesta Police Department | Village of Tequesta | | LEF_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Tequesta Village Hall | Village of Tequesta | | LGF_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - Warehouse and Offices | Village of Tequesta | | LGF_002 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - Clerk's Office Records | Village of Tequesta | | LGF_003 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - PD Evidence Bay | Village of Tequesta | | LGF_004 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Services Bulk Storage Fuel Tank | Village of Tequesta | | LGF_005 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Services 4000 Gallon Split Tank | Village of Tequesta | | LGF_006 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Village Hall IT Server Room | Village of Tequesta | | LGF_007 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Safety 4000g Bulk Storage Tank | Village of Tequesta | | LGF_008 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Tequesta Recreational Center | Village of Tequesta | | LGF_009 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Rec Center IT Server Room | Village of Tequesta | | LGF_010 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | School | Schools | Good Shepherd Episcopal School | Private | | SCL_001 | 9.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | School | Schools | Providence Education Group | Private | | SCL_002 | 8.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | School | Schools | Mary, Mother of the Light Academy | Private | | SCL_003 | 12.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | School | Schools | First Presbyterian Church Preschool of Tequesta | Private | | SCL_004 | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Conservation Lands | Conservation Lands | Jupiter Inlet Lighthouse Outstanding Natural Area | US DOI, BLM | | CL_001 | -1.7 | 365 | 365 | 365 | 365 | 365 |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical and Cultural Assets - Sites | Florida East Coast Railway | Private | | HCAS_001 | 7.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical and Cultural Assets - Sites | Old Dixie Highway | FDOT | | HCAS_002 | 11.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical and Cultural Assets - Sites | Broadway (US 1) | FDOT | | HCAS_003 | 12.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |

# EXPOSURE LEVEL RESULTS FOR TIDAL FLOODING - DAYS FLOODED ANNUALLY

| Tequesta Critical Assets | | | | | | | | Flood Frequency (Days Flooded Annually) | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | High Tide Flooding | | | | |
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | High Tide Existing Conditions | High Tide Int-Low 2040 | High Tide Int-Low 2070 | High Tide Int-High 2040 | High Tide Int-High 2070 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Constitution Park | Village of Tequesta | | PRK_001 | 3.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 10 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Paradise Park | Village of Tequesta | | PRK_002 | 16.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Parks | Parks | Coral Cove Park | Palm Beach County | | PRK_003 | -1.7 | 365 | 365 | 365 | 365 | 365 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Tequesta Park | FDEP | | PRK_004 | 9.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Palm Beach County | | SHL_001 | 0.6 | 77 | 205 | 352 | 360 | 365 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Palm Beach County | | SHL_002 | -1.0 | 365 | 365 | 365 | 365 | 365 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_003 | -3.0 | 365 | 365 | 365 | 365 | 365 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_004 | -1.7 | 365 | 365 | 365 | 365 | 365 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | US DOI, BLM | | SHL_005 | -1.7 | 365 | 365 | 365 | 365 | 365 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_006 | -1.7 | 365 | 365 | 365 | 365 | 365 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_007 | -0.5 | 363 | 365 | 365 | 365 | 365 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_008 | -0.5 | 363 | 365 | 365 | 365 | 365 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_009 | -1.5 | 365 | 365 | 365 | 365 | 365 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_010 | -2.7 | 365 | 365 | 365 | 365 | 365 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_001 | 0.4 | 135 | 283 | 363 | 365 | 365 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_002 | 0.8 | 30 | 138 | 306 | 341 | 365 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_003 | 3.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 110 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_004 | -1.7 | 365 | 365 | 365 | 365 | 365 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_005 | 0.5 | 107 | 241 | 360 | 363 | 365 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_006 | 0.6 | 77 | 205 | 352 | 360 | 365 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_007 | 0.3 | 159 | 315 | 365 | 365 | 365 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_008 | 0.5 | 107 | 241 | 360 | 363 | 365 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_009 | 0.5 | 107 | 241 | 360 | 363 | 365 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Village of Tequesta | | SFW_010 | 11.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_011 | 1.0 | 9 | 79 | 231 | 281 | 365 |
| Natural, Cultural, and Historical Resources | Wetland | Wetlands | Wetland | Palm Beach County | | WLD_001 | -1.7 | 365 | 365 | 365 | 365 | 365 |
| Natural, Cultural, and Historical Resources | Wetland | Wetlands | Wetland | Private | | WLD_002 | -1.7 | 365 | 365 | 365 | 365 | 365 |

# Attachment 2

# Exposure Level Results for Rainfall-Induced Flooding

# EXPOSURE LEVEL RESULTS FOR RAINFALL-INDUCED FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Rainfall Inundation | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Rainfall 100-YR/24-HR Int-High Existing Conditions | Rainfall 100-YR/24-HR Int-High 2040 | Rainfall 100-YR/24-HR Int-High 2070 | Rainfall 500-YR/24-HR Int-High Existing Conditions | Rainfall 500-YR/24-HR Int-High 2040 | Rainfall 500-YR/24-HR Int-High 2070 |
| Transportation and Evacuation Routes | Bridge | Bridges | Tequesta Bridge | Village of Tequesta | | BRD_001 | 17.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Bridge | Bridges | Beach Rd Bridge | Palm Beach County | | BRD_002 | 17.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_001 | 18.7 | 28.0 | 28.4 | 28.8 | 29.0 | 29.4 | 29.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_002 | 17.9 | 11.9 | 12.6 | 12.7 | 13.3 | 13.9 | 14.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_003 | 14.3 | 32.6 | 33.0 | 34.0 | 33.7 | 34.2 | 35.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_004 | 16.5 | 24.0 | 24.8 | 25.0 | 25.8 | 26.5 | 26.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_005 | 24.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_006 | 21.0 | Not Flooded | 21.1 | 21.7 | 21.7 | 22.0 | 21.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_007 | 18.2 | 11.6 | 12.1 | 12.5 | 12.6 | 13.1 | 13.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_008 | 21.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_009 | 18.4 | 10.7 | 11.4 | 12.1 | 12.4 | 13.3 | 14.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_010 | 22.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_011 | 6.4 | 28.3 | 29.5 | 30.2 | 30.8 | 32.3 | 53.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_012 | 13.0 | 11.4 | 11.9 | 12.4 | 12.2 | 12.6 | 13.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_013 | 16.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_014 | 18.5 | 4.1 | 4.8 | 5.3 | 5.5 | 9.6 | 10.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_015 | 18.3 | 5.3 | 5.6 | 6.1 | 6.1 | 6.6 | 7.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_016 | 7.0 | 21.2 | 22.3 | 22.6 | 23.6 | 25.0 | 25.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_017 | 17.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_018 | 17.6 | 20.2 | 20.9 | 21.2 | 21.8 | 22.8 | 23.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_019 | 18.6 | 6.8 | 7.3 | 7.7 | 7.8 | 8.4 | 8.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_020 | 17.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_021 | 18.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_022 | 17.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_023 | 17.6 | 39.8 | 40.2 | 40.8 | 40.7 | 41.3 | 42.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_024 | 12.7 | 15.0 | 15.2 | 15.8 | 15.7 | 16.1 | 16.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_025 | 13.0 | 21.0 | 21.1 | 21.8 | 21.7 | 22.3 | 22.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chestnut Trl | Village of Tequesta | Local | MJRD_026 | 7.9 | 11.6 | 14.0 | 15.7 | 16.2 | 18.1 | 20.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cedar Hill Ln | Village of Tequesta | Local | MJRD_027 | 7.9 | 10.7 | 13.1 | 14.6 | 15.2 | 17.3 | 19.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_028 | 10.6 | Not Flooded | Not Flooded | Not Flooded | 2.4 | 4.0 | 3.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Ln | Village of Tequesta | Local | MJRD_029 | 8.8 | 7.9 | 10.4 | 11.4 | 13.1 | 15.4 | 16.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Cir | Village of Tequesta | Local | MJRD_030 | 9.0 | 16.2 | 18.6 | 21.4 | 20.9 | 22.2 | 24.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Ct | Village of Tequesta | Local | MJRD_031 | 10.0 | 4.8 | 7.7 | 7.3 | 9.6 | 12.1 | 11.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Ct | Village of Tequesta | Local | MJRD_032 | 8.7 | 20.0 | 22.4 | 22.4 | 24.4 | 25.8 | 25.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Ln | Village of Tequesta | Local | MJRD_033 | 8.4 | 7.2 | 14.4 | 15.6 | 16.8 | 18.8 | 20.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Magnolia Way | Village of Tequesta | Local | MJRD_034 | 4.3 | 25.9 | 30.0 | 33.8 | 33.5 | 36.6 | 47.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Magnolia Way | Village of Tequesta | Local | MJRD_035 | 5.3 | 13.9 | 17.5 | 25.6 | 21.2 | 25.0 | 29.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beechwood Trl | Village of Tequesta | Local | MJRD_036 | 5.9 | 3.0 | 5.8 | 5.8 | 6.7 | 8.6 | 15.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_037 | 4.4 | 10.0 | 16.4 | 24.0 | 20.6 | 26.8 | 33.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_038 | 3.7 | 18.8 | 25.2 | 33.2 | 29.4 | 35.5 | 42.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_039 | 7.3 | 8.3 | 11.2 | 12.5 | 14.9 | 18.5 | 20.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_040 | 7.5 | 11.8 | 15.2 | 15.2 | 17.3 | 20.3 | 21.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hemlock Ln | Village of Tequesta | Local | MJRD_041 | 7.2 | 5.5 | 9.5 | 11.9 | 14.0 | 17.8 | 19.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_042 | 5.3 | 29.3 | 33.0 | 35.4 | 37.2 | 41.0 | 43.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_043 | 7.2 | 9.4 | 12.2 | 13.6 | 16.1 | 20.3 | 22.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dogwood Rdg | Village of Tequesta | Local | MJRD_044 | 5.9 | 21.8 | 25.7 | 27.8 | 29.8 | 33.7 | 36.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_045 | 5.9 | 21.5 | 33.7 | 34.1 | 35.0 | 36.2 | 36.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_046 | 7.7 | 4.3 | 10.9 | 12.5 | 14.2 | 18.0 | 19.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_047 | 8.8 | Not Flooded | 23.0 | 13.6 | 24.1 | 25.0 | 23.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_048 | 7.7 | 3.7 | 9.5 | 13.3 | 13.2 | 14.6 | 17.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Buttonwood Cir | Village of Tequesta | Local | MJRD_049 | 4.4 | 9.8 | 16.3 | 24.0 | 20.5 | 26.6 | 33.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_050 | 7.8 | 12.2 | 14.0 | 15.0 | 15.7 | 17.0 | 17.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_051 | 7.8 | 12.7 | 14.5 | 15.5 | 16.3 | 17.6 | 18.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_052 | 3.9 | 22.4 | 27.0 | 30.8 | 29.0 | 32.4 | 40.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_053 | 7.9 | 10.9 | 13.0 | 13.9 | 15.0 | 16.6 | 17.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Birch Pl | Village of Tequesta | Local | MJRD_054 | 9.2 | 8.2 | 10.8 | 11.2 | 12.6 | 14.2 | 14.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beechwood Trl | Village of Tequesta | Local | MJRD_055 | 6.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 7.2 | 14.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chestnut Trl | Village of Tequesta | Local | MJRD_056 | 7.8 | 13.6 | 15.8 | 17.3 | 17.9 | 19.8 | 21.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_057 | 8.5 | 3.0 | 6.0 | 7.7 | 8.2 | 10.9 | 11.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_058 | 6.1 | Not Flooded | Not Flooded | Not Flooded | 10.2 | 11.2 | 22.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pinetree Cir | Village of Tequesta | Local | MJRD_059 | 6.6 | 29.9 | 30.7 | 31.2 | 31.7 | 33.0 | 33.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_060 | 7.0 | 24.7 | 25.6 | 26.3 | 26.8 | 28.4 | 29.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oak Ridge Ln | Village of Tequesta | Local | MJRD_061 | 7.6 | 16.0 | 17.6 | 18.5 | 19.9 | 22.3 | 23.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bay Tree Ln | Village of Tequesta | Local | MJRD_062 | 7.3 | 20.3 | 22.0 | 22.3 | 24.2 | 26.5 | 27.1 |

# EXPOSURE LEVEL RESULTS FOR RAINFALL-INDUCED FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Rainfall Inundation | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Rainfall 100-YR/24-HR Int-High Existing Conditions | Rainfall 100-YR/24-HR Int-High 2040 | Rainfall 100-YR/24-HR Int-High 2070 | Rainfall 500-YR/24-HR Int-High Existing Conditions | Rainfall 500-YR/24-HR Int-High 2040 | Rainfall 500-YR/24-HR Int-High 2070 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oak Ridge Ln | Village of Tequesta | Local | MJRD_063 | 8.0 | 11.2 | 12.8 | 14.4 | 15.5 | 17.9 | 19.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Cypress Dr | Village of Tequesta | Local | MJRD_064 | 10.6 | 7.3 | 10.1 | 10.4 | 13.6 | 15.6 | 15.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_065 | 7.3 | 20.3 | 22.0 | 22.6 | 24.1 | 26.5 | 27.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_066 | 7.3 | 20.5 | 22.2 | 24.1 | 24.4 | 37.7 | 38.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Cypress Dr | Village of Tequesta | Local | MJRD_067 | 10.8 | Not Flooded | 6.5 | 7.6 | 46.1 | 47.4 | 47.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Poplar Rd | Village of Tequesta | Local | MJRD_068 | 8.2 | 20.3 | 24.6 | 26.0 | 26.3 | 27.6 | 29.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_069 | 9.4 | 10.8 | 12.5 | 12.6 | 14.3 | 15.6 | 15.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Woodland Dr | Village of Tequesta | Local | MJRD_070 | 8.8 | 18.1 | 19.9 | 21.7 | 21.7 | 23.2 | 24.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_071 | 9.5 | 9.1 | 10.9 | 11.3 | 12.6 | 14.2 | 14.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_072 | 9.3 | 17.2 | 18.0 | 19.1 | 18.8 | 19.8 | 21.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Acorn Cir | Village of Tequesta | Local | MJRD_073 | 11.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Teakwood Cir | Village of Tequesta | Local | MJRD_074 | 9.0 | 20.4 | 21.1 | 21.4 | 22.0 | 22.8 | 23.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_075 | 9.3 | 17.2 | 17.9 | 18.2 | 18.7 | 19.6 | 20.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_076 | 16.9 | 36.4 | 37.0 | 37.6 | 37.7 | 38.5 | 38.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oakleaf Ct | Village of Tequesta | Local | MJRD_077 | 18.8 | 15.0 | 15.5 | 15.8 | 16.2 | 16.8 | 17.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Laurel Oaks Cir | Village of Tequesta | Local | MJRD_078 | 18.8 | 16.1 | 16.7 | 16.9 | 17.4 | 18.1 | 18.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_079 | 19.2 | 10.1 | 10.7 | 10.1 | 11.4 | 12.1 | 11.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oakland Ct | Village of Tequesta | Local | MJRD_080 | 18.8 | 14.3 | 14.9 | 16.0 | 15.6 | 16.3 | 17.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_081 | 19.2 | 10.0 | 10.6 | 10.3 | 11.3 | 12.1 | 11.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Live Oak Cir | Village of Tequesta | Local | MJRD_082 | 18.8 | 15.0 | 15.6 | 16.8 | 16.4 | 17.0 | 18.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_083 | 19.2 | 10.7 | 11.3 | 12.6 | 12.1 | 12.7 | 14.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tall Oaks Cir | Village of Tequesta | Local | MJRD_084 | 18.9 | 15.0 | 15.6 | 17.4 | 16.4 | 17.0 | 18.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Live Oak Cir | Village of Tequesta | Local | MJRD_085 | 19.0 | 13.0 | 13.6 | 16.1 | 14.4 | 15.0 | 17.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Live Oak Cir | Village of Tequesta | Local | MJRD_086 | 18.5 | 18.4 | 18.6 | 21.1 | 19.0 | 19.3 | 21.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Village Blvd | Village of Tequesta | Local | MJRD_087 | 13.4 | 93.2 | 93.7 | 94.2 | 94.6 | 95.4 | 96.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Intracoastal Cir | Village of Tequesta | Local | MJRD_088 | 14.3 | 59.6 | 60.6 | 61.0 | 61.4 | 62.3 | 62.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Coconut Ln | Village of Tequesta | Local | MJRD_089 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Intracoastal Cir | Village of Tequesta | Local | MJRD_090 | 6.2 | 19.0 | 23.3 | 25.9 | 28.0 | 31.9 | 34.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Intracoastal Cir | Village of Tequesta | Local | MJRD_091 | 11.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Intracoastal Cir | Village of Tequesta | Local | MJRD_092 | 6.3 | 9.8 | 10.6 | 11.6 | 11.3 | 14.3 | 16.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Point Dr | Village of Tequesta | Local | MJRD_093 | 5.5 | 8.0 | 9.1 | 10.6 | 10.1 | 12.7 | 20.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Tree Dr | Village of Tequesta | Local | MJRD_094 | 6.0 | 5.4 | 5.8 | 6.1 | 6.1 | 6.6 | 13.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Tree Dr | Village of Tequesta | Local | MJRD_095 | 5.5 | 12.7 | 13.0 | 13.4 | 13.2 | 14.5 | 21.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_096 | -0.5 | 75.5 | 81.5 | 88.8 | 85.4 | 91.1 | 97.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_097 | 4.4 | 16.0 | 18.8 | 25.2 | 22.8 | 28.0 | 34.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_098 | 4.3 | 17.0 | 20.0 | 26.9 | 23.9 | 29.0 | 35.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_099 | 4.5 | 13.4 | 16.4 | 24.0 | 20.4 | 25.4 | 33.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_100 | 4.2 | 16.7 | 19.7 | 26.6 | 23.6 | 28.7 | 36.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_101 | 4.8 | 9.8 | 12.5 | 19.6 | 16.3 | 21.4 | 29.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Evergreen Ave | Village of Tequesta | Local | MJRD_102 | 4.3 | 15.8 | 18.8 | 25.6 | 22.8 | 27.8 | 35.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Evergreen Ave | Village of Tequesta | Local | MJRD_103 | 4.3 | 16.0 | 19.0 | 26.0 | 22.9 | 28.0 | 35.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_104 | 4.5 | 13.8 | 16.7 | 23.9 | 20.6 | 25.7 | 33.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_105 | 3.5 | 25.2 | 28.4 | 36.1 | 32.4 | 37.6 | 45.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Evergreen Ave | Village of Tequesta | Local | MJRD_106 | 4.2 | 16.8 | 19.9 | 27.0 | 23.9 | 29.0 | 36.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Norfolk Ave | Village of Tequesta | Local | MJRD_107 | 4.1 | 18.4 | 21.2 | 28.0 | 25.2 | 30.2 | 37.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_108 | 4.6 | 12.8 | 15.5 | 21.7 | 19.2 | 24.4 | 31.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_109 | 4.5 | 14.6 | 17.5 | 24.4 | 21.5 | 26.5 | 34.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_110 | 3.5 | 25.2 | 28.4 | 35.0 | 32.4 | 37.6 | 44.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_111 | 4.0 | 19.9 | 23.0 | 30.6 | 27.0 | 32.0 | 40.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_112 | 5.0 | 23.0 | 24.8 | 29.0 | 27.0 | 28.7 | 32.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Venus Ave | Village of Tequesta | Local | MJRD_113 | 5.0 | 14.0 | 15.1 | 16.9 | 16.6 | 20.8 | 26.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_114 | 6.1 | 26.6 | 29.2 | 30.1 | 32.2 | 35.2 | 37.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Mars Ave | Village of Tequesta | Local | MJRD_115 | 5.9 | 15.1 | 49.3 | 48.2 | 52.9 | 56.3 | 55.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Saturn Ave | Village of Tequesta | Local | MJRD_116 | 6.6 | 30.0 | 32.0 | 32.5 | 34.6 | 37.4 | 38.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Venus Ave | Village of Tequesta | Local | MJRD_117 | 6.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 6.7 | 12.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Franklin Rd | Village of Tequesta | Local | MJRD_118 | 3.3 | 33.4 | 34.4 | 37.9 | 35.6 | 39.8 | 47.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_119 | 4.2 | 16.1 | 19.2 | 27.4 | 23.0 | 28.2 | 37.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_120 | 4.0 | 20.9 | 24.0 | 29.4 | 27.8 | 33.0 | 39.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Saturn Ave | Village of Tequesta | Local | MJRD_121 | 8.1 | 16.4 | 18.2 | 18.4 | 20.9 | 23.9 | 25.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Church Rd | Village of Tequesta | Local | MJRD_122 | 3.6 | 24.6 | 27.7 | 34.6 | 32.2 | 37.3 | 44.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Venus Ave | Village of Tequesta | Local | MJRD_123 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Saturn Ave | Village of Tequesta | Local | MJRD_124 | 8.3 | 17.3 | 19.1 | 20.5 | 22.7 | 26.6 | 27.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_125 | 3.7 | 25.0 | 28.1 | 33.8 | 31.9 | 37.1 | 43.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Venus Ave | Village of Tequesta | Local | MJRD_126 | 8.7 | Not Flooded | 3.0 | Not Flooded | 5.0 | 9.2 | 7.0 |

# EXPOSURE LEVEL RESULTS FOR RAINFALL-INDUCED FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Rainfall Inundation | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Rainfall 100-YR/24-HR Int-High Existing Conditions | Rainfall 100-YR/24-HR Int-High 2040 | Rainfall 100-YR/24-HR Int-High 2070 | Rainfall 500-YR/24-HR Int-High Existing Conditions | Rainfall 500-YR/24-HR Int-High 2040 | Rainfall 500-YR/24-HR Int-High 2070 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_127 | 8.6 | 23.3 | 23.9 | 24.4 | 24.5 | 26.9 | 29.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_128 | 8.8 | 12.0 | 13.8 | 15.8 | 17.4 | 21.5 | 24.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_129 | 9.2 | 6.7 | 8.5 | 10.1 | 11.9 | 15.5 | 17.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_130 | 8.8 | Not Flooded | Not Flooded | 14.0 | 15.8 | 19.0 | 21.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_131 | 7.5 | Not Flooded | 11.0 | 12.8 | 13.9 | 15.2 | 18.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_132 | 4.7 | 11.3 | 14.2 | 21.4 | 20.2 | 23.9 | 32.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Holly Cir | Village of Tequesta | Local | MJRD_133 | 10.0 | 6.5 | 7.0 | 7.7 | 7.7 | 10.7 | 14.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_134 | 10.3 | 2.6 | 3.2 | 4.0 | 4.3 | 8.0 | 10.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Cypress Dr | Village of Tequesta | Local | MJRD_135 | 10.6 | 49.1 | 49.4 | 49.6 | 49.9 | 50.3 | 50.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Camelia Cir | Village of Tequesta | Local | MJRD_136 | 10.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 6.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_137 | 10.3 | 5.9 | 6.6 | 7.3 | 7.4 | 8.2 | 8.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Ridgewood Cir | Village of Tequesta | Local | MJRD_138 | 5.4 | 28.8 | 29.2 | 29.9 | 30.2 | 30.8 | 31.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Azalea Cir | Village of Tequesta | Local | MJRD_139 | 9.9 | 9.4 | 10.1 | 10.2 | 11.4 | 12.4 | 13.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_140 | 8.6 | 26.4 | 27.1 | 27.8 | 27.8 | 28.6 | 29.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Short Ave | Village of Tequesta | Local | MJRD_141 | 4.0 | 20.9 | 23.8 | 29.8 | 27.6 | 32.8 | 38.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_142 | 4.4 | 15.7 | 18.0 | 24.1 | 21.7 | 26.9 | 33.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_143 | 4.3 | 16.9 | 19.8 | 26.0 | 23.6 | 28.8 | 35.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Maple Ave | Village of Tequesta | Local | MJRD_144 | 3.3 | 28.9 | 32.2 | 38.2 | 36.1 | 41.3 | 47.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_145 | 3.3 | 26.8 | 30.0 | 38.3 | 34.0 | 39.1 | 47.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_146 | 3.1 | 30.4 | 33.6 | 40.4 | 37.6 | 42.7 | 50.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Garden St | Village of Tequesta | Local | MJRD_147 | 5.2 | 11.8 | 13.2 | 13.8 | 14.6 | 17.2 | 23.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Westwood Ave | Village of Tequesta | Local | MJRD_148 | 4.8 | 32.5 | 32.5 | 32.5 | 32.5 | 32.5 | 36.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Garden St | Village of Tequesta | Local | MJRD_149 | 4.4 | 20.5 | 22.0 | 23.8 | 23.4 | 26.3 | 33.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_150 | 4.3 | 19.3 | 21.0 | 27.1 | 24.4 | 29.5 | 36.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Elm Ave | Village of Tequesta | Local | MJRD_151 | 3.0 | 30.7 | 34.0 | 40.9 | 37.9 | 43.1 | 49.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_152 | 3.4 | 25.4 | 28.7 | 36.5 | 32.6 | 37.8 | 46.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_153 | 2.9 | 32.5 | 35.8 | 42.8 | 39.7 | 44.9 | 52.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oak Ave | Village of Tequesta | Local | MJRD_154 | 3.1 | 30.2 | 33.5 | 39.6 | 37.4 | 42.6 | 49.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_155 | 3.1 | 30.2 | 33.5 | 40.4 | 37.4 | 42.6 | 49.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_156 | 3.9 | 20.2 | 23.4 | 31.6 | 27.4 | 32.5 | 40.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Cir | Village of Tequesta | Local | MJRD_157 | 3.0 | 31.9 | 35.3 | 41.6 | 39.2 | 44.4 | 50.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_158 | 3.5 | 25.6 | 28.8 | 36.0 | 32.8 | 37.9 | 45.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cedar Ave | Village of Tequesta | Local | MJRD_159 | 3.5 | 25.1 | 28.3 | 35.5 | 32.3 | 37.4 | 45.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_160 | 3.9 | 21.6 | 24.8 | 32.4 | 28.8 | 34.0 | 42.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_161 | 3.7 | 23.3 | 26.4 | 33.1 | 30.2 | 35.4 | 42.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_162 | 7.1 | 6.4 | 7.8 | 8.2 | 9.8 | 12.2 | 13.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_163 | 6.9 | 6.1 | 7.6 | 7.2 | 10.2 | 12.5 | 12.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_164 | 6.4 | 6.5 | 9.1 | 10.0 | 11.8 | 13.9 | 14.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_165 | 6.3 | 5.6 | 7.3 | 7.8 | 9.6 | 11.6 | 12.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_166 | 5.8 | 8.5 | 9.8 | 10.8 | 12.0 | 14.4 | 16.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_167 | 4.8 | 20.5 | 22.6 | 22.9 | 25.2 | 27.8 | 30.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_168 | 4.3 | 16.6 | 19.6 | 26.0 | 23.3 | 28.4 | 35.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_169 | 4.3 | 15.7 | 18.8 | 25.3 | 22.7 | 27.8 | 34.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_170 | 4.2 | 18.4 | 21.4 | 27.5 | 25.2 | 30.4 | 37.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_171 | 6.8 | 28.9 | 30.1 | 31.2 | 31.9 | 34.4 | 36.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fiesta Ave | Village of Tequesta | Local | MJRD_172 | 8.9 | 5.5 | 7.0 | 7.9 | 9.2 | 12.5 | 13.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_173 | 9.3 | Not Flooded | 0.5 | 1.3 | 2.3 | 4.8 | 6.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_174 | 9.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 2.8 | 4.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_175 | 10.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cypress Dr | Village of Tequesta | Local | MJRD_176 | 10.2 | 16.2 | 17.0 | 17.3 | 18.8 | 18.8 | 22.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cove Rd | Village of Tequesta | Local | MJRD_177 | 20.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Leigh Rd | Village of Tequesta | Local | MJRD_178 | 7.9 | 17.6 | 19.3 | 20.6 | 21.6 | 24.7 | 26.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fiesta Ave | Village of Tequesta | Local | MJRD_179 | 8.9 | 8.5 | 10.2 | 10.9 | 12.6 | 16.0 | 17.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Daly Rd | Village of Tequesta | Local | MJRD_180 | 8.3 | 15.4 | 17.0 | 19.1 | 19.6 | 22.7 | 25.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fiesta Ave | Village of Tequesta | Local | MJRD_181 | 8.9 | 11.3 | 13.2 | 14.8 | 17.0 | 21.1 | 23.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_182 | 9.0 | 10.6 | 12.5 | 13.8 | 31.4 | 35.5 | 36.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_183 | 11.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 47.3 | 49.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cypress Dr | Village of Tequesta | Local | MJRD_184 | 10.5 | 27.5 | 29.2 | 29.5 | 32.6 | 37.2 | 38.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_185 | 14.9 | 25.4 | 25.9 | 28.9 | 26.4 | 27.4 | 30.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_186 | 16.4 | 13.1 | 13.7 | 14.9 | 14.5 | 15.1 | 16.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_187 | 17.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 14.5 | 15.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bay Harbor Rd | Village of Tequesta | Local | MJRD_188 | 2.6 | 27.7 | 30.4 | 34.2 | 32.6 | 34.8 | 50.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Point Dr | Village of Tequesta | Local | MJRD_189 | 4.8 | Not Flooded | 4.8 | 8.3 | 7.1 | 8.3 | 22.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Point Dr | Village of Tequesta | Local | MJRD_190 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 15.6 |

# EXPOSURE LEVEL RESULTS FOR RAINFALL-INDUCED FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Rainfall Inundation | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Rainfall 100-YR/24-HR Int-High Existing Conditions | Rainfall 100-YR/24-HR Int-High 2040 | Rainfall 100-YR/24-HR Int-High 2070 | Rainfall 500-YR/24-HR Int-High Existing Conditions | Rainfall 500-YR/24-HR Int-High 2040 | Rainfall 500-YR/24-HR Int-High 2070 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_191 | 5.0 | 16.3 | 18.7 | 21.0 | 21.4 | 23.6 | 25.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_192 | 4.8 | 23.2 | 24.8 | 26.8 | 27.8 | 30.7 | 32.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview W | Village of Tequesta | Local | MJRD_193 | 5.1 | 19.1 | 20.3 | 22.1 | 21.7 | 22.4 | 27.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fair Pl | Village of Tequesta | Local | MJRD_194 | 4.7 | 16.3 | 19.8 | 21.0 | 22.0 | 24.0 | 29.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview E | Village of Tequesta | Local | MJRD_195 | 5.3 | 9.2 | 11.4 | 13.6 | 13.4 | 15.6 | 21.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview E | Village of Tequesta | Local | MJRD_196 | 4.8 | 18.6 | 20.2 | 24.7 | 21.6 | 22.8 | 30.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_197 | 5.5 | 16.2 | 17.9 | 18.5 | 19.6 | 22.0 | 23.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_198 | 4.8 | 22.2 | 26.4 | 30.5 | 30.8 | 33.8 | 35.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golf Pl | Village of Tequesta | Local | MJRD_199 | 6.2 | 7.4 | 8.9 | 11.8 | 11.4 | 14.3 | 16.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_200 | 4.6 | 28.7 | 30.8 | 31.9 | 33.1 | 35.2 | 37.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bunker Pl | Village of Tequesta | Local | MJRD_201 | 4.4 | 23.8 | 30.6 | 35.5 | 35.0 | 38.0 | 41.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_202 | 4.6 | 27.7 | 29.6 | 31.4 | 31.9 | 34.8 | 37.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | R View Pl | Village of Tequesta | Local | MJRD_203 | 5.8 | 14.9 | 16.9 | 17.4 | 19.2 | 21.5 | 23.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_204 | 5.9 | 16.0 | 21.7 | 29.5 | 24.4 | 27.2 | 35.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway W | Village of Tequesta | Local | MJRD_205 | 4.9 | 25.3 | 28.9 | 33.5 | 33.5 | 37.0 | 40.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway E | Village of Tequesta | Local | MJRD_206 | 4.8 | 24.5 | 31.2 | 34.9 | 35.8 | 39.2 | 40.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_207 | 6.3 | 16.7 | 17.3 | 18.0 | 19.0 | 22.2 | 24.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_208 | 5.3 | 5.3 | 7.2 | 13.3 | 9.4 | 15.5 | 22.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway N | Village of Tequesta | Local | MJRD_209 | 6.6 | 4.9 | 8.5 | 13.9 | 13.4 | 16.7 | 19.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | North Pl | Village of Tequesta | Local | MJRD_210 | 6.4 | 8.5 | 13.0 | 14.6 | 17.0 | 18.8 | 20.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway N | Village of Tequesta | Local | MJRD_211 | 5.9 | 14.0 | 17.3 | 21.2 | 22.1 | 25.4 | 27.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway N | Village of Tequesta | Local | MJRD_212 | 5.0 | 24.2 | 27.5 | 32.8 | 32.4 | 35.8 | 38.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway N | Village of Tequesta | Local | MJRD_213 | 5.9 | 14.9 | 16.2 | 19.9 | 19.8 | 23.0 | 25.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_214 | 4.9 | 27.7 | 28.9 | 30.8 | 31.4 | 34.3 | 38.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Cir | Village of Tequesta | Local | MJRD_215 | 5.2 | 6.4 | 7.9 | 14.5 | 10.7 | 16.8 | 24.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_216 | 5.3 | 6.8 | 27.6 | 30.1 | 30.6 | 32.4 | 34.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_217 | 7.4 | Not Flooded | Not Flooded | 3.7 | 5.2 | 7.1 | 8.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_218 | 6.4 | 14.0 | 16.2 | 19.7 | 25.6 | 26.3 | 28.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_219 | 4.9 | 13.7 | 16.2 | 18.6 | 18.4 | 21.1 | 28.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Palmetto Way | Village of Tequesta | Local | MJRD_220 | 4.7 | 18.0 | 20.3 | 23.2 | 22.4 | 24.5 | 31.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_221 | 4.9 | 8.9 | 11.5 | 19.3 | 15.7 | 21.7 | 28.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_222 | 5.3 | 4.9 | 6.7 | 12.5 | 10.9 | 16.9 | 22.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Starboard Way | Village of Tequesta | Local | MJRD_223 | 3.6 | 20.9 | 25.7 | 34.9 | 29.9 | 35.9 | 44.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_224 | 5.5 | Not Flooded | 3.4 | 11.6 | 9.1 | 15.1 | 21.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Gulfstream Dr | Village of Tequesta | Local | MJRD_225 | 3.7 | 18.8 | 25.2 | 32.4 | 29.4 | 35.4 | 42.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Leeward Cir | Village of Tequesta | Local | MJRD_226 | 3.6 | 20.0 | 26.4 | 34.3 | 30.6 | 36.7 | 43.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_227 | 5.1 | Not Flooded | 7.8 | 15.5 | 13.0 | 19.1 | 25.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tradewinds Cir | Village of Tequesta | Local | MJRD_228 | 3.4 | 23.8 | 30.1 | 36.0 | 34.3 | 40.4 | 45.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_229 | 5.1 | Not Flooded | 8.6 | 14.9 | 12.8 | 19.0 | 24.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Cir | Village of Tequesta | Local | MJRD_230 | 3.9 | 15.6 | 22.0 | 30.4 | 26.2 | 32.3 | 39.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_231 | 5.4 | Not Flooded | 4.2 | 11.8 | 8.5 | 14.6 | 21.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_232 | 5.4 | Not Flooded | Not Flooded | 11.9 | 8.5 | 14.6 | 21.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golf Club Cir | Village of Tequesta | Local | MJRD_233 | 5.1 | 8.4 | 9.5 | 15.7 | 12.2 | 18.4 | 26.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_234 | 4.8 | 11.8 | 12.7 | 20.3 | 16.4 | 22.6 | 29.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Yacht Club Pl | Village of Tequesta | | MJRD_235 | 4.0 | 25.6 | 27.5 | 29.0 | 29.3 | 30.7 | 33.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_236 | 5.2 | 11.5 | 13.4 | 15.5 | 15.8 | 17.3 | 20.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | El Portal Dr | Village of Tequesta | Local | MJRD_237 | 4.9 | 15.2 | 17.4 | 19.9 | 19.4 | 21.6 | 27.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview E | Village of Tequesta | Local | MJRD_238 | 4.5 | 20.4 | 22.6 | 24.2 | 24.6 | 26.6 | 32.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Tree Pl | Village of Tequesta | Local | MJRD_239 | 5.0 | 13.8 | 15.7 | 17.9 | 17.5 | 19.7 | 25.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | El Portal Dr | Village of Tequesta | Local | MJRD_240 | 5.2 | 13.3 | 15.5 | 18.1 | 17.5 | 19.7 | 25.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_241 | 5.2 | 12.0 | 13.9 | 15.8 | 15.7 | 17.3 | 19.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | El Portal Dr | Village of Tequesta | Local | MJRD_242 | 5.7 | 2.8 | 6.4 | 8.3 | 8.3 | 10.3 | 16.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Yacht Club Pl | Village of Tequesta | Local | MJRD_243 | 4.9 | 14.4 | 16.4 | 19.0 | 18.6 | 20.6 | 27.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Yacht Club Pl | Village of Tequesta | Local | MJRD_244 | 5.4 | 10.9 | 11.3 | 12.4 | 13.4 | 14.5 | 20.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_245 | 5.1 | 11.3 | 13.7 | 16.3 | 16.0 | 18.5 | 25.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_246 | 5.5 | 7.1 | 9.2 | 14.0 | 11.4 | 14.3 | 22.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Ct | Village of Tequesta | Local | MJRD_247 | 4.8 | 8.0 | 11.2 | 14.4 | 13.6 | 16.3 | 26.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Ter | Village of Tequesta | Local | MJRD_248 | 4.2 | 21.0 | 23.2 | 25.9 | 25.3 | 27.8 | 34.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Rd | Village of Tequesta | Local | MJRD_249 | 4.6 | 8.0 | 10.0 | 12.6 | 12.1 | 14.6 | 24.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Rd | Village of Tequesta | Local | MJRD_250 | 4.3 | 20.8 | 22.8 | 25.0 | 24.7 | 27.1 | 32.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Shady Ln | Village of Tequesta | Local | MJRD_251 | 4.2 | 15.4 | 17.0 | 19.9 | 19.1 | 21.6 | 38.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Rd | Village of Tequesta | Local | MJRD_252 | 4.3 | 19.6 | 21.7 | 24.6 | 23.9 | 26.4 | 33.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Point Dr | Village of Tequesta | Local | MJRD_253 | 6.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 8.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_254 | 5.3 | 13.6 | 14.6 | 16.1 | 16.1 | 17.5 | 19.2 |

# EXPOSURE LEVEL RESULTS FOR RAINFALL-INDUCED FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Rainfall Inundation | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Rainfall 100-YR/24-HR Int-High Existing Conditions | Rainfall 100-YR/24-HR Int-High 2040 | Rainfall 100-YR/24-HR Int-High 2070 | Rainfall 500-YR/24-HR Int-High Existing Conditions | Rainfall 500-YR/24-HR Int-High 2040 | Rainfall 500-YR/24-HR Int-High 2070 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_255 | 5.7 | 5.5 | 6.5 | 8.5 | 8.2 | 16.6 | 16.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_256 | 4.8 | 16.4 | 17.9 | 20.0 | 19.8 | 21.8 | 27.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_257 | 5.0 | 15.7 | 16.7 | 18.8 | 18.4 | 20.4 | 26.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview W | Village of Tequesta | Local | MJRD_258 | 4.8 | 16.1 | 18.6 | 20.6 | 20.8 | 22.8 | 29.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_259 | 5.8 | 6.5 | 9.1 | 10.8 | 11.0 | 12.7 | 14.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Club Pl | Village of Tequesta | Local | MJRD_260 | 5.6 | 9.1 | 10.0 | 10.1 | 11.0 | 12.0 | 14.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Magnolia Way | Village of Tequesta | Local | MJRD_261 | 5.3 | 14.9 | 17.5 | 28.4 | 28.7 | 32.3 | 35.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Coconut Ln | Village of Tequesta | Local | MJRD_262 | 20.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 7.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Shady Ln | Village of Tequesta | Local | MJRD_263 | 4.3 | 13.7 | 15.6 | 18.4 | 17.9 | 20.3 | 30.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_264 | 6.2 | 18.2 | 22.0 | 24.4 | 26.2 | 30.0 | 32.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Alley | Village of Tequesta | Local | MJRD_265 | 10.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Water Treatment Facility | Water Treatment Plants | Water Treatment Facility | Village of Tequesta | | DWF_001 | 18.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Water Ground Storage Tank | Ground Storage Tanks | Ground Storage Tank | Village of Tequesta | | DWF_008 | 15.2 | 3.5 | 6.2 | 7.3 | 10.8 | 14.2 | 17.2 |
| Critical Infrastructure | Water Ground Storage Tank | Ground Storage Tanks | Ground Storage Tank | Village of Tequesta | | DWF_009 | 15.2 | Not Flooded | 1.7 | 3.4 | 6.8 | 10.3 | 11.9 |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well R4 | Village of Tequesta | | DWF_002 | 19.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well R3 | Village of Tequesta | | DWF_003 | 14.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 7 | Village of Tequesta | | DWF_004 | 11.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 20 | Village of Tequesta | | DWF_005 | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 8.8 | 10.1 |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 19 | Village of Tequesta | | DWF_006 | 12.3 | Not Flooded | Not Flooded | Not Flooded | 3.1 | 4.0 | 8.4 |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 18 | Village of Tequesta | | DWF_007 | 13.8 | Not Flooded | Not Flooded | 4.8 | 7.9 | 8.6 | 7.2 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well R4 Pump | Village of Tequesta | | DWF_010 | 19.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well R3 Pump | Village of Tequesta | | DWF_011 | 14.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 7 Pump | Village of Tequesta | | DWF_012 | 11.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 20 Pump | Village of Tequesta | | DWF_013 | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 8.8 | 10.1 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 19 Pump | Village of Tequesta | | DWF_014 | 12.3 | Not Flooded | Not Flooded | Not Flooded | 3.1 | 4.0 | 8.4 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 18 Pump | Village of Tequesta | | DWF_015 | 13.8 | Not Flooded | Not Flooded | 4.8 | 7.9 | 8.6 | 7.2 |
| Critical Infrastructure | Generator | Electric Facilities | Village Hall IT Standby Generator | Village of Tequesta | | ELC_001 | 14.3 | -16.8 | -16.4 | -15.9 | -15.9 | -13.3 | -13.6 |
| Critical Infrastructure | Generator | Electric Facilities | Public Safety 300kw Standby Generator | Village of Tequesta | | ELC_002 | 12.9 | -26.8 | -24.9 | -24.5 | -23.4 | -23.1 | -22.8 |
| Critical Infrastructure | Generator | Electric Facilities | Rec Center 100kw LP Standby Generator | Village of Tequesta | | ELC_003 | 8.3 | -18.9 | -18.3 | -18.2 | -17.8 | -12.8 | -8.3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS053 - Wetwell | Loxahatchee River District | | WWF_001 | 16.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS066 - Wetwell | Loxahatchee River District | | WWF_002 | 4.5 | Not Flooded | Not Flooded | 4.8 | Not Flooded | Not Flooded | 14.4 |
| Critical Infrastructure | Lift Station | Lift Stations | LS050 - Wetwell | Loxahatchee River District | | WWF_003 | 10.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS055 - Wetwell | Loxahatchee River District | | WWF_004 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 4.1 | 10.7 |
| Critical Infrastructure | Lift Station | Lift Stations | LS057 - Wetwell | Loxahatchee River District | | WWF_005 | 10.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS058 - Wetwell | Loxahatchee River District | | WWF_006 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS061 - Wetwell | Loxahatchee River District | | WWF_007 | 7.9 | 4.1 | 5.5 | 7.9 | 7.8 | 10.0 | 12.7 |
| Critical Infrastructure | Lift Station | Lift Stations | LS064 - Wetwell | Loxahatchee River District | | WWF_008 | 13.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 11.9 |
| Critical Infrastructure | Lift Station | Lift Stations | LS065 - Wetwell | Loxahatchee River District | | WWF_009 | 5.7 | Not Flooded | 3.6 | 9.7 | 6.8 | 12.0 | 19.3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS067 - Wetwell | Loxahatchee River District | | WWF_010 | 3.1 | 22.7 | 23.6 | 20.3 | 24.6 | 25.6 | 31.1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS069 - Wetwell | Loxahatchee River District | | WWF_011 | 11.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS070 - Wetwell | Loxahatchee River District | | WWF_012 | 6.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 6.4 |
| Critical Infrastructure | Lift Station | Lift Stations | LS071 - Wetwell | Loxahatchee River District | | WWF_013 | 7.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 2.3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS072 - Wetwell | Loxahatchee River District | | WWF_014 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS075 - Wetwell | Loxahatchee River District | | WWF_015 | 6.2 | Not Flooded | Not Flooded | 2.9 | Not Flooded | 5.3 | 12.5 |
| Critical Infrastructure | Lift Station | Lift Stations | LS076 - Wetwell | Loxahatchee River District | | WWF_016 | 6.4 | Not Flooded | 3.1 | 2.2 | 3.8 | 6.2 | 3.4 |
| Critical Infrastructure | Lift Station | Lift Stations | LS077 - Wetwell | Loxahatchee River District | | WWF_017 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS078 - Wetwell | Loxahatchee River District | | WWF_018 | 4.3 | Not Flooded | 8.4 | 16.6 | 10.2 | 13.3 | 32.2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS141 - Wetwell | Loxahatchee River District | | WWF_019 | 6.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS144 - Wetwell | Loxahatchee River District | | WWF_020 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS079 - Wetwell | Loxahatchee River District | | WWF_021 | 5.0 | 4.3 | 9.1 | 18.1 | 13.2 | 18.4 | 26.5 |
| Critical Infrastructure | Lift Station | Lift Stations | LS054 - Wetwell | Loxahatchee River District | | WWF_022 | 9.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -0.4 |
| Critical Infrastructure | Lift Station | Lift Stations | LS143 - Wetwell | Loxahatchee River District | | WWF_023 | 3.4 | 26.0 | 29.4 | 31.4 | 33.4 | 38.5 | 41.0 |
| Critical Infrastructure | Lift Station | Lift Stations | LS062 - Wetwell | Loxahatchee River District | | WWF_024 | 15.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS060 - Wetwell | Loxahatchee River District | | WWF_025 | 9.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS107 - Wetwell | Loxahatchee River District | | WWF_026 | 4.4 | Not Flooded | Not Flooded | 6.7 | Not Flooded | 1.9 | 16.3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS053 - Electrical Panel | Loxahatchee River District | | WWF_001a | 20.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS066 - Electrical Panel | Loxahatchee River District | | WWF_002a | 8.5 | Not Flooded | Not Flooded | -43.2 | Not Flooded | Not Flooded | -33.6 |
| Critical Infrastructure | Lift Station | Lift Stations | LS050 - Electrical Panel | Loxahatchee River District | | WWF_003a | 14.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS055 - Electrical Panel | Loxahatchee River District | | WWF_004a | 10.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -43.9 | -37.3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS057 - Electrical Panel | Loxahatchee River District | | WWF_005a | 14.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS058 - Electrical Panel | Loxahatchee River District | | WWF_006a | 12.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS061 - Electrical Panel | Loxahatchee River District | | WWF_007a | 11.9 | -43.9 | -42.5 | -40.1 | -40.2 | -38.0 | -35.3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS064 - Electrical Panel | Loxahatchee River District | | WWF_008a | 17.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -36.1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS065 - Electrical Panel | Loxahatchee River District | | WWF_009a | 9.7 | Not Flooded | -44.4 | -38.3 | -41.2 | -36.0 | -28.7 |

# EXPOSURE LEVEL RESULTS FOR RAINFALL-INDUCED FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Rainfall Inundation | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Rainfall 100-YR/24-HR Int-High Existing Conditions | Rainfall 100-YR/24-HR Int-High 2040 | Rainfall 100-YR/24-HR Int-High 2070 | Rainfall 500-YR/24-HR Int-High Existing Conditions | Rainfall 500-YR/24-HR Int-High 2040 | Rainfall 500-YR/24-HR Int-High 2070 |
| Critical Infrastructure | Lift Station | Lift Stations | LS067 - Electrical Panel | Loxahatchee River District | | WWF_010a | 7.1 | -25.3 | -24.4 | -27.7 | -23.4 | -22.4 | -16.9 |
| Critical Infrastructure | Lift Station | Lift Stations | LS069 - Electrical Panel | Loxahatchee River District | | WWF_011a | 15.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS070 - Electrical Panel | Loxahatchee River District | | WWF_012a | 10.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -41.6 |
| Critical Infrastructure | Lift Station | Lift Stations | LS071 - Electrical Panel | Loxahatchee River District | | WWF_013a | 11.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -45.7 |
| Critical Infrastructure | Lift Station | Lift Stations | LS072 - Electrical Panel | Loxahatchee River District | | WWF_014a | 12.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS075 - Electrical Panel | Loxahatchee River District | | WWF_015a | 10.2 | Not Flooded | Not Flooded | -45.1 | Not Flooded | -42.7 | -35.5 |
| Critical Infrastructure | Lift Station | Lift Stations | LS076 - Electrical Panel | Loxahatchee River District | | WWF_016a | 10.4 | Not Flooded | -44.9 | -45.8 | -44.2 | -41.8 | -44.6 |
| Critical Infrastructure | Lift Station | Lift Stations | LS077 - Electrical Panel | Loxahatchee River District | | WWF_017a | 11.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS078 - Electrical Panel | Loxahatchee River District | | WWF_018a | 8.3 | Not Flooded | -39.6 | -31.4 | -37.8 | -34.7 | -15.8 |
| Critical Infrastructure | Lift Station | Lift Stations | LS141 - Electrical Panel | Loxahatchee River District | | WWF_019a | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS144 - Electrical Panel | Loxahatchee River District | | WWF_020a | 11.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS079 - Electrical Panel | Loxahatchee River District | | WWF_021a | 9.0 | -43.7 | -38.9 | -29.9 | -34.8 | -29.6 | -21.5 |
| Critical Infrastructure | Lift Station | Lift Stations | LS054 - Electrical Panel | Loxahatchee River District | | WWF_022a | 13.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -48.4 |
| Critical Infrastructure | Lift Station | Lift Stations | LS143 - Electrical Panel | Loxahatchee River District | | WWF_023a | 7.4 | -22.0 | -18.6 | -16.6 | -14.6 | -9.5 | -7.0 |
| Critical Infrastructure | Lift Station | Lift Stations | LS062 - Electrical Panel | Loxahatchee River District | | WWF_024a | 19.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS060 - Electrical Panel | Loxahatchee River District | | WWF_025a | 13.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS107 - Electrical Panel | Loxahatchee River District | | WWF_026a | 8.4 | Not Flooded | Not Flooded | -41.3 | Not Flooded | -46.1 | -31.7 |
| Critical Community and Emergency Facilities | EMS | Emergency Medical Service Facilities | Tequesta EMS | Village of Tequesta | | EMF_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -12.2 |
| Critical Community and Emergency Facilities | EOC | Emergency Operations Centers | Emergency Operations Center | Village of Tequesta | | EOC_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -12.2 |
| Critical Community and Emergency Facilities | Fire Station | Fire Stations | Tequesta Fire Department | Village of Tequesta | | FS_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -12.2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Brookdale Tequesta | Private | | HCF_001 | 17.5 | -1.7 | -0.4 | -0.5 | 1.2 | 3.2 | 3.8 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Clarebridge Cottage Tequesta | Private | | HCF_002 | 18.5 | Not Flooded | Not Flooded | Not Flooded | -24.7 | -14.3 | -6.8 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Terrace | Private | | HCF_003 | 23.8 | -2.0 | -1.6 | -1.8 | -1.1 | -0.4 | -0.6 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Urgent Care | Private | | HCF_004 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Publix Pharmacy | Private | | HCF_005 | 25.4 | -16.6 | -16.3 | -4.4 | -15.1 | -14.4 | -4.4 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Drugs | Private | | HCF_006 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | CVS Pharmacy | Private | | HCF_007 | 24.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Law Enforcement Facility | Law Enforcement Facilities | Tequesta Police Department | Village of Tequesta | | LEF_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -12.2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Tequesta Village Hall | Village of Tequesta | | LGF_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -13.3 | -13.6 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - Warehouse and Offices | Village of Tequesta | | LGF_002 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - Clerk's Office Records | Village of Tequesta | | LGF_003 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - PD Evidence Bay | Village of Tequesta | | LGF_004 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Services Bulk Storage Fuel Tank | Village of Tequesta | | LGF_005 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Services 4000 Gallon Split Tank | Village of Tequesta | | LGF_006 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Village Hall IT Server Room | Village of Tequesta | | LGF_007 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -13.3 | -13.6 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Safety 4000g Bulk Storage Tank | Village of Tequesta | | LGF_008 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -12.2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Tequesta Recreational Center | Village of Tequesta | | LGF_009 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -12.8 | -8.3 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Rec Center IT Server Room | Village of Tequesta | | LGF_010 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -12.8 | -8.3 |
| Critical Community and Emergency Facilities | School | Schools | Good Shepherd Episcopal School | Private | | SCL_001 | 9.2 | Not Flooded | Not Flooded | Not Flooded | 1.2 | 2.3 | 3.2 |
| Critical Community and Emergency Facilities | School | Schools | Providence Education Group | Private | | SCL_002 | 8.0 | Not Flooded | -19.8 | -14.9 | -14.6 | -9.7 | -3.7 |
| Critical Community and Emergency Facilities | School | Schools | Mary, Mother of the Light Academy | Private | | SCL_003 | 12.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | School | Schools | First Presbyterian Church Preschool of Tequesta | Private | | SCL_004 | 9.0 | -34.4 | -28.1 | -26.0 | -26.2 | -23.4 | -6.4 |
| Natural, Cultural, and Historical Resources | Conservation Lands | Conservation Lands | Jupiter Inlet Lighthouse Outstanding Natural Area | US DOI, BLM | | CL_001 | -1.7 | 271.7 | 328.2 | 329.0 | 361.7 | 361.7 | 361.7 |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical and Cultural Assets - Sites | Florida East Coast Railway | Private | | HCAS_001 | 7.1 | 111.7 | 113.2 | 114.1 | 114.2 | 116.4 | 116.6 |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical and Cultural Assets - Sites | Old Dixie Highway | FDOT | | HCAS_002 | 11.3 | 62.6 | 79.2 | 79.8 | 80.4 | 80.8 | 81.0 |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical and Cultural Assets - Sites | Broadway (US 1) | FDOT | | HCAS_003 | 12.3 | 127.2 | 127.4 | 127.3 | 127.8 | 128.2 | 128.5 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Constitution Park | Village of Tequesta | | PRK_001 | 3.8 | 45.7 | 46.1 | 49.1 | 47.9 | 59.2 | 65.6 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Paradise Park | Village of Tequesta | | PRK_002 | 16.1 | 41.4 | 41.8 | 41.6 | 42.6 | 43.7 | 44.3 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Coral Cove Park | Palm Beach County | | PRK_003 | -1.7 | 87.8 | 87.8 | 105.7 | 88.0 | 98.6 | 115.3 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Tequesta Park | FDEP | | PRK_004 | 9.8 | 134.8 | 137.6 | 138.1 | 140.6 | 217.2 | 218.2 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Palm Beach County | | SHL_001 | 0.6 | 42.1 | 42.2 | 49.4 | 42.2 | 42.4 | 53.4 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Palm Beach County | | SHL_002 | -1.0 | 70.6 | 70.8 | 82.3 | 71.0 | 75.6 | 91.9 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_003 | -3.0 | 83.4 | 83.4 | 89.9 | 83.4 | 83.4 | 94.7 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_004 | -1.7 | 126.4 | 126.4 | 145.2 | 126.4 | 137.2 | 154.8 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | US DOI, BLM | | SHL_005 | -1.7 | 70.4 | 70.4 | 87.4 | 70.4 | 81.2 | 98.2 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_006 | -1.7 | 90.0 | 90.0 | 109.4 | 90.0 | 100.1 | 117.8 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_007 | -0.5 | 263.8 | 269.6 | 277.6 | 273.5 | 278.9 | 286.0 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_008 | -0.5 | 122.9 | 179.4 | 260.6 | 183.2 | 188.8 | 269.0 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_009 | -1.5 | 146.6 | 153.0 | 160.8 | 157.2 | 163.3 | 170.4 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_010 | -2.7 | 121.0 | 121.0 | 127.4 | 121.0 | 121.0 | 133.4 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_001 | 0.4 | 71.5 | 77.8 | 86.2 | 81.7 | 89.8 | 97.0 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_002 | 0.8 | 107.4 | 112.0 | 120.1 | 115.9 | 121.7 | 128.5 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_003 | 3.3 | 52.4 | 58.9 | 82.8 | 66.0 | 77.5 | 85.2 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_004 | -1.7 | 94.9 | 94.9 | 111.7 | 94.9 | 105.7 | 122.5 |

# EXPOSURE LEVEL RESULTS FOR RAINFALL-INDUCED FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Rainfall Inundation | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Rainfall 100-YR/24-HR Int-High Existing Conditions | Rainfall 100-YR/24-HR Int-High 2040 | Rainfall 100-YR/24-HR Int-High 2070 | Rainfall 500-YR/24-HR Int-High Existing Conditions | Rainfall 500-YR/24-HR Int-High 2040 | Rainfall 500-YR/24-HR Int-High 2070 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_005 | 0.5 | 80.5 | 86.4 | 92.4 | 89.8 | 95.0 | 102.0 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_006 | 0.6 | 94.3 | 96.7 | 104.0 | 101.0 | 106.8 | 112.4 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_007 | 0.3 | 100.2 | 105.7 | 111.6 | 110.0 | 118.2 | 121.2 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_008 | 0.5 | 88.4 | 94.0 | 98.9 | 98.2 | 104.3 | 108.5 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_009 | 0.5 | 95.6 | 100.0 | 102.1 | 103.7 | 107.4 | 108.1 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Village of Tequesta | | SFW_010 | 11.2 | 60.6 | 64.0 | 57.6 | 69.2 | 72.6 | 66.0 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_011 | 1.0 | 74.3 | 78.4 | 80.9 | 78.8 | 82.6 | 88.1 |
| Natural, Cultural, and Historical Resources | Wetland | Wetlands | Wetland | Palm Beach County | | WLD_001 | -1.7 | 87.8 | 87.8 | 105.7 | 87.8 | 98.6 | 115.3 |
| Natural, Cultural, and Historical Resources | Wetland | Wetlands | Wetland | Private | | WLD_002 | -1.7 | 94.9 | 94.9 | 111.7 | 94.9 | 105.7 | 122.5 |

# EXPOSURE LEVEL RESULTS FOR RAINFALL-INDUCED FLOODING - FLOOD RISK LEVEL

| Tequesta Critical Assets | | | | | | | | Flood Risk Level | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | Rainfall Inundation | | | | | | | |
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Rainfall 100-YR/24-HR Int-High Existing Conditions | Rainfall 100-YR/24-HR Int-High 2040 | Rainfall 100-YR/24-HR Int-High 2070 | Rainfall 500-YR/24-HR Int-High Existing Conditions | Rainfall 500-YR/24-HR Int-High 2040 | Rainfall 500-YR/24-HR Int-High 2070 | Final Priority Ranking | Focus Area |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 20 | Village of Tequesta | | DWF_005 | 10.8 | High | High | High | High | High | High | Medium | 1 |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 19 | Village of Tequesta | | DWF_006 | 12.3 | High | High | High | High | High | High | Medium | 1 |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 18 | Village of Tequesta | | DWF_007 | 13.8 | High | High | High | High | High | High | Medium | 1 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 19 Pump | Village of Tequesta | | DWF_014 | 12.3 | High | High | High | High | High | High | Medium | 1 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 18 Pump | Village of Tequesta | | DWF_015 | 13.8 | High | High | High | High | High | High | High | 1 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 20 Pump | Village of Tequesta | | DWF_013 | 10.8 | High | High | High | High | High | High | Medium | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS107 - Wetwell | Loxahatchee River District | | WWF_026 | 4.4 | High | High | High | High | High | High | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS141 - Wetwell | Loxahatchee River District | | WWF_019 | 6.8 | Not Flooded | High | High | High | High | High | Low | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS066 - Electrical Panel | Loxahatchee River District | | WWF_002a | 8.5 | High | High | High | High | High | High | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS067 - Electrical Panel | Loxahatchee River District | | WWF_010a | 7.1 | High | High | High | High | High | High | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS141 - Electrical Panel | Loxahatchee River District | | WWF_019a | 10.8 | Not Flooded | High | High | High | High | High | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS060 - Wetwell | Loxahatchee River District | | WWF_025 | 9.7 | High | High | High | High | High | High | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS069 - Electrical Panel | Loxahatchee River District | | WWF_011a | 15.2 | High | High | High | High | High | High | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS060 - Electrical Panel | Loxahatchee River District | | WWF_025a | 13.7 | Not Flooded | Not Flooded | High | High | High | High | Low | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS067 - Wetwell | Loxahatchee River District | | WWF_010 | 3.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS066 - Wetwell | Loxahatchee River District | | WWF_002 | 4.5 | High | High | High | High | High | High | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS061 - Wetwell | Loxahatchee River District | | WWF_007 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS069 - Wetwell | Loxahatchee River District | | WWF_011 | 11.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS107 - Electrical Panel | Loxahatchee River District | | WWF_026a | 8.4 | Not Flooded | High | High | High | High | High | High | 1 |
| Natural, Cultural, and Historical Resources | Conservation Lands | Conservation Lands | Jupiter Inlet Lighthouse Outstanding Natural Area | US DOI, BLM | | CL_001 | -1.7 | Not Flooded | Flooding Outside Cı | Low | Low | Medium | High | Low | 1 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Coral Cove Park | Palm Beach County | | PRK_003 | -1.7 | Low | Low | Medium | Medium | Medium | High | Low | 1 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Tequesta Park | FDEP | | PRK_004 | 9.8 | Medium | Medium | High | Medium | High | High | Low | 1 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Palm Beach County | | SHL_001 | 0.6 | Low | Low | Medium | Medium | Medium | High | Low | 1 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Palm Beach County | | SHL_002 | -1.0 | Low | Low | Medium | Low | Medium | High | Low | 1 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_003 | -3.0 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | Low | 1 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_004 | -1.7 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | Low | Low | 1 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | US DOI, BLM | | SHL_005 | -1.7 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | Low | Low | 1 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_006 | -1.7 | Flooding Outside Cı | Flooding Outside Cı | Low | Low | Medium | High | Low | 1 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_004 | -1.7 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 1 |
| Natural, Cultural, and Historical Resources | Wetland | Wetlands | Wetland | Palm Beach County | | WLD_001 | -1.7 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 1 |
| Natural, Cultural, and Historical Resources | Wetland | Wetlands | Wetland | Private | | WLD_002 | -1.7 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 1 |
| Transportation and Evacuation Routes | Bridge | Bridges | Beach Rd Bridge | Palm Beach County | | BRD_002 | 17.0 | Not Flooded | Not Flooded | Not Flooded | Low | Low | Medium | Low | 1 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_011 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 1 |
| Transportation and Evacuation Routes | Major Roadway | Local | Coconut Ln | Village of Tequesta | Local | MJRD_089 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Transportation and Evacuation Routes | Major Roadway | Local | Coconut Ln | Village of Tequesta | Local | MJRD_262 | 20.5 | High | High | High | High | High | High | Low | 1 |
| Transportation and Evacuation Routes | Major Roadway | Local | Intracoastal Cir | Village of Tequesta | Local | MJRD_090 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | Low | 1 |
| Transportation and Evacuation Routes | Major Roadway | Local | Intracoastal Cir | Village of Tequesta | Local | MJRD_091 | 11.1 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 1 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_016 | 7.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 1 |
| Transportation and Evacuation Routes | Major Roadway | Local | Intracoastal Cir | Village of Tequesta | Local | MJRD_092 | 6.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 1 |
| Critical Community and Emergency Facilities | EMS | Emergency Medical Service Facilities | Tequesta EMS | Village of Tequesta | | EMF_001 | 14.3 | Not Flooded | Medium | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | EOC | Emergency Operation Centers | Emergency Operations Center | Village of Tequesta | | EOC_001 | 14.3 | Not Flooded | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Fire Station | Fire Stations | Tequesta Fire Department | Village of Tequesta | | FS_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Low | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Brookdale Tequesta | Private | | HCF_001 | 17.5 | High | High | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Clarebridge Cottage Tequesta | Private | | HCF_002 | 18.5 | High | High | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Terrace | Private | | HCF_003 | 23.8 | High | High | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Publix Pharmacy | Private | | HCF_005 | 25.4 | High | High | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Urgent Care | Private | | HCF_004 | 20.6 | High | High | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Drugs | Private | | HCF_006 | 20.6 | High | High | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | CVS Pharmacy | Private | | HCF_007 | 24.1 | High | High | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Law Enforcement Facility | Law Enforcement Facilities | Tequesta Police Department | Village of Tequesta | | LEF_001 | 14.3 | High | High | High | High | High | High | High | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Tequesta Village Hall | Village of Tequesta | | LGF_001 | 14.3 | High | High | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Village Hall IT Server Room | Village of Tequesta | | LGF_007 | 14.3 | High | High | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Safety 4000g Bulk Storage Tank | Village of Tequesta | | LGF_008 | 14.3 | High | High | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Tequesta Recreational Center | Village of Tequesta | | LGF_009 | 8.3 | High | High | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Rec Center IT Server Room | Village of Tequesta | | LGF_010 | 8.3 | High | High | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - Warehouse and Offices | Village of Tequesta | | LGF_002 | 20.6 | High | High | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - Clerk's Office Records | Village of Tequesta | | LGF_003 | 20.6 | High | High | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - PD Evidence Bay | Village of Tequesta | | LGF_004 | 20.6 | High | High | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Services Bulk Storage Fuel Tank | Village of Tequesta | | LGF_005 | 19.2 | High | High | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Services 4000 Gallon Split Tank | Village of Tequesta | | LGF_006 | 19.2 | High | High | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | School | Schools | Good Shepherd Episcopal School | Private | | SCL_001 | 9.2 | High | High | High | High | High | High | Low | 2 |
| Critical Community and Emergency Facilities | School | Schools | Providence Education Group | Private | | SCL_002 | 8.0 | High | High | High | High | High | High | Low | 2 |
| Critical Community and Emergency Facilities | School | Schools | Mary, Mother of the Light Academy | Private | | SCL_003 | 12.9 | High | High | High | High | High | High | Low | 2 |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well R4 | Village of Tequesta | | DWF_002 | 19.8 | High | High | High | High | High | High | Medium | 2 |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well R3 | Village of Tequesta | | DWF_003 | 14.2 | High | High | High | High | High | High | Medium | 2 |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 7 | Village of Tequesta | | DWF_004 | 11.5 | High | High | High | High | High | High | Medium | 2 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 7 Pump | Village of Tequesta | | DWF_012 | 11.5 | High | High | High | High | High | High | Medium | 2 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well R4 Pump | Village of Tequesta | | DWF_010 | 19.8 | High | High | High | High | High | High | Medium | 2 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well R3 Pump | Village of Tequesta | | DWF_011 | 14.1 | High | High | High | High | High | High | Medium | 2 |
| Critical Infrastructure | Generator | Electric Facilities | Rec Center 100kw LP Standby Generator | Village of Tequesta | | ELC_003 | 8.3 | High | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Generator | Electric Facilities | Public Safety 300kw Standby Generator | Village of Tequesta | | ELC_002 | 12.9 | High | High | High | High | High | High | High | 2 |

# EXPOSURE LEVEL RESULTS FOR RAINFALL-INDUCED FLOODING - FLOOD RISK LEVEL

| Tequesta Critical Assets | | | | | | | | Flood Risk Level | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | Rainfall Inundation | | | | | | | |
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Rainfall 100-YR/24-HR Int-High Existing Conditions | Rainfall 100-YR/24-HR Int-High 2040 | Rainfall 100-YR/24-HR Int-High 2070 | Rainfall 500-YR/24-HR Int-High Existing Conditions | Rainfall 500-YR/24-HR Int-High 2040 | Rainfall 500-YR/24-HR Int-High 2070 | Final Priority Ranking | Focus Area |
| Critical Infrastructure | Generator | Electric Facilities | Village Hall IT Standby Generator | Village of Tequesta | | ELC_001 | 14.3 | High | High | High | High | High | High | Medium | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS143 - Wetwell | Loxahatchee River District | | WWF_023 | 3.4 | High | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS054 - Wetwell | Loxahatchee River District | | WWF_022 | 9.6 | High | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS055 - Electrical Panel | Loxahatchee River District | | WWF_004a | 10.2 | High | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS058 - Electrical Panel | Loxahatchee River District | | WWF_006a | 12.3 | High | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS061 - Electrical Panel | Loxahatchee River District | | WWF_007a | 11.9 | High | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS064 - Electrical Panel | Loxahatchee River District | | WWF_008a | 17.8 | High | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS065 - Electrical Panel | Loxahatchee River District | | WWF_009a | 9.7 | High | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS079 - Electrical Panel | Loxahatchee River District | | WWF_021a | 9.0 | High | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS054 - Electrical Panel | Loxahatchee River District | | WWF_022a | 13.6 | High | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS079 - Wetwell | Loxahatchee River District | | WWF_021 | 5.0 | High | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS144 - Wetwell | Loxahatchee River District | | WWF_020 | 7.3 | High | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS062 - Wetwell | Loxahatchee River District | | WWF_024 | 15.8 | High | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS053 - Electrical Panel | Loxahatchee River District | | WWF_001a | 20.1 | High | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS050 - Electrical Panel | Loxahatchee River District | | WWF_003a | 14.0 | High | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS057 - Electrical Panel | Loxahatchee River District | | WWF_005a | 14.5 | High | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS144 - Electrical Panel | Loxahatchee River District | | WWF_020a | 11.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Low | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS062 - Electrical Panel | Loxahatchee River District | | WWF_024a | 19.8 | High | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS065 - Wetwell | Loxahatchee River District | | WWF_009 | 5.7 | Not Flooded | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS058 - Wetwell | Loxahatchee River District | | WWF_006 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS064 - Wetwell | Loxahatchee River District | | WWF_008 | 13.8 | Not Flooded | Not Flooded | Flooding Outside Cı | Not Flooded | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS143 - Electrical Panel | Loxahatchee River District | | WWF_023a | 7.4 | High | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS057 - Wetwell | Loxahatchee River District | | WWF_005 | 10.5 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS053 - Wetwell | Loxahatchee River District | | WWF_001 | 16.1 | High | High | High | High | High | High | Medium | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS050 - Wetwell | Loxahatchee River District | | WWF_003 | 10.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS055 - Wetwell | Loxahatchee River District | | WWF_004 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Critical Infrastructure | Water Ground Storage Tank | Ground Storage Tanks | Ground Storage Tank | Village of Tequesta | | DWF_009 | 15.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | Low | 2 |
| Critical Infrastructure | Water Ground Storage Tank | Ground Storage Tanks | Ground Storage Tank | Village of Tequesta | | DWF_008 | 15.2 | High | High | High | High | High | High | Medium | 2 |
| Critical Infrastructure | Water Treatment Facility | Water Treatment Plants | Water Treatment Facility | Village of Tequesta | | DWF_001 | 18.9 | High | High | High | High | High | High | Medium | 2 |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical Cultural Assets - Sites | Florida East Coast Railway | Private | | HCAS_001 | 7.1 | Not Flooded | High | High | High | High | High | Low | 2 |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical Cultural Assets - Sites | Old Dixie Highway | FDOT | | HCAS_002 | 11.3 | High | High | High | High | High | High | Low | 2 |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical Cultural Assets - Sites | Broadway (US 1) | FDOT | | HCAS_003 | 12.3 | High | High | High | High | High | High | Medium | 2 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Constitution Park | Village of Tequesta | | PRK_001 | 3.8 | Medium | Medium | High | High | High | High | Low | 2 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Paradise Park | Village of Tequesta | | PRK_002 | 16.1 | Medium | Medium | High | High | High | High | Low | 2 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_007 | -0.5 | Flooding Outside Cı | Low | Medium | Low | Medium | High | Low | 2 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_009 | 0.5 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Village of Tequesta | | SFW_010 | 11.2 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Bridge | Bridges | Tequesta Bridge | Village of Tequesta | | BRD_001 | 17.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | Medium | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_097 | 4.4 | Low | Medium | Medium | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Dover Rd | Village of Tequesta | Local | MJRD_098 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_099 | 4.5 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_100 | 4.2 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Evergreen Ave | Village of Tequesta | Local | MJRD_102 | 4.3 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Evergreen Ave | Village of Tequesta | Local | MJRD_103 | 4.3 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_104 | 4.5 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beacon St | Village of Tequesta | Local | MJRD_105 | 3.5 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Evergreen Ave | Village of Tequesta | Local | MJRD_106 | 4.2 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Norfolk Ave | Village of Tequesta | Local | MJRD_107 | 4.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Dover Rd | Village of Tequesta | Local | MJRD_108 | 4.6 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_109 | 4.5 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_110 | 3.5 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Seabrook Rd | Village of Tequesta | Local | MJRD_111 | 4.0 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Franklin Rd | Village of Tequesta | Local | MJRD_118 | 3.3 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Seabrook Rd | Village of Tequesta | Local | MJRD_119 | 4.2 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Seabrook Rd | Village of Tequesta | Local | MJRD_120 | 4.0 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Church Rd | Village of Tequesta | Local | MJRD_122 | 3.6 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beacon St | Village of Tequesta | Local | MJRD_125 | 3.7 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_132 | 4.7 | Low | Medium | Medium | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_007 | 18.2 | Not Flooded | Not Flooded | Flooding Outside Cı | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Cedar Hill Ln | Village of Tequesta | Local | MJRD_027 | 7.9 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chapel Ln | Village of Tequesta | Local | MJRD_029 | 8.8 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chapel Cir | Village of Tequesta | Local | MJRD_030 | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chapel Ct | Village of Tequesta | Local | MJRD_031 | 10.0 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chapel Ct | Village of Tequesta | Local | MJRD_032 | 8.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chapel Ln | Village of Tequesta | Local | MJRD_033 | 8.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Magnolia Way | Village of Tequesta | Local | MJRD_035 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beechwood Trl | Village of Tequesta | Local | MJRD_036 | 5.9 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_037 | 4.4 | Medium | Medium | Medium | Medium | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Oak Ridge Ln | Village of Tequesta | Local | MJRD_063 | 8.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pineview Rd | Village of Tequesta | Local | MJRD_112 | 5.0 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pineview Rd | Village of Tequesta | Local | MJRD_114 | 6.1 | High | High | High | High | High | High | High | 2 |

# EXPOSURE LEVEL RESULTS FOR RAINFALL-INDUCED FLOODING - FLOOD RISK LEVEL

| Tequesta Critical Assets | | | | | | | | Flood Risk Level | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | Rainfall Inundation | | | | | | | |
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Rainfall 100-YR/24-HR Int-High Existing Conditions | Rainfall 100-YR/24-HR Int-High 2040 | Rainfall 100-YR/24-HR Int-High 2070 | Rainfall 500-YR/24-HR Int-High Existing Conditions | Rainfall 500-YR/24-HR Int-High 2040 | Rainfall 500-YR/24-HR Int-High 2070 | Final Priority Ranking | Focus Area |
| Transportation and Evacuation Routes | Major Roadway | Local | Venus Ave | Village of Tequesta | Local | MJRD_117 | 6.1 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Venus Ave | Village of Tequesta | Local | MJRD_126 | 8.7 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Willow Rd | Village of Tequesta | Local | MJRD_127 | 8.6 | Medium | High | High | High | High | High | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_128 | 8.8 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_129 | 9.2 | High | High | High | High | High | High | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_130 | 8.8 | Medium | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_131 | 7.5 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Holly Cir | Village of Tequesta | Local | MJRD_133 | 10.0 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Willow Rd | Village of Tequesta | Local | MJRD_134 | 10.3 | Low | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Cypress Dr | Village of Tequesta | Local | MJRD_135 | 10.6 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Camelia Cir | Village of Tequesta | Local | MJRD_136 | 10.9 | Low | Low | Low | Low | Low | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Willow Rd | Village of Tequesta | Local | MJRD_137 | 10.3 | Medium | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Magnolia Way | Village of Tequesta | Local | MJRD_034 | 4.3 | High | High | High | High | High | High | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Dover Rd | Village of Tequesta | Local | MJRD_101 | 4.8 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Venus Ave | Village of Tequesta | Local | MJRD_113 | 5.0 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Mars Ave | Village of Tequesta | Local | MJRD_115 | 5.9 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Saturn Ave | Village of Tequesta | Local | MJRD_121 | 8.1 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Saturn Ave | Village of Tequesta | Local | MJRD_124 | 8.3 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Ridgewood Cir | Village of Tequesta | Local | MJRD_138 | 5.4 | Medium | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Venus Ave | Village of Tequesta | Local | MJRD_123 | 8.9 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Short Ave | Village of Tequesta | Local | MJRD_141 | 4.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Dover Rd | Village of Tequesta | Local | MJRD_142 | 4.4 | Not Flooded | Low | Not Flooded | Low | Medium | Low | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_143 | 4.3 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Maple Ave | Village of Tequesta | Local | MJRD_144 | 3.3 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beacon St | Village of Tequesta | Local | MJRD_145 | 3.3 | Low | Low | Medium | Medium | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_146 | 3.1 | Not Flooded | Not Flooded | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Garden St | Village of Tequesta | Local | MJRD_149 | 4.4 | Low | Low | Low | Low | Low | Medium | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Dover Rd | Village of Tequesta | Local | MJRD_150 | 4.3 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Elm Ave | Village of Tequesta | Local | MJRD_151 | 3.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beacon St | Village of Tequesta | Local | MJRD_152 | 3.4 | Low | Low | Low | Low | Low | Low | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_153 | 2.9 | High | High | High | High | High | High | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Oak Ave | Village of Tequesta | Local | MJRD_154 | 3.1 | Medium | High | High | High | High | High | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_155 | 3.1 | High | High | High | High | High | High | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beacon St | Village of Tequesta | Local | MJRD_156 | 3.9 | High | High | High | High | High | High | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Cir | Village of Tequesta | Local | MJRD_157 | 3.0 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_158 | 3.5 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Cedar Ave | Village of Tequesta | Local | MJRD_159 | 3.5 | High | High | High | High | High | High | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beacon St | Village of Tequesta | Local | MJRD_160 | 3.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_161 | 3.7 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_168 | 4.3 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Seabrook Rd | Village of Tequesta | Local | MJRD_169 | 4.3 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Seabrook Rd | Village of Tequesta | Local | MJRD_170 | 4.2 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_001 | 18.7 | Not Flooded | Not Flooded | Medium | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_002 | 17.9 | Not Flooded | Not Flooded | Not Flooded | Medium | Medium | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_003 | 14.3 | Not Flooded | Not Flooded | Medium | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_004 | 16.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_006 | 21.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_009 | 18.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_012 | 13.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_014 | 18.5 | Not Flooded | Not Flooded | Medium | Not Flooded | Not Flooded | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_015 | 18.3 | Medium | Medium | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_024 | 12.7 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_028 | 10.6 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_046 | 7.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_047 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_048 | 7.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Buttonwood Cir | Village of Tequesta | Local | MJRD_049 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_053 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Birch Pl | Village of Tequesta | Local | MJRD_054 | 9.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_058 | 6.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Cypress Dr | Village of Tequesta | Local | MJRD_064 | 10.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Cypress Dr | Village of Tequesta | Local | MJRD_067 | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Poplar Rd | Village of Tequesta | Local | MJRD_068 | 8.2 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl E | Village of Tequesta | Local | MJRD_069 | 9.4 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Woodland Dr | Village of Tequesta | Local | MJRD_070 | 8.8 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl E | Village of Tequesta | Local | MJRD_071 | 9.5 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl E | Village of Tequesta | Local | MJRD_072 | 9.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Teakwood Cir | Village of Tequesta | Local | MJRD_074 | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl E | Village of Tequesta | Local | MJRD_075 | 9.3 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_076 | 16.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Village Blvd | Village of Tequesta | Local | MJRD_087 | 13.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |

# EXPOSURE LEVEL RESULTS FOR RAINFALL-INDUCED FLOODING - FLOOD RISK LEVEL

| Tequesta Critical Assets | | | | | | | | Flood Risk Level | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | Rainfall Inundation | | | | | | | |
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Rainfall 100-YR/24-HR Int-High Existing Conditions | Rainfall 100-YR/24-HR Int-High 2040 | Rainfall 100-YR/24-HR Int-High 2070 | Rainfall 500-YR/24-HR Int-High Existing Conditions | Rainfall 500-YR/24-HR Int-High 2040 | Rainfall 500-YR/24-HR Int-High 2070 | Final Priority Ranking | Focus Area |
| Transportation and Evacuation Routes | Major Roadway | Local | Intracoastal Cir | Village of Tequesta | Local | MJRD_088 | 14.3 | Not Flooded | Low | Medium | Low | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Azalea Cir | Village of Tequesta | Local | MJRD_139 | 9.9 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Willow Rd | Village of Tequesta | Local | MJRD_140 | 8.6 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_162 | 7.1 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_163 | 6.9 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_165 | 6.3 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pineview Rd | Village of Tequesta | Local | MJRD_171 | 6.8 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fiesta Ave | Village of Tequesta | Local | MJRD_172 | 8.9 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pineview Rd | Village of Tequesta | Local | MJRD_173 | 9.3 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pineview Rd | Village of Tequesta | Local | MJRD_174 | 9.5 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Cypress Dr | Village of Tequesta | Local | MJRD_176 | 10.2 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fiesta Ave | Village of Tequesta | Local | MJRD_179 | 8.9 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fiesta Ave | Village of Tequesta | Local | MJRD_181 | 8.9 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Cypress Dr | Village of Tequesta | Local | MJRD_184 | 10.5 | Medium | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_185 | 14.9 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_186 | 16.4 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_187 | 17.4 | Not Flooded | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Magnolia Way | Village of Tequesta | Local | MJRD_261 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Hickory Hill Rd | Village of Tequesta | Local | MJRD_045 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_050 | 7.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Hickory Hill Rd | Village of Tequesta | Local | MJRD_051 | 7.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_052 | 3.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pinetree Cir | Village of Tequesta | Local | MJRD_059 | 6.6 | Not Flooded | Not Flooded | Not Flooded | Low | Low | Low | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Willow Rd | Village of Tequesta | Local | MJRD_060 | 7.0 | Not Flooded | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Oak Ridge Ln | Village of Tequesta | Local | MJRD_061 | 7.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bay Tree Ln | Village of Tequesta | Local | MJRD_062 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl E | Village of Tequesta | Local | MJRD_065 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl E | Village of Tequesta | Local | MJRD_066 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Garden St | Village of Tequesta | Local | MJRD_147 | 5.2 | Not Flooded | Medium | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Westwood Ave | Village of Tequesta | Local | MJRD_148 | 4.8 | Low | Low | Low | Low | Medium | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_166 | 5.8 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Leigh Rd | Village of Tequesta | Local | MJRD_178 | 7.9 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_005 | 24.3 | Not Flooded | Not Flooded | High | Not Flooded | Low | High | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_010 | 22.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_013 | 16.6 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_020 | 17.5 | High | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_021 | 18.5 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_022 | 17.9 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Acorn Cir | Village of Tequesta | Local | MJRD_073 | 11.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pineview Rd | Village of Tequesta | Local | MJRD_175 | 10.1 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Cove Rd | Village of Tequesta | Local | MJRD_177 | 20.5 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_023 | 17.6 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_025 | 13.0 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_164 | 6.4 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_183 | 11.7 | High | High | High | High | High | High | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Saturn Ave | Village of Tequesta | Local | MJRD_116 | 6.6 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_167 | 4.8 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Daly Rd | Village of Tequesta | Local | MJRD_180 | 8.3 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_182 | 9.0 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_008 | 21.0 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_018 | 17.6 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_019 | 18.6 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chestnut Trl | Village of Tequesta | Local | MJRD_026 | 7.9 | High | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_039 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Hemlock Ln | Village of Tequesta | Local | MJRD_041 | 7.2 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | Low | Low | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Hickory Hill Rd | Village of Tequesta | Local | MJRD_043 | 7.2 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beechwood Trl | Village of Tequesta | Local | MJRD_055 | 6.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_057 | 8.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Oakleaf Ct | Village of Tequesta | Local | MJRD_077 | 18.8 | Not Flooded | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Laurel Oaks Cir | Village of Tequesta | Local | MJRD_078 | 18.8 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_079 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Oakland Ct | Village of Tequesta | Local | MJRD_080 | 18.8 | Low | Medium | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_081 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Live Oak Cir | Village of Tequesta | Local | MJRD_082 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_083 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tall Oaks Cir | Village of Tequesta | Local | MJRD_084 | 18.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Live Oak Cir | Village of Tequesta | Local | MJRD_085 | 19.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Live Oak Cir | Village of Tequesta | Local | MJRD_086 | 18.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_038 | 3.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_040 | 7.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Hickory Hill Rd | Village of Tequesta | Local | MJRD_042 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |

# EXPOSURE LEVEL RESULTS FOR RAINFALL-INDUCED FLOODING - FLOOD RISK LEVEL

| Tequesta Critical Assets | | | | | | | | Flood Risk Level | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | Rainfall Inundation | | | | | | | |
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Rainfall 100-YR/24-HR Int-High Existing Conditions | Rainfall 100-YR/24-HR Int-High 2040 | Rainfall 100-YR/24-HR Int-High 2070 | Rainfall 500-YR/24-HR Int-High Existing Conditions | Rainfall 500-YR/24-HR Int-High 2040 | Rainfall 500-YR/24-HR Int-High 2070 | Final Priority Ranking | Focus Area |
| Transportation and Evacuation Routes | Major Roadway | Local | Dogwood Rdg | Village of Tequesta | Local | MJRD_044 | 5.9 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chestnut Trl | Village of Tequesta | Local | MJRD_056 | 7.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Hickory Hill Rd | Village of Tequesta | Local | MJRD_264 | 6.2 | Medium | High | High | High | High | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_017 | 17.9 | Not Flooded | Not Flooded | Flooding Outside Cı | Not Flooded | Flooding Outside Cı | Flooding Outside Cı | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Alley | Village of Tequesta | Local | MJRD_265 | 10.9 | Low | Medium | High | High | High | High | Low | 2 |
| Critical Community and Emergency Facilities | School | Schools | First Presbyterian Church Preschool of Tequesta | Private | | SCL_004 | 9.0 | High | High | High | High | High | High | Low | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS070 - Electrical Panel | Loxahatchee River District | | WWF_012a | 10.7 | High | High | High | High | High | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS071 - Electrical Panel | Loxahatchee River District | | WWF_013a | 11.5 | High | High | High | High | High | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS075 - Electrical Panel | Loxahatchee River District | | WWF_015a | 10.2 | High | High | High | High | High | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS076 - Electrical Panel | Loxahatchee River District | | WWF_016a | 10.4 | High | High | High | High | High | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS077 - Electrical Panel | Loxahatchee River District | | WWF_017a | 11.9 | High | High | High | High | High | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS072 - Electrical Panel | Loxahatchee River District | | WWF_014a | 12.9 | High | High | High | High | High | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS070 - Wetwell | Loxahatchee River District | | WWF_012 | 6.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Low | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS071 - Wetwell | Loxahatchee River District | | WWF_013 | 7.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Low | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS075 - Wetwell | Loxahatchee River District | | WWF_015 | 6.2 | Not Flooded | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS078 - Electrical Panel | Loxahatchee River District | | WWF_018a | 8.3 | High | High | High | High | High | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS072 - Wetwell | Loxahatchee River District | | WWF_014 | 8.9 | Not Flooded | Not Flooded | High | Not Flooded | High | High | Low | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS076 - Wetwell | Loxahatchee River District | | WWF_016 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS077 - Wetwell | Loxahatchee River District | | WWF_017 | 7.9 | Not Flooded | High | High | High | High | High | Medium | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS078 - Wetwell | Loxahatchee River District | | WWF_018 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_008 | -0.5 | Flooding Outside Cı | Low | Low | Low | Low | Medium | Low | 3 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_009 | -1.5 | Low | Low | Medium | Medium | Medium | High | Low | 3 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_010 | -2.7 | Low | Low | Low | Low | Medium | High | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_001 | 0.4 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_002 | 0.8 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_003 | 3.3 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_005 | 0.5 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_006 | 0.6 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_007 | 0.3 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_008 | 0.5 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_011 | 1.0 | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Flooding Outside Cı | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bay Harbor Rd | Village of Tequesta | Local | MJRD_188 | 2.6 | Medium | Medium | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fair Pl | Village of Tequesta | Local | MJRD_194 | 4.7 | Low | Medium | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairview E | Village of Tequesta | Local | MJRD_196 | 4.8 | Low | Medium | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_200 | 4.6 | Not Flooded | Not Flooded | Not Flooded | Medium | Medium | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bunker Pl | Village of Tequesta | Local | MJRD_201 | 4.4 | Low | Medium | Medium | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_202 | 4.6 | Not Flooded | Low | Low | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Palmetto Way | Village of Tequesta | Local | MJRD_220 | 4.7 | Not Flooded | Low | Low | Low | Low | Low | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Starboard Way | Village of Tequesta | Local | MJRD_223 | 3.6 | Low | Medium | Medium | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Gulfstream Dr | Village of Tequesta | Local | MJRD_225 | 3.7 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Leeward Cir | Village of Tequesta | Local | MJRD_226 | 3.6 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tradewinds Cir | Village of Tequesta | Local | MJRD_228 | 3.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Country Club Cir | Village of Tequesta | Local | MJRD_230 | 3.9 | High | High | High | High | High | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Yacht Club Pl | Village of Tequesta | | MJRD_235 | 4.0 | High | High | High | High | High | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairview W | Village of Tequesta | Local | MJRD_258 | 4.8 | High | High | High | High | High | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Point Dr | Village of Tequesta | Local | MJRD_189 | 4.8 | Medium | Medium | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Point Dr | Village of Tequesta | Local | MJRD_190 | 5.4 | Low | Low | Low | Low | Medium | Medium | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golf Pl | Village of Tequesta | Local | MJRD_199 | 6.2 | Low | Medium | Medium | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairway N | Village of Tequesta | Local | MJRD_209 | 6.6 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | North Pl | Village of Tequesta | Local | MJRD_210 | 6.4 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tequesta Cir | Village of Tequesta | Local | MJRD_215 | 5.2 | Low | Low | Low | Medium | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_217 | 7.4 | Low | Medium | Medium | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_224 | 5.5 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_231 | 5.4 | High | High | High | High | High | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_232 | 5.4 | High | High | High | High | High | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Point Dr | Village of Tequesta | Local | MJRD_253 | 6.3 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Club Pl | Village of Tequesta | Local | MJRD_260 | 5.6 | Medium | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_191 | 5.0 | Low | Low | Low | Low | Low | Low | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_192 | 4.8 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairview W | Village of Tequesta | Local | MJRD_193 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Low | Low | Low | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairview E | Village of Tequesta | Local | MJRD_195 | 5.3 | Not Flooded | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_197 | 5.5 | Medium | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_198 | 4.8 | Medium | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | R View Pl | Village of Tequesta | Local | MJRD_203 | 5.8 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_204 | 5.9 | Medium | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairway W | Village of Tequesta | Local | MJRD_205 | 4.9 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairway E | Village of Tequesta | Local | MJRD_206 | 4.8 | Medium | Medium | Medium | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_207 | 6.3 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_208 | 5.3 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairway N | Village of Tequesta | Local | MJRD_211 | 5.9 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairway N | Village of Tequesta | Local | MJRD_212 | 5.0 | High | High | High | High | High | High | Low | 3 |

# EXPOSURE LEVEL RESULTS FOR RAINFALL-INDUCED FLOODING - FLOOD RISK LEVEL

| Tequesta Critical Assets | | | | | | | | Flood Risk Level | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | Rainfall Inundation | | | | | | | |
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Rainfall 100-YR/24-HR Int-High Existing Conditions | Rainfall 100-YR/24-HR Int-High 2040 | Rainfall 100-YR/24-HR Int-High 2070 | Rainfall 500-YR/24-HR Int-High Existing Conditions | Rainfall 500-YR/24-HR Int-High 2040 | Rainfall 500-YR/24-HR Int-High 2070 | Final Priority Ranking | Focus Area |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairway N | Village of Tequesta | Local | MJRD_213 | 5.9 | Medium | Medium | Medium | Medium | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_214 | 4.9 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_216 | 5.3 | Medium | Medium | Medium | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_218 | 6.4 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_219 | 4.9 | Low | Medium | Medium | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_221 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | Low | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_222 | 5.3 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_227 | 5.1 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_229 | 5.1 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_254 | 5.3 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairview E | Village of Tequesta | Local | MJRD_238 | 4.5 | High | High | High | High | High | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bayview Ter | Village of Tequesta | Local | MJRD_248 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bayview Rd | Village of Tequesta | Local | MJRD_250 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Shady Ln | Village of Tequesta | Local | MJRD_251 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bayview Rd | Village of Tequesta | Local | MJRD_252 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_256 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Shady Ln | Village of Tequesta | Local | MJRD_263 | 4.3 | Low | Low | Low | Low | Low | Low | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | El Portal Dr | Village of Tequesta | Local | MJRD_242 | 5.7 | Low | Medium | Medium | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_255 | 5.7 | Low | Medium | Medium | Medium | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_259 | 5.8 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golf Club Cir | Village of Tequesta | Local | MJRD_233 | 5.1 | High | High | High | High | High | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_234 | 4.8 | High | High | High | High | High | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_236 | 5.2 | High | High | High | High | High | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | El Portal Dr | Village of Tequesta | Local | MJRD_237 | 4.9 | High | High | High | High | High | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Tree Pl | Village of Tequesta | Local | MJRD_239 | 5.0 | High | High | High | High | High | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | El Portal Dr | Village of Tequesta | Local | MJRD_240 | 5.2 | Medium | High | High | High | High | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_241 | 5.2 | High | High | High | High | High | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Yacht Club Pl | Village of Tequesta | Local | MJRD_243 | 4.9 | High | High | High | High | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Yacht Club Pl | Village of Tequesta | Local | MJRD_244 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_245 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_246 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bayview Ct | Village of Tequesta | Local | MJRD_247 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bayview Rd | Village of Tequesta | Local | MJRD_249 | 4.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_257 | 5.0 | High | High | High | High | High | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_096 | -0.5 | Not Flooded | Low | Low | Medium | High | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Point Dr | Village of Tequesta | Local | MJRD_093 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Tree Dr | Village of Tequesta | Local | MJRD_094 | 6.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Tree Dr | Village of Tequesta | Local | MJRD_095 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | Medium | Low | 3 |

# Attachment 3

# Exposure Level Results for Coastal Flooding

# EXPOSURE LEVEL RESULTS FOR COASTAL FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Storm Surge Flooding | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Storm Surge 100-YR Existing Conditions | Storm Surge 100-YR Int-Low 2040 | Storm Surge 100-YR Int-Low 2070 | Storm Surge 100-YR Int-High 2040 | Storm Surge 100-YR Int-High 2070 |
| Transportation and Evacuation Routes | Bridge | Bridges | Tequesta Bridge | Village of Tequesta | | BRD_001 | 17.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Bridge | Bridges | Beach Rd Bridge | Palm Beach County | | BRD_002 | 17.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_001 | 18.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_002 | 17.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_003 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_004 | 16.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_005 | 24.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_006 | 21.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_007 | 18.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_008 | 21.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_009 | 18.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_010 | 22.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_011 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_012 | 13.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_013 | 16.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_014 | 18.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_015 | 18.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_016 | 7.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_017 | 17.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_018 | 17.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_019 | 18.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_020 | 17.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_021 | 18.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_022 | 17.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_023 | 17.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_024 | 12.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | US-1 | FDOT | Arterial | MJRD_025 | 13.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chestnut Trl | Village of Tequesta | Local | MJRD_026 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 7.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cedar Hill Ln | Village of Tequesta | Local | MJRD_027 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 7.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_028 | 10.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Ln | Village of Tequesta | Local | MJRD_029 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Cir | Village of Tequesta | Local | MJRD_030 | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Ct | Village of Tequesta | Local | MJRD_031 | 10.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Ct | Village of Tequesta | Local | MJRD_032 | 8.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chapel Ln | Village of Tequesta | Local | MJRD_033 | 8.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Magnolia Way | Village of Tequesta | Local | MJRD_034 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Magnolia Way | Village of Tequesta | Local | MJRD_035 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beechwood Trl | Village of Tequesta | Local | MJRD_036 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_037 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_038 | 3.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_039 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 14.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_040 | 7.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 12.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hemlock Ln | Village of Tequesta | Local | MJRD_041 | 7.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 16.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_042 | 5.3 | Not Flooded | 10.1 | 17.2 | 15.7 | 38.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_043 | 7.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 16.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dogwood Rdg | Village of Tequesta | Local | MJRD_044 | 5.9 | Not Flooded | 2.9 | 10.0 | 8.5 | 31.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_045 | 5.9 | Not Flooded | 2.9 | 10.0 | 8.5 | 31.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_046 | 7.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 10.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_047 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_048 | 7.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 10.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Buttonwood Cir | Village of Tequesta | Local | MJRD_049 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_050 | 7.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 9.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_051 | 7.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 9.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_052 | 3.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_053 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 7.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Birch Pl | Village of Tequesta | Local | MJRD_054 | 9.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beechwood Trl | Village of Tequesta | Local | MJRD_055 | 6.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Chestnut Trl | Village of Tequesta | Local | MJRD_056 | 7.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 9.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_057 | 8.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 0.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl W | Village of Tequesta | Local | MJRD_058 | 6.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |

# EXPOSURE LEVEL RESULTS FOR COASTAL FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Storm Surge Flooding | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Storm Surge 100-YR Existing Conditions | Storm Surge 100-YR Int-Low 2040 | Storm Surge 100-YR Int-Low 2070 | Storm Surge 100-YR Int-High 2040 | Storm Surge 100-YR Int-High 2070 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pinetree Cir | Village of Tequesta | Local | MJRD_059 | 6.6 | Not Flooded | Not Flooded | 1.4 | 0.0 | 23.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_060 | 7.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 18.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oak Ridge Ln | Village of Tequesta | Local | MJRD_061 | 7.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 11.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bay Tree Ln | Village of Tequesta | Local | MJRD_062 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 15.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oak Ridge Ln | Village of Tequesta | Local | MJRD_063 | 8.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 6.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Cypress Dr | Village of Tequesta | Local | MJRD_064 | 10.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_065 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 15.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_066 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 15.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Cypress Dr | Village of Tequesta | Local | MJRD_067 | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Poplar Rd | Village of Tequesta | Local | MJRD_068 | 8.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_069 | 9.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Woodland Dr | Village of Tequesta | Local | MJRD_070 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_071 | 9.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_072 | 9.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Acorn Cir | Village of Tequesta | Local | MJRD_073 | 11.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Teakwood Cir | Village of Tequesta | Local | MJRD_074 | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Hill Trl E | Village of Tequesta | Local | MJRD_075 | 9.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_076 | 16.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oakleaf Ct | Village of Tequesta | Local | MJRD_077 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Laurel Oaks Cir | Village of Tequesta | Local | MJRD_078 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_079 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oakland Ct | Village of Tequesta | Local | MJRD_080 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_081 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Live Oak Cir | Village of Tequesta | Local | MJRD_082 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_083 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tall Oaks Cir | Village of Tequesta | Local | MJRD_084 | 18.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Live Oak Cir | Village of Tequesta | Local | MJRD_085 | 19.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Live Oak Cir | Village of Tequesta | Local | MJRD_086 | 18.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Village Blvd | Village of Tequesta | Local | MJRD_087 | 13.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Intracoastal Cir | Village of Tequesta | Local | MJRD_088 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Coconut Ln | Village of Tequesta | Local | MJRD_089 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 13.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Intracoastal Cir | Village of Tequesta | Local | MJRD_090 | 6.2 | Not Flooded | Not Flooded | 4.0 | 2.5 | 25.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Intracoastal Cir | Village of Tequesta | Local | MJRD_091 | 11.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Intracoastal Cir | Village of Tequesta | Local | MJRD_092 | 6.3 | Not Flooded | Not Flooded | 3.5 | 2.0 | 25.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Point Dr | Village of Tequesta | Local | MJRD_093 | 5.5 | Not Flooded | 7.9 | 15.0 | 13.6 | 36.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Tree Dr | Village of Tequesta | Local | MJRD_094 | 6.0 | Not Flooded | 2.0 | 9.1 | 7.7 | 30.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Tree Dr | Village of Tequesta | Local | MJRD_095 | 5.5 | Not Flooded | 8.0 | 15.1 | 13.7 | 36.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_096 | -0.5 | Not Flooded | 82.6 | 89.6 | 88.2 | 111.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_097 | 4.4 | Not Flooded | 21.0 | 28.1 | 26.6 | 49.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_098 | 4.3 | Not Flooded | 22.3 | 29.4 | 28.0 | 51.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_099 | 4.5 | Not Flooded | 19.8 | 26.9 | 25.4 | 48.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_100 | 4.2 | 9.6 | 23.9 | 31.0 | 29.5 | 52.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_101 | 4.8 | Not Flooded | 16.3 | 23.4 | 22.0 | 45.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Evergreen Ave | Village of Tequesta | Local | MJRD_102 | 4.3 | Not Flooded | 22.3 | 29.4 | 28.0 | 51.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Evergreen Ave | Village of Tequesta | Local | MJRD_103 | 4.3 | 8.4 | 22.7 | 29.8 | 28.3 | 51.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_104 | 4.5 | Not Flooded | 19.8 | 26.9 | 25.4 | 48.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_105 | 3.5 | 20.2 | 34.4 | 41.5 | 40.1 | 63.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Evergreen Ave | Village of Tequesta | Local | MJRD_106 | 4.2 | 9.6 | 23.9 | 31.0 | 29.5 | 52.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Norfolk Ave | Village of Tequesta | Local | MJRD_107 | 4.1 | Not Flooded | 24.6 | 31.7 | 30.2 | 53.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_108 | 4.6 | Not Flooded | 18.6 | 25.7 | 24.2 | 47.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_109 | 4.5 | Not Flooded | 19.7 | 26.8 | 25.3 | 48.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_110 | 3.5 | 18.0 | 32.3 | 39.4 | 37.9 | 61.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_111 | 4.0 | 12.0 | 26.3 | 33.4 | 31.9 | 55.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_112 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Venus Ave | Village of Tequesta | Local | MJRD_113 | 5.0 | Not Flooded | 11.3 | 18.4 | 16.9 | 40.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_114 | 6.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Mars Ave | Village of Tequesta | Local | MJRD_115 | 5.9 | Not Flooded | 0.0 | 7.2 | 5.8 | 29.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Saturn Ave | Village of Tequesta | Local | MJRD_116 | 6.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 20.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Venus Ave | Village of Tequesta | Local | MJRD_117 | 6.1 | Not Flooded | Not Flooded | 5.3 | 3.8 | 27.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Franklin Rd | Village of Tequesta | Local | MJRD_118 | 3.3 | 20.4 | 34.7 | 41.8 | 40.3 | 63.5 |

# EXPOSURE LEVEL RESULTS FOR COASTAL FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Storm Surge Flooding | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Storm Surge 100-YR Existing Conditions | Storm Surge 100-YR Int-Low 2040 | Storm Surge 100-YR Int-Low 2070 | Storm Surge 100-YR Int-High 2040 | Storm Surge 100-YR Int-High 2070 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_119 | 4.2 | 9.6 | 23.9 | 31.0 | 29.5 | 52.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_120 | 4.0 | 12.0 | 26.3 | 33.4 | 31.9 | 55.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Saturn Ave | Village of Tequesta | Local | MJRD_121 | 8.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 2.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Church Rd | Village of Tequesta | Local | MJRD_122 | 3.6 | 16.8 | 31.1 | 38.2 | 36.7 | 59.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Venus Ave | Village of Tequesta | Local | MJRD_123 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Saturn Ave | Village of Tequesta | Local | MJRD_124 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 0.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_125 | 3.7 | Not Flooded | 28.2 | 35.3 | 33.8 | 57.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Venus Ave | Village of Tequesta | Local | MJRD_126 | 8.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_127 | 8.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_128 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_129 | 9.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_130 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_131 | 7.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 10.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_132 | 4.7 | Not Flooded | 16.4 | 23.5 | 22.1 | 45.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Holly Cir | Village of Tequesta | Local | MJRD_133 | 10.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_134 | 10.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Cypress Dr | Village of Tequesta | Local | MJRD_135 | 10.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Camelia Cir | Village of Tequesta | Local | MJRD_136 | 10.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_137 | 10.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Ridgewood Cir | Village of Tequesta | Local | MJRD_138 | 5.4 | Not Flooded | 8.6 | 15.7 | 14.3 | 37.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Azalea Cir | Village of Tequesta | Local | MJRD_139 | 9.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Willow Rd | Village of Tequesta | Local | MJRD_140 | 8.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Short Ave | Village of Tequesta | Local | MJRD_141 | 4.0 | Not Flooded | 25.7 | 32.8 | 31.3 | 54.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_142 | 4.4 | Not Flooded | 20.9 | 28.0 | 26.5 | 49.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_143 | 4.3 | Not Flooded | 21.8 | 28.9 | 27.5 | 50.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Maple Ave | Village of Tequesta | Local | MJRD_144 | 3.3 | 22.8 | 37.1 | 44.2 | 42.7 | 65.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_145 | 3.3 | 22.8 | 37.1 | 44.2 | 42.7 | 65.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_146 | 3.1 | 25.2 | 39.5 | 46.6 | 45.1 | 68.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Garden St | Village of Tequesta | Local | MJRD_147 | 5.2 | Not Flooded | 11.5 | 18.6 | 17.2 | 40.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Westwood Ave | Village of Tequesta | Local | MJRD_148 | 4.8 | Not Flooded | 16.3 | 23.4 | 22.0 | 45.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Garden St | Village of Tequesta | Local | MJRD_149 | 4.4 | Not Flooded | 21.1 | 28.2 | 26.8 | 49.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | N Dover Rd | Village of Tequesta | Local | MJRD_150 | 4.3 | Not Flooded | 22.1 | 29.2 | 27.7 | 50.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Elm Ave | Village of Tequesta | Local | MJRD_151 | 3.0 | 26.4 | 40.7 | 47.8 | 46.3 | 69.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_152 | 3.4 | 19.2 | 33.5 | 40.6 | 39.1 | 62.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_153 | 2.9 | 27.6 | 41.9 | 49.0 | 47.5 | 70.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Oak Ave | Village of Tequesta | Local | MJRD_154 | 3.1 | 22.8 | 37.1 | 44.2 | 42.7 | 65.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_155 | 3.1 | 22.8 | 37.1 | 44.2 | 42.7 | 65.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_156 | 3.9 | 13.2 | 27.5 | 34.6 | 33.1 | 56.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Cir | Village of Tequesta | Local | MJRD_157 | 3.0 | 24.0 | 38.3 | 45.4 | 43.9 | 67.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_158 | 3.5 | 18.0 | 32.3 | 39.4 | 37.9 | 61.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cedar Ave | Village of Tequesta | Local | MJRD_159 | 3.5 | 18.0 | 32.3 | 39.4 | 37.9 | 61.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Beacon St | Village of Tequesta | Local | MJRD_160 | 3.9 | 13.2 | 27.5 | 34.6 | 33.1 | 56.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Dover Rd | Village of Tequesta | Local | MJRD_161 | 3.7 | 15.6 | 29.9 | 37.0 | 35.5 | 58.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_162 | 7.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 17.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_163 | 6.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 19.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_164 | 6.4 | Not Flooded | Not Flooded | 3.8 | 2.4 | 25.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_165 | 6.3 | Not Flooded | Not Flooded | 4.9 | 3.5 | 26.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_166 | 5.8 | Not Flooded | 3.8 | 10.9 | 9.5 | 32.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_167 | 4.8 | Not Flooded | 15.7 | 22.8 | 21.4 | 44.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Collector | MJRD_168 | 4.3 | Not Flooded | 21.4 | 28.4 | 27.0 | 50.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_169 | 4.3 | Not Flooded | 21.2 | 28.3 | 26.9 | 50.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Seabrook Rd | Village of Tequesta | Local | MJRD_170 | 4.2 | Not Flooded | 22.2 | 29.3 | 27.8 | 51.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_171 | 6.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fiesta Ave | Village of Tequesta | Local | MJRD_172 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_173 | 9.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_174 | 9.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pineview Rd | Village of Tequesta | Local | MJRD_175 | 10.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cypress Dr | Village of Tequesta | Local | MJRD_176 | 10.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cove Rd | Village of Tequesta | Local | MJRD_177 | 20.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Leigh Rd | Village of Tequesta | Local | MJRD_178 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 4.8 |

# EXPOSURE LEVEL RESULTS FOR COASTAL FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Storm Surge Flooding | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Storm Surge 100-YR Existing Conditions | Storm Surge 100-YR Int-Low 2040 | Storm Surge 100-YR Int-Low 2070 | Storm Surge 100-YR Int-High 2040 | Storm Surge 100-YR Int-High 2070 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fiesta Ave | Village of Tequesta | Local | MJRD_179 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Daly Rd | Village of Tequesta | Local | MJRD_180 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 0.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fiesta Ave | Village of Tequesta | Local | MJRD_181 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_182 | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_183 | 11.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Cypress Dr | Village of Tequesta | Local | MJRD_184 | 10.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_185 | 14.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_186 | 16.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_187 | 17.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bay Harbor Rd | Village of Tequesta | Local | MJRD_188 | 2.6 | 28.8 | 43.1 | 50.2 | 48.7 | 71.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Point Dr | Village of Tequesta | Local | MJRD_189 | 4.8 | Not Flooded | 16.2 | 23.3 | 21.8 | 45.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Point Dr | Village of Tequesta | Local | MJRD_190 | 5.4 | Not Flooded | 9.1 | 16.3 | 14.9 | 38.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_191 | 5.0 | Not Flooded | 17.2 | 24.2 | 22.8 | 46.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_192 | 4.8 | Not Flooded | 19.0 | 26.0 | 24.6 | 47.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview W | Village of Tequesta | Local | MJRD_193 | 5.1 | Not Flooded | 15.2 | 22.3 | 20.9 | 44.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fair Pl | Village of Tequesta | Local | MJRD_194 | 4.7 | Not Flooded | 19.3 | 26.4 | 25.0 | 48.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview E | Village of Tequesta | Local | MJRD_195 | 5.3 | Not Flooded | 12.2 | 19.3 | 17.9 | 41.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview E | Village of Tequesta | Local | MJRD_196 | 4.8 | Not Flooded | 18.8 | 25.9 | 24.5 | 47.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_197 | 5.5 | Not Flooded | 11.5 | 18.6 | 17.2 | 40.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_198 | 4.8 | Not Flooded | 19.3 | 26.4 | 25.0 | 48.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golf Pl | Village of Tequesta | Local | MJRD_199 | 6.2 | Not Flooded | 3.1 | 10.2 | 8.8 | 31.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_200 | 4.6 | Not Flooded | 23.4 | 30.5 | 29.0 | 52.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bunker Pl | Village of Tequesta | Local | MJRD_201 | 4.4 | Not Flooded | 23.5 | 30.6 | 29.2 | 52.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_202 | 4.6 | Not Flooded | 23.4 | 30.5 | 29.0 | 52.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | R View Pl | Village of Tequesta | Local | MJRD_203 | 5.8 | Not Flooded | 9.0 | 16.1 | 14.6 | 37.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_204 | 5.9 | Not Flooded | 7.9 | 15.2 | 13.8 | 37.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway W | Village of Tequesta | Local | MJRD_205 | 4.9 | Not Flooded | 18.6 | 25.7 | 24.2 | 47.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway E | Village of Tequesta | Local | MJRD_206 | 4.8 | Not Flooded | 19.8 | 26.9 | 25.4 | 48.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_207 | 6.3 | Not Flooded | 3.0 | 10.4 | 9.0 | 32.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_208 | 5.3 | Not Flooded | 13.4 | 20.5 | 19.1 | 42.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway N | Village of Tequesta | Local | MJRD_209 | 6.6 | Not Flooded | Not Flooded | 5.3 | 3.8 | 27.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | North Pl | Village of Tequesta | Local | MJRD_210 | 6.4 | Not Flooded | 0.6 | 7.7 | 6.2 | 29.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway N | Village of Tequesta | Local | MJRD_211 | 5.9 | Not Flooded | 6.6 | 13.7 | 12.2 | 35.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway N | Village of Tequesta | Local | MJRD_212 | 5.0 | Not Flooded | 19.0 | 26.0 | 24.6 | 47.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairway N | Village of Tequesta | Local | MJRD_213 | 5.9 | Not Flooded | 6.4 | 14.3 | 12.8 | 36.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_214 | 4.9 | Not Flooded | 20.4 | 27.5 | 26.0 | 49.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Cir | Village of Tequesta | Local | MJRD_215 | 5.2 | Not Flooded | 14.6 | 21.7 | 20.3 | 43.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_216 | 5.3 | Not Flooded | 13.8 | 20.9 | 19.4 | 42.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_217 | 7.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 17.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_218 | 6.4 | Not Flooded | 2.0 | 9.8 | 8.4 | 31.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_219 | 4.9 | Not Flooded | 17.0 | 24.1 | 22.7 | 45.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Palmetto Way | Village of Tequesta | Local | MJRD_220 | 4.7 | Not Flooded | 19.4 | 26.5 | 25.1 | 48.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_221 | 4.9 | Not Flooded | 17.3 | 24.4 | 22.9 | 46.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_222 | 5.3 | Not Flooded | 12.5 | 19.6 | 18.1 | 41.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Starboard Way | Village of Tequesta | Local | MJRD_223 | 3.6 | 22.4 | 36.7 | 43.8 | 42.4 | 65.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_224 | 5.5 | Not Flooded | 10.2 | 17.3 | 15.8 | 39.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Gulfstream Dr | Village of Tequesta | Local | MJRD_225 | 3.7 | 20.4 | 34.7 | 41.8 | 40.3 | 63.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Leeward Cir | Village of Tequesta | Local | MJRD_226 | 3.6 | Not Flooded | 34.2 | 41.3 | 39.8 | 63.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_227 | 5.1 | Not Flooded | 15.1 | 22.2 | 20.8 | 43.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tradewinds Cir | Village of Tequesta | Local | MJRD_228 | 3.4 | 24.5 | 38.8 | 45.8 | 44.4 | 67.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_229 | 5.1 | Not Flooded | 15.4 | 22.4 | 21.0 | 44.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Cir | Village of Tequesta | Local | MJRD_230 | 3.9 | Not Flooded | 29.8 | 36.8 | 35.4 | 58.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_231 | 5.4 | Not Flooded | 11.9 | 19.0 | 17.5 | 40.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_232 | 5.4 | Not Flooded | 11.9 | 19.0 | 17.5 | 40.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golf Club Cir | Village of Tequesta | Local | MJRD_233 | 5.1 | Not Flooded | 15.6 | 22.7 | 21.2 | 44.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_234 | 4.8 | Not Flooded | 19.3 | 26.4 | 25.0 | 48.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Yacht Club Pl | Village of Tequesta | | MJRD_235 | 4.0 | 16.8 | 31.1 | 38.2 | 36.7 | 59.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_236 | 5.2 | Not Flooded | 14.2 | 21.6 | 20.2 | 43.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | El Portal Dr | Village of Tequesta | Local | MJRD_237 | 4.9 | Not Flooded | 16.4 | 23.5 | 22.1 | 45.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview E | Village of Tequesta | Local | MJRD_238 | 4.5 | Not Flooded | 21.6 | 28.7 | 27.2 | 50.4 |

# EXPOSURE LEVEL RESULTS FOR COASTAL FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Storm Surge Flooding | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Storm Surge 100-YR Existing Conditions | Storm Surge 100-YR Int-Low 2040 | Storm Surge 100-YR Int-Low 2070 | Storm Surge 100-YR Int-High 2040 | Storm Surge 100-YR Int-High 2070 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Pine Tree Pl | Village of Tequesta | Local | MJRD_239 | 5.0 | Not Flooded | 15.8 | 22.9 | 21.5 | 44.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | El Portal Dr | Village of Tequesta | Local | MJRD_240 | 5.2 | Not Flooded | 12.8 | 19.9 | 18.5 | 41.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_241 | 5.2 | Not Flooded | 13.2 | 20.3 | 18.8 | 42.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | El Portal Dr | Village of Tequesta | Local | MJRD_242 | 5.7 | Not Flooded | 6.7 | 13.8 | 12.4 | 35.5 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Yacht Club Pl | Village of Tequesta | Local | MJRD_243 | 4.9 | Not Flooded | 16.9 | 24.0 | 22.6 | 45.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Yacht Club Pl | Village of Tequesta | Local | MJRD_244 | 5.4 | Not Flooded | 10.2 | 17.3 | 15.8 | 39.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Country Club Dr | Village of Tequesta | Collector | MJRD_245 | 5.1 | Not Flooded | 14.0 | 21.1 | 19.7 | 42.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Tequesta Dr | Village of Tequesta | Collector | MJRD_246 | 5.5 | Not Flooded | 8.8 | 15.8 | 14.4 | 37.6 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Ct | Village of Tequesta | Local | MJRD_247 | 4.8 | Not Flooded | 17.2 | 24.2 | 22.8 | 46.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Ter | Village of Tequesta | Local | MJRD_248 | 4.2 | Not Flooded | 24.2 | 31.3 | 29.9 | 53.0 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Rd | Village of Tequesta | Local | MJRD_249 | 4.6 | Not Flooded | 19.4 | 26.5 | 25.1 | 48.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Rd | Village of Tequesta | Local | MJRD_250 | 4.3 | Not Flooded | 23.0 | 30.1 | 28.7 | 51.8 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Shady Ln | Village of Tequesta | Local | MJRD_251 | 4.2 | Not Flooded | 24.1 | 31.2 | 29.8 | 52.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Bayview Rd | Village of Tequesta | Local | MJRD_252 | 4.3 | Not Flooded | 22.9 | 30.0 | 28.6 | 51.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Point Dr | Village of Tequesta | Local | MJRD_253 | 6.3 | Not Flooded | Not Flooded | 5.4 | 4.0 | 27.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_254 | 5.3 | Not Flooded | 12.2 | 20.5 | 19.1 | 42.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_255 | 5.7 | Not Flooded | 8.0 | 15.6 | 14.2 | 37.3 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_256 | 4.8 | Not Flooded | 17.6 | 24.7 | 23.3 | 46.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Golfview Dr | Village of Tequesta | Local | MJRD_257 | 5.0 | Not Flooded | 16.9 | 24.0 | 22.6 | 45.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Fairview W | Village of Tequesta | Local | MJRD_258 | 4.8 | Not Flooded | 18.6 | 25.7 | 24.2 | 47.4 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | River Dr | Village of Tequesta | Local | MJRD_259 | 5.8 | Not Flooded | 6.1 | 13.2 | 11.8 | 34.9 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Club Pl | Village of Tequesta | Local | MJRD_260 | 5.6 | Not Flooded | 8.4 | 15.5 | 14.0 | 37.2 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Magnolia Way | Village of Tequesta | Local | MJRD_261 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Coconut Ln | Village of Tequesta | Local | MJRD_262 | 20.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Shady Ln | Village of Tequesta | Local | MJRD_263 | 4.3 | Not Flooded | 22.9 | 30.0 | 28.6 | 51.7 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Hickory Hill Rd | Village of Tequesta | Local | MJRD_264 | 6.2 | Not Flooded | Not Flooded | 6.4 | 4.9 | 28.1 |
| Transportation and Evacuation Routes | Major Roadway | Major Roads | Alley | Village of Tequesta | Local | MJRD_265 | 10.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Water Treatment Facility | Water Treatment Plants | Water Treatment Facility | Village of Tequesta | | DWF_001 | 18.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Water Ground Storage Tank | Ground Storage Tanks | Ground Storage Tank | Village of Tequesta | | DWF_008 | 15.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Water Ground Storage Tank | Ground Storage Tanks | Ground Storage Tank | Village of Tequesta | | DWF_009 | 15.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well R4 | Village of Tequesta | | DWF_002 | 19.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well R3 | Village of Tequesta | | DWF_003 | 14.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 7 | Village of Tequesta | | DWF_004 | 11.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 20 | Village of Tequesta | | DWF_005 | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 19 | Village of Tequesta | | DWF_006 | 12.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 18 | Village of Tequesta | | DWF_007 | 13.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well R4 Pump | Village of Tequesta | | DWF_010 | 19.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well R3 Pump | Village of Tequesta | | DWF_011 | 14.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 7 Pump | Village of Tequesta | | DWF_012 | 11.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 20 Pump | Village of Tequesta | | DWF_013 | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 19 Pump | Village of Tequesta | | DWF_014 | 12.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 18 Pump | Village of Tequesta | | DWF_015 | 13.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Generator | Electric Facilities | Village Hall IT Standby Generator | Village of Tequesta | | ELC_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -70.2 |
| Critical Infrastructure | Generator | Electric Facilities | Public Safety 300kw Standby Generator | Village of Tequesta | | ELC_002 | 12.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -53.8 |
| Critical Infrastructure | Generator | Electric Facilities | Rec Center 100kw LP Standby Generator | Village of Tequesta | | ELC_003 | 8.3 | Not Flooded | -26.4 | -19.3 | -20.8 | 2.4 |
| Critical Infrastructure | Lift Station | Lift Stations | LS053 - Wetwell | Loxahatchee River District | | WWF_001 | 16.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS066 - Wetwell | Loxahatchee River District | | WWF_002 | 4.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS050 - Wetwell | Loxahatchee River District | | WWF_003 | 10.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS055 - Wetwell | Loxahatchee River District | | WWF_004 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS057 - Wetwell | Loxahatchee River District | | WWF_005 | 10.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS058 - Wetwell | Loxahatchee River District | | WWF_006 | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 1.3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS061 - Wetwell | Loxahatchee River District | | WWF_007 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS064 - Wetwell | Loxahatchee River District | | WWF_008 | 13.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS065 - Wetwell | Loxahatchee River District | | WWF_009 | 5.7 | Not Flooded | 5.2 | 12.2 | 10.8 | 34.0 |
| Critical Infrastructure | Lift Station | Lift Stations | LS067 - Wetwell | Loxahatchee River District | | WWF_010 | 3.1 | 22.8 | 37.1 | 44.2 | 42.7 | 65.9 |
| Critical Infrastructure | Lift Station | Lift Stations | LS069 - Wetwell | Loxahatchee River District | | WWF_011 | 11.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS070 - Wetwell | Loxahatchee River District | | WWF_012 | 6.7 | Not Flooded | Not Flooded | 1.6 | 0.1 | 23.3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS071 - Wetwell | Loxahatchee River District | | WWF_013 | 7.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 14.6 |
| Critical Infrastructure | Lift Station | Lift Stations | LS072 - Wetwell | Loxahatchee River District | | WWF_014 | 8.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS075 - Wetwell | Loxahatchee River District | | WWF_015 | 6.2 | Not Flooded | 1.8 | 8.9 | 7.4 | 30.6 |

# EXPOSURE LEVEL RESULTS FOR COASTAL FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Storm Surge Flooding | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Storm Surge 100-YR Existing Conditions | Storm Surge 100-YR Int-Low 2040 | Storm Surge 100-YR Int-Low 2070 | Storm Surge 100-YR Int-High 2040 | Storm Surge 100-YR Int-High 2070 |
| Critical Infrastructure | Lift Station | Lift Stations | LS076 - Wetwell | Loxahatchee River District | | WWF_016 | 6.4 | Not Flooded | Not Flooded | 5.9 | 4.4 | 27.6 |
| Critical Infrastructure | Lift Station | Lift Stations | LS077 - Wetwell | Loxahatchee River District | | WWF_017 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 12.1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS078 - Wetwell | Loxahatchee River District | | WWF_018 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS141 - Wetwell | Loxahatchee River District | | WWF_019 | 6.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | 20.0 |
| Critical Infrastructure | Lift Station | Lift Stations | LS144 - Wetwell | Loxahatchee River District | | WWF_020 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS079 - Wetwell | Loxahatchee River District | | WWF_021 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS054 - Wetwell | Loxahatchee River District | | WWF_022 | 9.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS143 - Wetwell | Loxahatchee River District | | WWF_023 | 3.4 | 19.3 | 33.6 | 40.7 | 39.2 | 62.4 |
| Critical Infrastructure | Lift Station | Lift Stations | LS062 - Wetwell | Loxahatchee River District | | WWF_024 | 15.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS060 - Wetwell | Loxahatchee River District | | WWF_025 | 9.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS107 - Wetwell | Loxahatchee River District | | WWF_026 | 4.4 | 31.0 | 24.6 | 35.5 | 33.2 | 69.1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS053 - Electrical Panel | Loxahatchee River District | | WWF_001a | 20.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS066 - Electrical Panel | Loxahatchee River District | | WWF_002a | 8.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS050 - Electrical Panel | Loxahatchee River District | | WWF_003a | 14.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS055 - Electrical Panel | Loxahatchee River District | | WWF_004a | 10.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS057 - Electrical Panel | Loxahatchee River District | | WWF_005a | 14.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS058 - Electrical Panel | Loxahatchee River District | | WWF_006a | 12.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -46.7 |
| Critical Infrastructure | Lift Station | Lift Stations | LS061 - Electrical Panel | Loxahatchee River District | | WWF_007a | 11.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS064 - Electrical Panel | Loxahatchee River District | | WWF_008a | 17.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS065 - Electrical Panel | Loxahatchee River District | | WWF_009a | 9.7 | Not Flooded | -42.8 | -35.8 | -37.2 | -14.0 |
| Critical Infrastructure | Lift Station | Lift Stations | LS067 - Electrical Panel | Loxahatchee River District | | WWF_010a | 7.1 | -25.2 | -10.9 | -3.8 | -5.3 | 17.9 |
| Critical Infrastructure | Lift Station | Lift Stations | LS069 - Electrical Panel | Loxahatchee River District | | WWF_011a | 15.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS070 - Electrical Panel | Loxahatchee River District | | WWF_012a | 10.7 | Not Flooded | Not Flooded | -46.4 | -47.9 | -24.7 |
| Critical Infrastructure | Lift Station | Lift Stations | LS071 - Electrical Panel | Loxahatchee River District | | WWF_013a | 11.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -33.4 |
| Critical Infrastructure | Lift Station | Lift Stations | LS072 - Electrical Panel | Loxahatchee River District | | WWF_014a | 12.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS075 - Electrical Panel | Loxahatchee River District | | WWF_015a | 10.2 | Not Flooded | -46.2 | -39.1 | -40.6 | -17.4 |
| Critical Infrastructure | Lift Station | Lift Stations | LS076 - Electrical Panel | Loxahatchee River District | | WWF_016a | 10.4 | Not Flooded | Not Flooded | -42.1 | -43.6 | -20.4 |
| Critical Infrastructure | Lift Station | Lift Stations | LS077 - Electrical Panel | Loxahatchee River District | | WWF_017a | 11.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -35.9 |
| Critical Infrastructure | Lift Station | Lift Stations | LS078 - Electrical Panel | Loxahatchee River District | | WWF_018a | 8.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS141 - Electrical Panel | Loxahatchee River District | | WWF_019a | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | -28.0 |
| Critical Infrastructure | Lift Station | Lift Stations | LS144 - Electrical Panel | Loxahatchee River District | | WWF_020a | 11.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS079 - Electrical Panel | Loxahatchee River District | | WWF_021a | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS054 - Electrical Panel | Loxahatchee River District | | WWF_022a | 13.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS143 - Electrical Panel | Loxahatchee River District | | WWF_023a | 7.4 | -28.7 | -14.4 | -7.3 | -8.8 | 14.4 |
| Critical Infrastructure | Lift Station | Lift Stations | LS062 - Electrical Panel | Loxahatchee River District | | WWF_024a | 19.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS060 - Electrical Panel | Loxahatchee River District | | WWF_025a | 13.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Infrastructure | Lift Station | Lift Stations | LS107 - Electrical Panel | Loxahatchee River District | | WWF_026a | 8.4 | -17.0 | -23.4 | -12.5 | -14.8 | 21.1 |
| Critical Community and Emergency Facilities | EMS | Emergency Medical Service Facilities | Tequesta EMS | Village of Tequesta | | EMF_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | EOC | Emergency Operations Centers | Emergency Operations Center | Village of Tequesta | | EOC_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Fire Station | Fire Stations | Tequesta Fire Department | Village of Tequesta | | FS_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Brookdale Tequesta | Private | | HCF_001 | 17.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Clarebridge Cottage Tequesta | Private | | HCF_002 | 18.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Terrace | Private | | HCF_003 | 23.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Urgent Care | Private | | HCF_004 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Publix Pharmacy | Private | | HCF_005 | 25.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Drugs | Private | | HCF_006 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | CVS Pharmacy | Private | | HCF_007 | 24.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Law Enforcement Facility | Law Enforcement Facilities | Tequesta Police Department | Village of Tequesta | | LEF_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Tequesta Village Hall | Village of Tequesta | | LGF_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - Warehouse and Offices | Village of Tequesta | | LGF_002 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - Clerk's Office Records | Village of Tequesta | | LGF_003 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - PD Evidence Bay | Village of Tequesta | | LGF_004 | 20.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Services Bulk Storage Fuel Tank | Village of Tequesta | | LGF_005 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Services 4000 Gallon Split Tank | Village of Tequesta | | LGF_006 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Village Hall IT Server Room | Village of Tequesta | | LGF_007 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Safety 4000g Bulk Storage Tank | Village of Tequesta | | LGF_008 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Tequesta Recreational Center | Village of Tequesta | | LGF_009 | 8.3 | Not Flooded | -26.4 | -19.3 | -20.8 | 2.4 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Rec Center IT Server Room | Village of Tequesta | | LGF_010 | 8.3 | Not Flooded | -26.4 | -19.3 | -20.8 | 2.4 |
| Critical Community and Emergency Facilities | School | Schools | Good Shepherd Episcopal School | Private | | SCL_001 | 9.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | School | Schools | Providence Education Group | Private | | SCL_002 | 8.0 | Not Flooded | -22.9 | -15.8 | -17.3 | 5.9 |

# EXPOSURE LEVEL RESULTS FOR COASTAL FLOODING - FLOOD DEPTH

| Tequesta Critical Assets | | | | | | | | Flood Depth (in) Storm Surge Flooding | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Storm Surge 100-YR Existing Conditions | Storm Surge 100-YR Int-Low 2040 | Storm Surge 100-YR Int-Low 2070 | Storm Surge 100-YR Int-High 2040 | Storm Surge 100-YR Int-High 2070 |
| Critical Community and Emergency Facilities | School | Schools | Mary, Mother of the Light Academy | Private | | SCL_003 | 12.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Critical Community and Emergency Facilities | School | Schools | First Presbyterian Church Preschool of Tequesta | Private | | SCL_004 | 9.0 | Not Flooded | -34.8 | -27.7 | -29.2 | -6.0 |
| Natural, Cultural, and Historical Resources | Conservation Lands | Conservation Lands | Jupiter Inlet Lighthouse Outstanding Natural Area | US DOI, BLM | | CL_001 | -1.7 | 98.4 | 118.9 | 129.8 | 127.6 | 163.4 |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical and Cultural Assets - Sites | Florida East Coast Railway | Private | | HCAS_001 | 7.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical and Cultural Assets - Sites | Old Dixie Highway | FDOT | | HCAS_002 | 11.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical and Cultural Assets - Sites | Broadway (US 1) | FDOT | | HCAS_003 | 12.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Parks | Parks | Constitution Park | Village of Tequesta | | PRK_001 | 3.8 | Not Flooded | 28.2 | 35.3 | 33.8 | 57.0 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Paradise Park | Village of Tequesta | | PRK_002 | 16.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Parks | Parks | Coral Cove Park | Palm Beach County | | PRK_003 | -1.7 | 164.4 | 148.4 | 155.5 | 154.1 | 177.2 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Tequesta Park | FDEP | | PRK_004 | 9.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Palm Beach County | | SHL_001 | 0.6 | 136.8 | 120.7 | 127.8 | 126.4 | 149.5 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Palm Beach County | | SHL_002 | -1.0 | 96.0 | 100.8 | 111.7 | 109.4 | 145.3 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_003 | -3.0 | Not Flooded | 198.8 | 205.9 | 204.5 | 227.6 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_004 | -1.7 | 86.4 | 100.8 | 107.9 | 106.4 | 129.6 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | US DOI, BLM | | SHL_005 | -1.7 | 80.4 | 97.4 | 104.5 | 103.1 | 126.2 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_006 | -1.7 | 80.4 | 101.2 | 112.1 | 109.9 | 145.7 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_007 | -0.5 | 72.2 | 93.4 | 104.3 | 102.0 | 137.9 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_008 | -0.5 | 94.8 | 112.9 | 123.8 | 121.7 | 157.4 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_009 | -1.5 | 87.6 | 107.8 | 118.7 | 116.4 | 152.3 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_010 | -2.7 | 121.2 | 143.2 | 154.1 | 151.9 | 187.7 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_001 | 0.4 | Not Flooded | 72.1 | 79.2 | 77.8 | 100.9 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_002 | 0.8 | Not Flooded | 69.7 | 76.8 | 75.4 | 98.5 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_003 | 3.3 | Not Flooded | 37.8 | 44.9 | 43.4 | 66.6 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_004 | -1.7 | 80.4 | 102.5 | 113.4 | 111.2 | 147.0 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_005 | 0.5 | Not Flooded | 69.6 | 76.7 | 75.2 | 98.4 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_006 | 0.6 | Not Flooded | 70.6 | 77.6 | 76.2 | 99.4 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_007 | 0.3 | Not Flooded | 75.1 | 82.2 | 80.8 | 103.9 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_008 | 0.5 | Not Flooded | 73.4 | 80.5 | 79.1 | 102.2 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_009 | 0.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Village of Tequesta | | SFW_010 | 11.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_011 | 1.0 | Not Flooded | 63.2 | 70.3 | 68.9 | 92.0 |
| Natural, Cultural, and Historical Resources | Wetland | Wetlands | Wetland | Palm Beach County | | WLD_001 | -1.7 | 80.4 | 94.7 | 101.8 | 100.3 | 123.5 |
| Natural, Cultural, and Historical Resources | Wetland | Wetlands | Wetland | Private | | WLD_002 | -1.7 | 80.4 | 94.7 | 101.8 | 100.3 | 123.5 |

# EXPOSURE LEVEL RESULTS FOR COASTAL FLOODING - FLOOD RISK LEVEL

| Tequesta Critical Assets | | | | | | | | Storm Surge Flooding | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Storm Surge 100-YR Existing Conditions | Storm Surge 100-YR Int-Low 2040 | Storm Surge 100-YR Int-Low 2070 | Storm Surge 100-YR Int-High 2040 | Storm Surge 100-YR Int-High 2070 | Final Priority Ranking | Focus Area |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 20 | Village of Tequesta | | DWF_005 | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 1 |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 19 | Village of Tequesta | | DWF_006 | 12.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 1 |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 18 | Village of Tequesta | | DWF_007 | 13.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 1 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 19 Pump | Village of Tequesta | | DWF_014 | 12.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 1 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 18 Pump | Village of Tequesta | | DWF_015 | 13.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | 1 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 20 Pump | Village of Tequesta | | DWF_013 | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS107 - Wetwell | Loxahatchee River District | | WWF_026 | 4.4 | Not Flooded | High | High | High | High | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS141 - Wetwell | Loxahatchee River District | | WWF_019 | 6.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS066 - Electrical Panel | Loxahatchee River District | | WWF_002a | 8.5 | Not Flooded | High | High | High | High | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS067 - Electrical Panel | Loxahatchee River District | | WWF_010a | 7.1 | Not Flooded | High | High | High | High | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS141 - Electrical Panel | Loxahatchee River District | | WWF_019a | 10.8 | Not Flooded | High | High | High | High | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS060 - Wetwell | Loxahatchee River District | | WWF_025 | 9.7 | Not Flooded | High | High | High | High | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS069 - Electrical Panel | Loxahatchee River District | | WWF_011a | 15.2 | Not Flooded | High | High | High | High | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS060 - Electrical Panel | Loxahatchee River District | | WWF_025a | 13.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Low | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS067 - Wetwell | Loxahatchee River District | | WWF_010 | 3.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Critical Range | Low | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS066 - Wetwell | Loxahatchee River District | | WWF_002 | 4.5 | Not Flooded | Not Flooded | High | High | High | High | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS061 - Wetwell | Loxahatchee River District | | WWF_007 | 7.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Critical Range | Low | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS069 - Wetwell | Loxahatchee River District | | WWF_011 | 11.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 1 |
| Critical Infrastructure | Lift Station | Lift Stations | LS107 - Electrical Panel | Loxahatchee River District | | WWF_026a | 8.4 | Not Flooded | High | High | High | High | High | 1 |
| Natural, Cultural, and Historical Resources | Conservation Lands | Conservation Lands | Jupiter Inlet Lighthouse Outstanding Natural Area | US DOI, BLM | | CL_001 | -1.7 | Not Flooded | Low | Medium | Medium | High | Low | 1 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Coral Cove Park | Palm Beach County | | PRK_003 | -1.7 | Not Flooded | High | High | High | High | Low | 1 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Tequesta Park | FDEP | | PRK_004 | 9.8 | Not Flooded | Medium | High | High | High | Low | 1 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Palm Beach County | | SHL_001 | 0.6 | Not Flooded | Low | High | Medium | High | Low | 1 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Palm Beach County | | SHL_002 | -1.0 | Not Flooded | Medium | High | High | High | Low | 1 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_003 | -3.0 | Not Flooded | Flooding Outside Cr | Low | Low | High | Low | 1 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_004 | -1.7 | Not Flooded | Flooding Outside Cr | Low | Low | High | Low | 1 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | US DOI, BLM | | SHL_005 | -1.7 | Not Flooded | Flooding Outside Cr | Low | Flooding Outside Cr | High | Low | 1 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_006 | -1.7 | Not Flooded | Low | Medium | Medium | High | Low | 1 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_004 | -1.7 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Critical Range | Low | 1 |
| Natural, Cultural, and Historical Resources | Wetland | Wetlands | Wetland | Palm Beach County | | WLD_001 | -1.7 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Critical Range | Low | 1 |
| Natural, Cultural, and Historical Resources | Wetland | Wetlands | Wetland | Private | | WLD_002 | -1.7 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Critical Range | Low | 1 |
| Transportation and Evacuation Routes | Bridge | Bridges | Beach Rd Bridge | Palm Beach County | | BRD_002 | 17.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_011 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 1 |
| Transportation and Evacuation Routes | Major Roadway | Local | Coconut Ln | Village of Tequesta | Local | MJRD_089 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | Low | 1 |
| Transportation and Evacuation Routes | Major Roadway | Local | Coconut Ln | Village of Tequesta | Local | MJRD_262 | 20.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Transportation and Evacuation Routes | Major Roadway | Local | Intracoastal Cir | Village of Tequesta | Local | MJRD_090 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 1 |
| Transportation and Evacuation Routes | Major Roadway | Local | Intracoastal Cir | Village of Tequesta | Local | MJRD_091 | 11.1 | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | High | Low | 1 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_016 | 7.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 1 |
| Transportation and Evacuation Routes | Major Roadway | Local | Intracoastal Cir | Village of Tequesta | Local | MJRD_092 | 6.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 1 |
| Critical Community and Emergency Facilities | EMS | Emergency Medical Service Facilities | Tequesta EMS | Village of Tequesta | | EMF_001 | 14.3 | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | EOC | Emergency Operation Centers | Emergency Operations Center | Village of Tequesta | | EOC_001 | 14.3 | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Fire Station | Fire Stations | Tequesta Fire Department | Village of Tequesta | | FS_001 | 14.3 | Not Flooded | Not Flooded | Medium | Medium | High | Low | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Brookdale Tequesta | Private | | HCF_001 | 17.5 | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Clarebridge Cottage Tequesta | Private | | HCF_002 | 18.5 | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Terrace | Private | | HCF_003 | 23.8 | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Publix Pharmacy | Private | | HCF_005 | 25.4 | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Urgent Care | Private | | HCF_004 | 20.6 | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | Tequesta Drugs | Private | | HCF_006 | 20.6 | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Health Care Facility | Health Care Facilities | CVS Pharmacy | Private | | HCF_007 | 24.1 | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Law Enforcement Facility | Law Enforcement Facilities | Tequesta Police Department | Village of Tequesta | | LEF_001 | 14.3 | Not Flooded | High | High | High | High | High | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Tequesta Village Hall | Village of Tequesta | | LGF_001 | 14.3 | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Village Hall IT Server Room | Village of Tequesta | | LGF_007 | 14.3 | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Safety 4000g Bulk Storage Tank | Village of Tequesta | | LGF_008 | 14.3 | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Tequesta Recreational Center | Village of Tequesta | | LGF_009 | 8.3 | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Rec Center IT Server Room | Village of Tequesta | | LGF_010 | 8.3 | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - Warehouse and Offices | Village of Tequesta | | LGF_002 | 20.6 | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - Clerk's Office Records | Village of Tequesta | | LGF_003 | 20.6 | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Serivces Facility - PD Evidence Bay | Village of Tequesta | | LGF_004 | 20.6 | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Services Bulk Storage Fuel Tank | Village of Tequesta | | LGF_005 | 19.2 | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | Local Government Facility | Local Government Facilities | Public Services 4000 Gallon Split Tank | Village of Tequesta | | LGF_006 | 19.2 | Not Flooded | High | High | High | High | Medium | 2 |
| Critical Community and Emergency Facilities | School | Schools | Good Shepherd Episcopal School | Private | | SCL_001 | 9.2 | Not Flooded | High | High | High | High | Low | 2 |
| Critical Community and Emergency Facilities | School | Schools | Providence Education Group | Private | | SCL_002 | 8.0 | Not Flooded | High | High | High | High | Low | 2 |
| Critical Community and Emergency Facilities | School | Schools | Mary, Mother of the Light Academy | Private | | SCL_003 | 12.9 | Not Flooded | High | High | High | High | Low | 2 |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well R4 | Village of Tequesta | | DWF_002 | 19.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Medium | 2 |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well R3 | Village of Tequesta | | DWF_003 | 14.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Infrastructure | Drinking Water Well | Water Supply Wells | Well 7 | Village of Tequesta | | DWF_004 | 11.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well 7 Pump | Village of Tequesta | | DWF_012 | 11.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well R4 Pump | Village of Tequesta | | DWF_010 | 19.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Infrastructure | Drinking Water Well Pump | Water Distribution Pumps | Well R3 Pump | Village of Tequesta | | DWF_011 | 14.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Critical Infrastructure | Generator | Electric Facilities | Rec Center 100kw LP Standby Generator | Village of Tequesta | | ELC_003 | 8.3 | Not Flooded | High | High | High | High | High | 2 |
| Critical Infrastructure | Generator | Electric Facilities | Public Safety 300kw Standby Generator | Village of Tequesta | | ELC_002 | 12.9 | Not Flooded | High | High | High | High | High | 2 |

# EXPOSURE LEVEL RESULTS FOR COASTAL FLOODING - FLOOD RISK LEVEL

| Tequesta Critical Assets | | | | | | | | Storm Surge Flooding | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Storm Surge 100-YR Existing Conditions | Storm Surge 100-YR Int-Low 2040 | Storm Surge 100-YR Int-Low 2070 | Storm Surge 100-YR Int-High 2040 | Storm Surge 100-YR Int-High 2070 | Final Priority Ranking | Focus Area |
| Critical Infrastructure | Generator | Electric Facilities | Village Hall IT Standby Generator | Village of Tequesta | | ELC_001 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Medium | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS143 - Wetwell | Loxahatchee River District | | WWF_023 | 3.4 | Not Flooded | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS054 - Wetwell | Loxahatchee River District | | WWF_022 | 9.6 | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS055 - Electrical Panel | Loxahatchee River District | | WWF_004a | 10.2 | Not Flooded | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS058 - Electrical Panel | Loxahatchee River District | | WWF_006a | 12.3 | Not Flooded | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS061 - Electrical Panel | Loxahatchee River District | | WWF_007a | 11.9 | Not Flooded | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS064 - Electrical Panel | Loxahatchee River District | | WWF_008a | 17.8 | Not Flooded | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS065 - Electrical Panel | Loxahatchee River District | | WWF_009a | 9.7 | Not Flooded | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS079 - Electrical Panel | Loxahatchee River District | | WWF_021a | 9.0 | Not Flooded | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS054 - Electrical Panel | Loxahatchee River District | | WWF_022a | 13.6 | Not Flooded | Not Flooded | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS079 - Wetwell | Loxahatchee River District | | WWF_021 | 5.0 | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS144 - Wetwell | Loxahatchee River District | | WWF_020 | 7.3 | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS062 - Wetwell | Loxahatchee River District | | WWF_024 | 15.8 | Not Flooded | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS053 - Electrical Panel | Loxahatchee River District | | WWF_001a | 20.1 | Not Flooded | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS050 - Electrical Panel | Loxahatchee River District | | WWF_003a | 14.0 | Not Flooded | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS057 - Electrical Panel | Loxahatchee River District | | WWF_005a | 14.5 | High | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS144 - Electrical Panel | Loxahatchee River District | | WWF_020a | 11.3 | Not Flooded | High | High | High | High | Low | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS062 - Electrical Panel | Loxahatchee River District | | WWF_024a | 19.8 | Not Flooded | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS065 - Wetwell | Loxahatchee River District | | WWF_009 | 5.7 | Not Flooded | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Critical Range | Low | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS058 - Wetwell | Loxahatchee River District | | WWF_006 | 8.3 | Not Flooded | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Critical Range | Low | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS064 - Wetwell | Loxahatchee River District | | WWF_008 | 13.8 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Critical Range | Low | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS143 - Electrical Panel | Loxahatchee River District | | WWF_023a | 7.4 | Not Flooded | High | High | High | High | High | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS057 - Wetwell | Loxahatchee River District | | WWF_005 | 10.5 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Low | Low | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS053 - Wetwell | Loxahatchee River District | | WWF_001 | 16.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Medium | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS050 - Wetwell | Loxahatchee River District | | WWF_003 | 10.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Critical Infrastructure | Lift Station | Lift Stations | LS055 - Wetwell | Loxahatchee River District | | WWF_004 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Critical Infrastructure | Water Ground Storage Tank | Ground Storage Tanks | Ground Storage Tank | Village of Tequesta | | DWF_009 | 15.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Low | 2 |
| Critical Infrastructure | Water Treatment Facility | Water Treatment Plants | Water Treatment Facility | Village of Tequesta | | DWF_001 | 18.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Medium | 2 |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical Cultural Assets - Sites | Florida East Coast Railway | Private | | HCAS_001 | 7.1 | Not Flooded | High | High | High | High | Low | 2 |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical Cultural Assets - Sites | Old Dixie Highway | FDOT | | HCAS_002 | 11.3 | Not Flooded | High | High | High | High | Low | 2 |
| Natural, Cultural, and Historical Resources | Historical and Cultural Assets - Site | Historical Cultural Assets - Sites | Broadway (US 1) | FDOT | | HCAS_003 | 12.3 | Not Flooded | High | High | High | High | Medium | 2 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Constitution Park | Village of Tequesta | | PRK_001 | 3.8 | Not Flooded | High | High | High | High | Low | 2 |
| Natural, Cultural, and Historical Resources | Parks | Parks | Paradise Park | Village of Tequesta | | PRK_002 | 16.1 | Not Flooded | Medium | High | High | High | Low | 2 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_007 | -0.5 | Not Flooded | Medium | High | High | High | Low | 2 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_009 | 0.5 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Critical Range | Low | 2 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Village of Tequesta | | SFW_010 | 11.2 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Critical Range | Low | 2 |
| Transportation and Evacuation Routes | Bridge | Bridges | Tequesta Bridge | Village of Tequesta | | BRD_001 | 17.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_097 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Dover Rd | Village of Tequesta | Local | MJRD_098 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_099 | 4.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_100 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Evergreen Ave | Village of Tequesta | Local | MJRD_102 | 4.3 | Not Flooded | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Evergreen Ave | Village of Tequesta | Local | MJRD_103 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_104 | 4.5 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beacon St | Village of Tequesta | Local | MJRD_105 | 3.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Evergreen Ave | Village of Tequesta | Local | MJRD_106 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Norfolk Ave | Village of Tequesta | Local | MJRD_107 | 4.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Dover Rd | Village of Tequesta | Local | MJRD_108 | 4.6 | Not Flooded | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_109 | 4.5 | Not Flooded | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_110 | 3.5 | Not Flooded | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Seabrook Rd | Village of Tequesta | Local | MJRD_111 | 4.0 | Medium | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Franklin Rd | Village of Tequesta | Local | MJRD_118 | 3.3 | Not Flooded | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Seabrook Rd | Village of Tequesta | Local | MJRD_119 | 4.2 | Not Flooded | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Seabrook Rd | Village of Tequesta | Local | MJRD_120 | 4.0 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Church Rd | Village of Tequesta | Local | MJRD_122 | 3.6 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beacon St | Village of Tequesta | Local | MJRD_125 | 3.7 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_132 | 4.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_007 | 18.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Cedar Hill Ln | Village of Tequesta | Local | MJRD_027 | 7.9 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chapel Ln | Village of Tequesta | Local | MJRD_029 | 8.8 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chapel Cir | Village of Tequesta | Local | MJRD_030 | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chapel Ct | Village of Tequesta | Local | MJRD_031 | 10.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chapel Ct | Village of Tequesta | Local | MJRD_032 | 8.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chapel Ln | Village of Tequesta | Local | MJRD_033 | 8.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Magnolia Way | Village of Tequesta | Local | MJRD_035 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beechwood Trl | Village of Tequesta | Local | MJRD_036 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_037 | 4.4 | Not Flooded | Not Flooded | Low | Low | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Oak Ridge Ln | Village of Tequesta | Local | MJRD_063 | 8.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pineview Rd | Village of Tequesta | Local | MJRD_112 | 5.0 | Not Flooded | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pineview Rd | Village of Tequesta | Local | MJRD_114 | 6.1 | Not Flooded | High | High | High | High | High | 2 |

# EXPOSURE LEVEL RESULTS FOR COASTAL FLOODING - FLOOD RISK LEVEL

| Tequesta Critical Assets | | | | | | | | Storm Surge Flooding | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Storm Surge 100-YR Existing Conditions | Storm Surge 100-YR Int-Low 2040 | Storm Surge 100-YR Int-Low 2070 | Storm Surge 100-YR Int-High 2040 | Storm Surge 100-YR Int-High 2070 | Final Priority Ranking | Focus Area |
| Transportation and Evacuation Routes | Major Roadway | Local | Venus Ave | Village of Tequesta | Local | MJRD_117 | 6.1 | Not Flooded | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Venus Ave | Village of Tequesta | Local | MJRD_126 | 8.7 | Not Flooded | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Willow Rd | Village of Tequesta | Local | MJRD_127 | 8.6 | Not Flooded | High | High | High | High | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_128 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_129 | 9.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_130 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_131 | 7.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Holly Cir | Village of Tequesta | Local | MJRD_133 | 10.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Willow Rd | Village of Tequesta | Local | MJRD_134 | 10.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Cypress Dr | Village of Tequesta | Local | MJRD_135 | 10.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Camelia Cir | Village of Tequesta | Local | MJRD_136 | 10.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Willow Rd | Village of Tequesta | Local | MJRD_137 | 10.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Magnolia Way | Village of Tequesta | Local | MJRD_034 | 4.3 | Not Flooded | Not Flooded | Low | Low | High | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Dover Rd | Village of Tequesta | Local | MJRD_101 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Venus Ave | Village of Tequesta | Local | MJRD_113 | 5.0 | Low | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Mars Ave | Village of Tequesta | Local | MJRD_115 | 5.9 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Saturn Ave | Village of Tequesta | Local | MJRD_121 | 8.1 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Saturn Ave | Village of Tequesta | Local | MJRD_124 | 8.3 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Ridgewood Cir | Village of Tequesta | Local | MJRD_138 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Venus Ave | Village of Tequesta | Local | MJRD_123 | 8.9 | Medium | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Short Ave | Village of Tequesta | Local | MJRD_141 | 4.0 | Not Flooded | Not Flooded | Low | Low | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Dover Rd | Village of Tequesta | Local | MJRD_142 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_143 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Maple Ave | Village of Tequesta | Local | MJRD_144 | 3.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beacon St | Village of Tequesta | Local | MJRD_145 | 3.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_146 | 3.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Garden St | Village of Tequesta | Local | MJRD_149 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Dover Rd | Village of Tequesta | Local | MJRD_150 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Elm Ave | Village of Tequesta | Local | MJRD_151 | 3.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beacon St | Village of Tequesta | Local | MJRD_152 | 3.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_153 | 2.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Oak Ave | Village of Tequesta | Local | MJRD_154 | 3.1 | Not Flooded | High | High | High | High | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_155 | 3.1 | Not Flooded | Medium | High | High | High | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beacon St | Village of Tequesta | Local | MJRD_156 | 3.9 | Not Flooded | Low | Low | Low | High | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Cir | Village of Tequesta | Local | MJRD_157 | 3.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_158 | 3.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Cedar Ave | Village of Tequesta | Local | MJRD_159 | 3.5 | Not Flooded | Low | High | High | High | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beacon St | Village of Tequesta | Local | MJRD_160 | 3.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Dover Rd | Village of Tequesta | Local | MJRD_161 | 3.7 | Not Flooded | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_168 | 4.3 | Not Flooded | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Seabrook Rd | Village of Tequesta | Local | MJRD_169 | 4.3 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Seabrook Rd | Village of Tequesta | Local | MJRD_170 | 4.2 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_001 | 18.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_002 | 17.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_003 | 14.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_004 | 16.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_006 | 21.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_009 | 18.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Critical Range | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_012 | 13.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_014 | 18.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_015 | 18.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_024 | 12.7 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_028 | 10.6 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_046 | 7.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_047 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_048 | 7.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Buttonwood Cir | Village of Tequesta | Local | MJRD_049 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_053 | 7.9 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Low | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Birch Pl | Village of Tequesta | Local | MJRD_054 | 9.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_058 | 6.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Cypress Dr | Village of Tequesta | Local | MJRD_064 | 10.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | N Cypress Dr | Village of Tequesta | Local | MJRD_067 | 10.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Poplar Rd | Village of Tequesta | Local | MJRD_068 | 8.2 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Low | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl E | Village of Tequesta | Local | MJRD_069 | 9.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Critical Range | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Woodland Dr | Village of Tequesta | Local | MJRD_070 | 8.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Critical Range | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl E | Village of Tequesta | Local | MJRD_071 | 9.5 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl E | Village of Tequesta | Local | MJRD_072 | 9.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Teakwood Cir | Village of Tequesta | Local | MJRD_074 | 9.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Flooding Outside Critical Range | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl E | Village of Tequesta | Local | MJRD_075 | 9.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_076 | 16.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Village Blvd | Village of Tequesta | Local | MJRD_087 | 13.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |

# EXPOSURE LEVEL RESULTS FOR COASTAL FLOODING - FLOOD RISK LEVEL

| Tequesta Critical Assets | | | | | | | | Storm Surge Flooding | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Storm Surge 100-YR Existing Conditions | Storm Surge 100-YR Int-Low 2040 | Storm Surge 100-YR Int-Low 2070 | Storm Surge 100-YR Int-High 2040 | Storm Surge 100-YR Int-High 2070 | Final Priority Ranking | Focus Area |
| Transportation and Evacuation Routes | Major Roadway | Local | Intracoastal Cir | Village of Tequesta | Local | MJRD_088 | 14.3 | Not Flooded | Low | High | Medium | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Azalea Cir | Village of Tequesta | Local | MJRD_139 | 9.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Willow Rd | Village of Tequesta | Local | MJRD_140 | 8.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_162 | 7.1 | Not Flooded | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_163 | 6.9 | Not Flooded | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_165 | 6.3 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pineview Rd | Village of Tequesta | Local | MJRD_171 | 6.8 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fiesta Ave | Village of Tequesta | Local | MJRD_172 | 8.9 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pineview Rd | Village of Tequesta | Local | MJRD_173 | 9.3 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pineview Rd | Village of Tequesta | Local | MJRD_174 | 9.5 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Cypress Dr | Village of Tequesta | Local | MJRD_176 | 10.2 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fiesta Ave | Village of Tequesta | Local | MJRD_179 | 8.9 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fiesta Ave | Village of Tequesta | Local | MJRD_181 | 8.9 | Not Flooded | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Cypress Dr | Village of Tequesta | Local | MJRD_184 | 10.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_185 | 14.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_186 | 16.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_187 | 17.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Magnolia Way | Village of Tequesta | Local | MJRD_261 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Hickory Hill Rd | Village of Tequesta | Local | MJRD_045 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_050 | 7.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Hickory Hill Rd | Village of Tequesta | Local | MJRD_051 | 7.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_052 | 3.9 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Low | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pinetree Cir | Village of Tequesta | Local | MJRD_059 | 6.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Willow Rd | Village of Tequesta | Local | MJRD_060 | 7.0 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Low | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Oak Ridge Ln | Village of Tequesta | Local | MJRD_061 | 7.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bay Tree Ln | Village of Tequesta | Local | MJRD_062 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl E | Village of Tequesta | Local | MJRD_065 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl E | Village of Tequesta | Local | MJRD_066 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Garden St | Village of Tequesta | Local | MJRD_147 | 5.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Westwood Ave | Village of Tequesta | Local | MJRD_148 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_166 | 5.8 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Leigh Rd | Village of Tequesta | Local | MJRD_178 | 7.9 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_005 | 24.3 | High | High | High | High | High | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_010 | 22.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_013 | 16.6 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_020 | 17.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_021 | 18.5 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_022 | 17.9 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Acorn Cir | Village of Tequesta | Local | MJRD_073 | 11.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pineview Rd | Village of Tequesta | Local | MJRD_175 | 10.1 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Cove Rd | Village of Tequesta | Local | MJRD_177 | 20.5 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_023 | 17.6 | Not Flooded | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_025 | 13.0 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_164 | 6.4 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_183 | 11.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Saturn Ave | Village of Tequesta | Local | MJRD_116 | 6.6 | Medium | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_167 | 4.8 | Not Flooded | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Daly Rd | Village of Tequesta | Local | MJRD_180 | 8.3 | Not Flooded | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_182 | 9.0 | Not Flooded | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_008 | 21.0 | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_018 | 17.6 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_019 | 18.6 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chestnut Trl | Village of Tequesta | Local | MJRD_026 | 7.9 | High | High | High | High | High | High | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_039 | 7.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Hemlock Ln | Village of Tequesta | Local | MJRD_041 | 7.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Hickory Hill Rd | Village of Tequesta | Local | MJRD_043 | 7.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Beechwood Trl | Village of Tequesta | Local | MJRD_055 | 6.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_057 | 8.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Oakleaf Ct | Village of Tequesta | Local | MJRD_077 | 18.8 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Critical Range | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Laurel Oaks Cir | Village of Tequesta | Local | MJRD_078 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_079 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Oakland Ct | Village of Tequesta | Local | MJRD_080 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_081 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Live Oak Cir | Village of Tequesta | Local | MJRD_082 | 18.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tequesta Oaks Dr | Village of Tequesta | Local | MJRD_083 | 19.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tall Oaks Cir | Village of Tequesta | Local | MJRD_084 | 18.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Live Oak Cir | Village of Tequesta | Local | MJRD_085 | 19.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Live Oak Cir | Village of Tequesta | Local | MJRD_086 | 18.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Hill Trl W | Village of Tequesta | Local | MJRD_038 | 3.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Seabrook Rd | Village of Tequesta | Collector | MJRD_040 | 7.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Hickory Hill Rd | Village of Tequesta | Local | MJRD_042 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |

# EXPOSURE LEVEL RESULTS FOR COASTAL FLOODING - FLOOD RISK LEVEL

| Tequesta Critical Assets | | | | | | | | Storm Surge Flooding | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Storm Surge 100-YR Existing Conditions | Storm Surge 100-YR Int-Low 2040 | Storm Surge 100-YR Int-Low 2070 | Storm Surge 100-YR Int-High 2040 | Storm Surge 100-YR Int-High 2070 | Final Priority Ranking | Focus Area |
| Transportation and Evacuation Routes | Major Roadway | Local | Dogwood Rdg | Village of Tequesta | Local | MJRD_044 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Chestnut Trl | Village of Tequesta | Local | MJRD_056 | 7.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Hickory Hill Rd | Village of Tequesta | Local | MJRD_264 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Arterial | US-1 | FDOT | Arterial | MJRD_017 | 17.9 | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | High | Low | 2 |
| Transportation and Evacuation Routes | Major Roadway | Local | Alley | Village of Tequesta | Local | MJRD_265 | 10.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Low | 2 |
| Critical Community and Emergency Facilities | School | Schools | First Presbyterian Church Preschool of Tequesta | Private | | SCL_004 | 9.0 | Not Flooded | High | High | High | High | Low | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS070 - Electrical Panel | Loxahatchee River District | | WWF_012a | 10.7 | High | High | High | High | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS071 - Electrical Panel | Loxahatchee River District | | WWF_013a | 11.5 | High | High | High | High | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS075 - Electrical Panel | Loxahatchee River District | | WWF_015a | 10.2 | High | High | High | High | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS076 - Electrical Panel | Loxahatchee River District | | WWF_016a | 10.4 | Not Flooded | High | High | High | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS077 - Electrical Panel | Loxahatchee River District | | WWF_017a | 11.9 | High | High | High | High | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS072 - Electrical Panel | Loxahatchee River District | | WWF_014a | 12.9 | Not Flooded | High | High | High | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS070 - Wetwell | Loxahatchee River District | | WWF_012 | 6.7 | Not Flooded | Not Flooded | High | High | High | Low | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS071 - Wetwell | Loxahatchee River District | | WWF_013 | 7.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Low | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS075 - Wetwell | Loxahatchee River District | | WWF_015 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS078 - Electrical Panel | Loxahatchee River District | | WWF_018a | 8.3 | Not Flooded | High | High | High | High | High | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS072 - Wetwell | Loxahatchee River District | | WWF_014 | 8.9 | Not Flooded | High | High | High | High | Low | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS076 - Wetwell | Loxahatchee River District | | WWF_016 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS077 - Wetwell | Loxahatchee River District | | WWF_017 | 7.9 | Not Flooded | Not Flooded | High | High | High | Medium | 3 |
| Critical Infrastructure | Lift Station | Lift Stations | LS078 - Wetwell | Loxahatchee River District | | WWF_018 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Low | 3 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_008 | -0.5 | Not Flooded | Low | Medium | Medium | High | Low | 3 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_009 | -1.5 | Not Flooded | Low | Medium | Medium | High | Low | 3 |
| Natural, Cultural, and Historical Resources | Shoreline | Shorelines | Shoreline | Private | | SHL_010 | -2.7 | Not Flooded | Low | Medium | Medium | High | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_001 | 0.4 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Critical Range | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_002 | 0.8 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Critical Range | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_003 | 3.3 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Critical Range | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_005 | 0.5 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Critical Range | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_006 | 0.6 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Critical Range | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_007 | 0.3 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Critical Range | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_008 | 0.5 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Critical Range | Low | 3 |
| Natural, Cultural, and Historical Resources | Surface Water | Surface Waters | Unnamed Pond | Private | | SFW_011 | 1.0 | Not Flooded | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Cr | Flooding Outside Critical Range | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bay Harbor Rd | Village of Tequesta | Local | MJRD_188 | 2.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fair Pl | Village of Tequesta | Local | MJRD_194 | 4.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairview E | Village of Tequesta | Local | MJRD_196 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_200 | 4.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bunker Pl | Village of Tequesta | Local | MJRD_201 | 4.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_202 | 4.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Palmetto Way | Village of Tequesta | Local | MJRD_220 | 4.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Starboard Way | Village of Tequesta | Local | MJRD_223 | 3.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Gulfstream Dr | Village of Tequesta | Local | MJRD_225 | 3.7 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Leeward Cir | Village of Tequesta | Local | MJRD_226 | 3.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tradewinds Cir | Village of Tequesta | Local | MJRD_228 | 3.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Country Club Cir | Village of Tequesta | Local | MJRD_230 | 3.9 | Not Flooded | Low | Medium | Low | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Yacht Club Pl | Village of Tequesta | | MJRD_235 | 4.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairview W | Village of Tequesta | Local | MJRD_258 | 4.8 | Not Flooded | High | High | High | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Point Dr | Village of Tequesta | Local | MJRD_189 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Point Dr | Village of Tequesta | Local | MJRD_190 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golf Pl | Village of Tequesta | Local | MJRD_199 | 6.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairway N | Village of Tequesta | Local | MJRD_209 | 6.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | North Pl | Village of Tequesta | Local | MJRD_210 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Tequesta Cir | Village of Tequesta | Local | MJRD_215 | 5.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_217 | 7.4 | Not Flooded | Not Flooded | Low | Low | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_224 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_231 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_232 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Point Dr | Village of Tequesta | Local | MJRD_253 | 6.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Club Pl | Village of Tequesta | Local | MJRD_260 | 5.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_191 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_192 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairview W | Village of Tequesta | Local | MJRD_193 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairview E | Village of Tequesta | Local | MJRD_195 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_197 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_198 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | R View Pl | Village of Tequesta | Local | MJRD_203 | 5.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_204 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairway W | Village of Tequesta | Local | MJRD_205 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairway E | Village of Tequesta | Local | MJRD_206 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_207 | 6.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_208 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairway N | Village of Tequesta | Local | MJRD_211 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairway N | Village of Tequesta | Local | MJRD_212 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |

# EXPOSURE LEVEL RESULTS FOR COASTAL FLOODING - FLOOD RISK LEVEL

| Tequesta Critical Assets | | | | | | | | Storm Surge Flooding | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Asset Class | Asset Type | Exposure Level Type | Asset Name | Asset Owner | Road Classification | Unique ID | Asset Elevation | Storm Surge 100-YR Existing Conditions | Storm Surge 100-YR Int-Low 2040 | Storm Surge 100-YR Int-Low 2070 | Storm Surge 100-YR Int-High 2040 | Storm Surge 100-YR Int-High 2070 | Final Priority Ranking | Focus Area |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairway N | Village of Tequesta | Local | MJRD_213 | 5.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_214 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_216 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_218 | 6.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_219 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_221 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_222 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_227 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_229 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_254 | 5.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Fairview E | Village of Tequesta | Local | MJRD_238 | 4.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bayview Ter | Village of Tequesta | Local | MJRD_248 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bayview Rd | Village of Tequesta | Local | MJRD_250 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Shady Ln | Village of Tequesta | Local | MJRD_251 | 4.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bayview Rd | Village of Tequesta | Local | MJRD_252 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_256 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Shady Ln | Village of Tequesta | Local | MJRD_263 | 4.3 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | El Portal Dr | Village of Tequesta | Local | MJRD_242 | 5.7 | Not Flooded | Low | Medium | Medium | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_255 | 5.7 | Not Flooded | Not Flooded | Low | Low | High | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_259 | 5.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golf Club Cir | Village of Tequesta | Local | MJRD_233 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_234 | 4.8 | Not Flooded | Not Flooded | Low | Low | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_236 | 5.2 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Medium | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | El Portal Dr | Village of Tequesta | Local | MJRD_237 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Tree Pl | Village of Tequesta | Local | MJRD_239 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | El Portal Dr | Village of Tequesta | Local | MJRD_240 | 5.2 | Not Flooded | Medium | High | High | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | River Dr | Village of Tequesta | Local | MJRD_241 | 5.2 | Not Flooded | High | High | High | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Yacht Club Pl | Village of Tequesta | Local | MJRD_243 | 4.9 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Yacht Club Pl | Village of Tequesta | Local | MJRD_244 | 5.4 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Country Club Dr | Village of Tequesta | Collector | MJRD_245 | 5.1 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_246 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bayview Ct | Village of Tequesta | Local | MJRD_247 | 4.8 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Bayview Rd | Village of Tequesta | Local | MJRD_249 | 4.6 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Golfview Dr | Village of Tequesta | Local | MJRD_257 | 5.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | High | Medium | 3 |
| Transportation and Evacuation Routes | Major Roadway | Collector | Tequesta Dr | Village of Tequesta | Collector | MJRD_096 | -0.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Point Dr | Village of Tequesta | Local | MJRD_093 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Tree Dr | Village of Tequesta | Local | MJRD_094 | 6.0 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Vulnerable | 3 |
| Transportation and Evacuation Routes | Major Roadway | Local | Pine Tree Dr | Village of Tequesta | Local | MJRD_095 | 5.5 | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Not Flooded | Low | 3 |